

Erskine Park Transfer Station EPL20986

Link to Environmental Protection Licence:

http://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=123957&SYSUID=1&LICID=20986

November 2018 Dust Deposition Results

Date for testing: 26 October 2018

Date results received: 13 December 2018

Date posted: 21 December 2018

Monthly Test Round

November 2018 Dust Deposition Results

Table 1: Dust Deposition Assessment Criteria and Results

	Assessment Criteria								
Gauge ID (units)	Exposure Period (Days)	Funnel Diameter (mm)	Total Solids (g m ⁻² month ⁻¹)	Insoluble Solids (g m² month¹)	Soluble Matter (g m ⁻² month ⁻¹)	Ash content (g m ⁻² month ⁻¹)	Combustible Matter (g m ⁻² month ⁻¹)	Assessment Criteria Limit (g m ⁻² month ⁻¹)	Comments
D10	32	150	5.9	3.6	2.3	3.1	0.5	5.0	25mm of rainwater, insects present, murky
D11	-	-	-	-	-	-	-	-	Removed due to construction works
D12	32	150	6.5	6.4	0.1	5.5	0.9	5.0	30mm rainwater, insects

All test results acquired from Arcadis November 2018 Report

Figure 1: Dust Deposition Gauge Locations

Property of the Control of the Control

Version: 1.0