

Erskine Park Landfill EPL4865
Link to Environment Protection Licence:
<http://www.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=32538&SYSUID=1&LICID=4865>
April 2014 Dust Deposition Results
Date for testing: 14 April 2014
Date results received: 1 August 2014
Monthly Test Round

Gauge ID	Exposure Period	Funnel Diameter	Total Solids	Insoluble Solids	Soluble Matter	Ash Content	Combustible Matter	12 month average insoluble solids	Comments
Units	Days	mm	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	
D1	33	150	1.1	1.0	0.1	0.6	0.4	0.83	Several amounts of small organic debris and very slight grit. Approximately 170mm rainwater.
D2	33	150	3.5	1.8	1.7	1.1	0.7	0.73	Few small insects, several amounts of small organic debris and very slight grit. Approximately 170mm rainwater.
D4	33	150	2.4	1.4	1.0	0.8	0.6	1.31	Some small forms of organic debris and very slight grit. Approximately 170mm rainwater.
D6	33	150	2.4	2.2	0.2	1.4	0.8	1.36	2 insects, copious small organic detritus visible, slight grit and a small pebble present. Bottle was full with signs of overflow.
D7	33	150	2.1	1.7	0.4	1.3	0.4	1.02	Several insects, amounts of small organic debris and slight grit. Approximately 150mm rainwater.
D8	33	150	2.6	1.2	1.4	0.8	0.4	0.81	Small droppings noted on top

Units	Gauge ID	Exposure Period	Funnel Diameter	Total Solids	Insoluble Solids	Soluble Matter	Ash Content	Combustible Matter	12 month average insoluble solids	Comments
		Days	mm	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	inside of funnel, 1 large insect, copious small organic debris and very slight grit. Approximately 150mm rainwater.