

Erskine Park Landfill EPL4865
Link to Environment Protection Licence:
<http://www.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=32538&SYSUID=1&LICID=4865>
November 2014 Dust Deposition Results
Date for testing: 13 November 2014
Date results received: 1 February 2015
Monthly Test Round

Gauge ID	Exposure Period	Funnel Diameter	Total Solids	Insoluble Solids	Soluble Matter	Ash Content	Combustible Matter	12 month average insoluble solids	Comments
Units	Days	mm	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	g m ⁻² month ⁻¹	
D1	32	150	2.8	1.5	1.3	1.1	0.4	0.68	Few insects and moderate grit present. Approximately 120mm rainwater.
D2	32	150	2.4	1.2	1.2	0.9	0.3	0.66	Few insects, some organic detritus and moderate grit present. Approximately 120mm rainwater.
D4	32	150	2	1.2	0.8	1.0	0.2	1.13	Few insects and moderate grit present. Approximately 150mm rainwater.
D6	32	150	2.8	1.6	1.2	1.4	0.2	1.3	Numerous insects, some organic detritus and moderate grit present. Approximately 150mm rainwater.
D7	32	150	3.1	2.2	0.9	1.8	0.4	1.28	Few insects, some organic detritus and moderate grit present. Approximately 140mm rainwater. Bird dropping noted on funnel.
D8	32	150	2.3	1.1	1.2	0.7	0.4	0.92	Few insects, some organic detritus and moderate grit present. Approximately 120mm rainwater. Bird

