



EPL No:	10251
Entity Name:	Cleanaway Industrial Solutions Pty Ltd
Site:	10-12 Waynote Place, Unanderra NSW
Monitoring Frequency:	Quarterly
Link to NSW EPA Register:	Click Here

Sample ID	Published Date	Obtained Date	Sampled Date	Sampled Parameters									Comment/s
				pH	Suspended Solids (SS)	Arsenic	Cadmium	Lead	Zinc	Hexavalent Chromium	Oil & Grease	Biochemical Oxygen Demand	
				pH unit	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	
Assessment Criteria				-	50.00	-	-	-	-	-	-	-	
EPA ID No.2 - First Flush Discharge	19/09/2022	16/09/2022	9/09/2022	7.56	5	<0.001	<0.0001	<0.001	0.031	<0.01	<5	27	
EPA ID No.2 - First Flush Discharge	5/07/2022	5/07/2022	24/06/2022	7.37	16	0.001	<0.0001	0.002	0.024	<0.01	<5	4	
EPA ID No.2 - First Flush Discharge	7/03/2022	4/03/2022	25/02/2022	7.61	7	<0.001	<0.0001	0.002	0.022	<0.01	<5	9	
EPA ID No.2 - First Flush Discharge	5/01/2022	31/12/2021	22/12/2021	6.98	17	0.001	<0.0001	<0.001	0.024	<0.01	<5	6	
EPA ID No.2 - First Flush Discharge	3/11/2021	2/11/2021	20/10/2021	7.11	<5	<0.001	<0.0001	0.002	0.016	<0.01	<5	122	
EPA ID No.2 - First Flush Discharge	22/07/2021	21/07/2021	13/07/2021	7.72	28	0.002	<0.0001	0.003	0.02	0.001	<5	3	
EPA ID No.2 - First Flush Discharge	29/03/2021	26/03/2021	18/03/2021	7.79	110	0.003	0.0001	0.012	0.08	<0.01	<5	<2	System cleaned out and controls inspected with drain wardens to be replaced.
EPA ID No.2 - First Flush Discharge	13/01/2021	12/01/2021	4/01/2021	7.3	18	0.002	<0.0001	0.002	0.023	<0.01	<5	3	
EPA ID No.2 - First Flush Discharge		4/08/2020	27/07/2020	8.51	145	<0.001	<0.0001	0.008	0.088	<0.01	<5	<2	System cleaned out and controls inspected with drain wardens to be replaced.

Please note, prior to the above samples being taken Cleanaway has been collecting and transporting first flush stormwater to the Charcoal Close, Unanderra Facility (EPL No.10771).