



### Pollutant Monitoring Results - General Pollutant

Environmental Protection Licence Number: 5065

Licensee Name: Lucas Heights Resource Recovery Park

Facility Address: New Illawarra Rd Lucas Heights, NSW 2234

*Disclaimer - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the requirements issued in writing by the Environment Protection Authority. To the best of Cleanaway's knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior consent from Cleanaway. For more details on publication of pollution monitoring data refer to the NSW EPA Website [www.epa.nsw.gov.au](http://www.epa.nsw.gov.au)*

A copy of the full licence can be found on the PDEO Public Register  
<http://www.epa.nsw.gov.au/prpoeoapp/>

Date Monitoring Data Obtained	Date Monitored	Sampling Point as per Licence	No. of times measured during reporting period	Pollutant	Monitoring Frequency Required by licence	Actual Value	Unit	Pollutant limit as per Licence	Exceedance (Y/N or NA)	Comments
5/05/2023	4/05/2023	LD001 (Point 3)	1	Electrical Conductivity (field)	Quarterly	20500	uS/cm	N/A	N	
5/05/2023	4/05/2023	LD001 (Point 3)	1	pH (field)	Quarterly	8.42	pH units	N/A	N	