

EPL No:	12628					
Entity Name:	Cleanaway Co Pty Ltd					
Site:	40 Christie St, St Marys NSW					
Monitoring Frequency:	Annually					
Link to NSW EPA Register:	<u>Click Here</u>					

<u>Discharge & Monitoring Point 1</u> Discharge from stack, HazPak Exhaust 100-V-323

Pollutant	Unit of measure	EPL Limit	No. of samples required per reporting period*	No. of samples collected and analysed to date*	Sample 1			Exceedance (Yes / No)	Lowest sample value*	Mean of sample*	Highest sample value*
Volatile organic compounds	milligrams per cubic metre	40	1	0	N/A - HazPak not operational during the reporting period and therefore monitoring was not undertaken			N/A	N/A	N/A	N/A
					N/A	N/A	N/A				
					Published Date	Report Date	Sample Date				

Discharge & Monitoring Point 2

Discharge from stack, BluBox Exhaust

Pollutant	Unit of measure	EPL Limit	No. of samples required per reporting period*	No. of samples collected and analysed to date*	Sample 1			Exceedance (Yes / No)	Lowest sample value*	Mean of sample*	Highest sample value*
Mercury	milligrams per cubic metre	0.2	1	1	< 0.00007			No	< 0.00007	< 0.00007	< 0.00007
					17/06/2024	7/06/2024	15/05/2024				-
					Published Date	Report Date	Sample Date				