

Pollutant Monitoring Results - Surface Gas

EPL No:	4068							
Entity Name:	Elizabeth Drive Landfill							
Site:	1725 Elizabeth Drive, KEMPS CREEK, NSW, 2178							
Monitoring Frequency:	Quarterly							
Link to NSW EPA Register:	<u>Click Here</u>							

Disclaimer - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the requirements issued in writing by the Environment Protection Authority. To the best of Cleanaway's knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior consent from Cleanaway. For more details on publication of pollution monitoring data refer to the NSW EPA Website www.epa.nsw.gov.au

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence	No. of GPS points measured during reporting period	Pollutant	Minimum Value	Mean Value	Median Value	Maximum Value	Unit of Measure	Pollutant limit as per Licence	Exceedanc e (Y/N)	Comments
2/05/2024	26/03/2024	21/03/2024	Surface Gas	1203	Methane	0.4	13.3	9.7	7970	ppm	500	Y	9 exceedances: 678, 711, 660, 991, 1150, 580, 7380, 7970, 672 ppm v/v respectively. Actions: Recover and adjust gas extraction. Retest of the areas done - exceedances rectified.
		24/05/2024	Surface Gas	1100	Methane	0.2	9.1	7.6	775	ppm	500	Y	3 exceedances: 775, 507, 623. Actions: Cover with bentonite clay, resurface the area that will eventually become an operational area. Retest of the areas done - 1 exceedances rectified, 2 were resurfaced to become operational areas.
		1/8/2024	Surface Gas	1150	Methane	0.5	12.7	9.5	3033	ppm	500	Y	11 exceedances 774, 3033, 574, 1205, 576, 1080, 704, 752, 539, 774, 602. Actions: Recover with soil and adjust gas extraction. Retest of the areas done areas have since been rectified.
7/02/2025	7/02/2025	28/11/2024	Surface Gas	1170	Methane	0.3	13.1	9.9	8300	ppm	500	Y	5 exceedances: 640, 1290, 3800, 8300, 590. Actions: Adjust gas extraction. Retest of the areas done - exceedances rectified.