



## Pollutant Monitoring Results - Gas Accumulation Monitoring

EPL No:	4865
Entity Name:	Enviroguard Pty Ltd
Site:	4 Quarry Road, Erskine Park NSW
Monitoring Frequency:	Quarterly
Link to NSW EPA Register:	<a href="#">Click Here</a>

Disclaimer - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the requirements issued in writing by the Environment Protection Authority. To the best of Cleanaway's knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior consent from Cleanaway. For more details on publication of pollution monitoring data refer to the NSW EPA Website [www.epa.nsw.gov.au](http://www.epa.nsw.gov.au)

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence
6/02/2025	11/04/2024	20/03/2024	Inside all buildings or other enclosed structures within 250m of deposited waste,

  

Site: Erskine Park		Monitoring equipment: RK Eagle II		Date: 20/03/24	Start time: 1000	Finish time: 1600	
Monitoring personnel: JC		Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud			
Atmospheric pressure at start (mb): 1005				Bump test: Yes			
Location ID	Max			Stable			Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	
<b>Cleanaway</b>							
Emergency Shower				0	0.00	20.9	0 0.0
Male Toilet				0	0.00	20.9	0 0.0
Female Toilet				0	0.00	20.9	0 0.0
Handicap Toilet				0	0.00	20.9	0 0.0
Office 7				0	0.00	20.9	0 0.0
Server room				0	0.00	20.9	0 0.0
Office 6				0	0.00	20.9	0 0.0
Office 5				0	0.00	20.9	0 0.0
Office 4				0	0.00	20.9	0 0.0
Office 3				0	0.00	20.9	0 0.0
Office 2				0	0.00	20.9	0 0.0
Office 1				0	0.00	20.9	0 0.0
Office 8				0	0.00	20.9	0 0.0
Weighbridge				0	0.00	20.9	0 0.0
Meal Room				0	0.00	20.9	0 0.0
Conference Room				0	0.00	20.9	0 0.0
Lobby				0	0.00	20.9	0 0.0
Male Toilet 2				0	0.00	20.9	0 0.0
Female Toilet 2				0	0.00	20.9	0 0.0
Unisex Toilet				0	0.00	20.9	0 0.0
Locker Room				0	0.00	20.9	0 0.0
<b>Stramit</b>							
Stormwater Pit 1				10	0.00	20.9	0 0.0
Stormwater Pit 2				0	0.00	20.9	0 0.0
Stormwater Pit 3				0	0.00	20.9	0 0.0
Stormwater Pit 4				5	0.00	20.9	0 0.0
Stormwater Pit 5				15	0.00	20.9	0 0.0
Stormwater Pit 6				0	0.00	20.9	0 0.0
Site: Erskine Park		Monitoring equipment: RK Eagle II		Date: 20/03/24	Start time: 1000	Finish time: 1600	
Monitoring personnel: JC		Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud			
Atmospheric pressure at start (mb): 1005				Bump test: Yes			
Location ID	Max			Stable			Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	
Stormwater Pit 7				0	0.00	20.9	0 0.0
Weighbridge				0	0.00	20.9	0 0.0
Men Toilet 1				0	0.00	20.9	0 0.0
Lunch Room 1				0	0.00	20.9	0 0.0
Men Toilet 2				0	0.00	20.9	0 0.0
Lunch Room 2				0	0.00	20.9	0 0.0
<b>Stockland/Viscount Pooling</b>							
Stormwater Pit 1				0	0.00	20.9	0 0.0
Stormwater Pit 2				0	0.00	20.9	0 0.0
Stormwater Pit 3				0	0.00	20.9	0 0.0
Stormwater Pit 4				0	0.00	20.9	0 0.0
Stormwater Pit 5				0	0.00	20.9	0 0.0
Stormwater Pit 6				0	0.00	20.9	0 0.0
Stormwater Pit 7				0	0.00	20.9	0 0.0
Stormwater Pit 8				0	0.00	20.9	0 0.0
Stormwater Pit 9				0	0.00	20.9	0 0.0
Stormwater Pit 10				0	0.00	20.9	0 0.0
Stormwater Pit 11				0	0.00	20.9	0 0.0
Stormwater Pit 12				0	0.00	20.9	0 0.0
Stormwater Pit 13				0	0.00	20.9	0 0.0
Stormwater Pit 14				0	0.00	20.9	0 0.0
Change Room				0	0.00	20.9	0 0.0
Lunch Room				0	0.00	20.9	0 0.0
Toilet				0	0.00	20.9	0 0.0
Warehouse				0	0.00	20.9	0 0.0

Dinceil																														
Stormwater Pit 1																	0	0.00	20.9	0	0.0									
Stormwater Pit 2																	0	0.00	20.9	0	0.0									
Stormwater Pit 3																	0	0.00	20.9	0	0.0									
Site: Erskine Park											Date: 20/03/24					Start time: 1000			Finish time: 1600											
Monitoring personnel: JC											Monitoring equipment: RK Eagle II					Weather and ground conditions: 20C, sunny, dry, some cloud					Bump test: Yes									
Atmospheric pressure at start (mb): 1005											Rising or falling: Rising																			
Location ID											Max					Stable					Comments									
											CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)		CO		H2S		CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)		CO		H2S	
Stormwater Pit 4																					5		0.00		20.9		0		0.0	
Stormwater Pit 5																					0		0.00		20.9		0		0.0	
Stormwater Pit 6																					0		0.00		20.9		0		0.0	
Stormwater Pit 7																					0		0.00		20.9		0		0.0	
Stormwater Pit 8																					20		0.00		20.9		0		0.0	
Dispatch Office																					0		0.00		20.9		0		0.0	
Toilet 1																					0		0.00		20.9		0		0.0	
Electrical Room																					0		0.00		20.9		0		0.0	
Toilet 2																					0		0.00		20.9		0		0.0	
Saputo																														
Stormwater Pit 1																					0		0.00		20.9		0		0.0	
Stormwater Pit 2																					0		0.00		20.9		0		0.0	
Stormwater Pit 3																					0		0.00		20.9		0		0.0	
Stormwater Pit 4																					10		0.00		20.9		0		0.0	
Stormwater Pit 5																					0		0.00		20.9		0		0.0	
Stormwater Pit 6																					0		0.00		20.9		0		0.0	
Electrical Pit 1																					0		0.00		20.9		0		0.0	
Electrical Pit 2																					0		0.00		20.9		0		0.0	
Electrical Pit 3																					0		0.00		20.9		0		0.0	
Electrical Pit 4																					0		0.36		20.9		0		0.0	
Electrical Pit 5																					0		0.12		20.9		0		0.0	
Electrical Pit 6																					0		0.00		20.9		0		0.0	
Electrical Pit 7																					0		0.00		20.9		0		0.0	
Electrical Pit 8																					0		0.00		20.9		0		0.0	
LOSCAM																														
Stormwater Pit 1																					0		0.00		20.9		0		0.0	
Stormwater Pit 2																					0		0.00		20.9		0		0.0	
Stormwater Pit 3																					0		0.00		20.9		0		0.0	
Stormwater Pit 4																					0		0.00		20.9		0		0.0	
Site: Erskine Park											Date: 20/03/24					Start time: 1000			Finish time: 1600											
Monitoring personnel: JC											Monitoring equipment: RK Eagle II					Weather and ground conditions: 20C, sunny, dry, some cloud					Bump test: Yes									
Atmospheric pressure at start (mb): 1005											Rising or falling: Rising																			
Location ID											Max					Stable					Comments									
											CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)		CO		H2S		CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)		CO		H2S	
Stormwater Pit 5																					0		0.00		20.9		0		0.0	
Stormwater Pit 6																					0		0.00		20.9		0		0.0	
Stormwater Pit 7																					0		0.00		20.9		0		0.0	
Stormwater Pit 8																					0		0.00		20.9		0		0.0	
Wash Bay																					0		0.00		20.9		0		0.0	
Storage Shed																					0		0.00		20.9		0		0.0	
Toilet 1 - Male																					0		0.00		20.9		0		0.0	
Toilet 2 - Female																					0		0.00		20.9		0		0.0	
Lunch Room																					0		0.00		20.9		0		0.0	
Toilet 3																					0		0.00		20.9		0		0.0	
Mainfreight																														
Stormwater Pit 1																					0		0.00		20.9		0		0.0	
Stormwater Pit 2																					0		0.00		20.9		0		0.0	
Stormwater Pit 3																					0		0.00		20.9		0		0.0	
Stormwater Pit 4																					0		0.00		20.9		0		0.0	
Stormwater Pit 5																					0		0.00		20.9		0		0.0	
Stormwater Pit 6																					0		0.00		20.9		0		0.0	
Stormwater Pit 7																					0		0.00		20.9		0		0.0	
Dispatch office																					0		0.00		20.9		0		0.0	
Lunchroom																					0		0.00		20.9		0		0.0	
Toilet																					0		0.00		20.9		0		0.0	
Mulgoa Quarries																														
Stormwater Pit 1																					0		0.00		20.9		0		0.0	
Stormwater Pit 2																					0		0.00		20.9		0		0.0	
Stormwater Pit 3																					0		0.00		20.9		0		0.0	
Stormwater Pit 4																					0		0.00		20.9		0		0.0	
Stormwater Pit 5																					0		0.00		20.9		0		0.0	
Stormwater Pit 6																					0		0.00		20.9		0		0.0	
Stormwater Pit 7																					0		0.00		20.9		0		0.0	
Stormwater Pit 8																					0		0.00		20.9		0		0.0	
Stormwater Pit 9																					0		0.00		20.9		0		0.0	
Site: Erskine Park											Date: 20/03/24					Start time: 1000			Finish time: 1600											
Monitoring personnel: JC											Monitoring equipment: RK Eagle II					Weather and ground conditions: 20C, sunny, dry, some cloud					Bump test: Yes									
Atmospheric pressure at start (mb): 1005											Rising or falling: Rising																			
Location ID											Max					Stable					Comments									
											CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)		CO		H2S		CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)		CO		H2S	
Stormwater Pit 10																					0		0.00		20.9		0		0.0	
Stormwater Pit 11																					0		0.00		20.9		0		0.0	
Stormwater Pit 12																					0		0.00		20.9		0		0.0	

Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15						0	0.00	20.9	0	0.0	
Wash Bay						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Kitchen						0	0.00	20.9	0	0.0	
<b>Darley Aluminium</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Warehouse						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Toilet 2						0	0.00	20.9	0	0.0	
<b>ORAFOL/EM</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Electrical 1						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Site: Erskine Park											

Monitoring personnel: JC Monitoring equipment: RK Eagle II Date: 20/03/24 Start time: 1000 Finish time: 1600  
 Atmospheric pressure at start (mb): 1005 Rising or falling: Rising Weather and ground conditions: 20C, sunny, dry, some cloud Bump test: Yes

Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Electrical 2						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15						0	0.00	20.9	0	0.0	
Stormwater Pit 16						0	0.00	20.9	0	0.0	
<b>Bluescope Steel</b>											
Service Pit 1						0	0.00	20.9	0	0.0	
Electrical Pit 1						0	0.00	20.9	0	0.0	
Service Pit 2						0	0.00	20.9	0	0.0	
Electrical Pit 2						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Shower						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Pump Room						0	0.00	20.9	0	0.0	

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence
6/02/2025	9/07/2024	18/06/2024	Inside all buildings or other enclosed structures within 250m of deposited waste.

Site: Erskine Park Monitoring personnel: LS / MS Monitoring equipment: RK Eagle II Date: 19/12/24 Start time: 0800 Finish time: 1600  
 Atmospheric pressure at start (mb): 1005 Rising or falling: Rising Weather and ground conditions: 14C, cloudy, dry, Wet ground Bump test: Yes

Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
<b>Cleanaway</b>											
Emergency Shower						10	0.02	20.9	0	0.0	
Male Toilet						10	0.04	20.9	0	0.0	
Female Toilet						10	0.04	20.9	0	0.0	
Handicap Toilet						5	0.02	20.9	0	0.0	
Office 7						0	0.04	20.9	0	0.0	
Server room						0	0.00	20.9	0	0.0	
Office 6						5	0.02	20.9	0	0.0	
Office 5						0	0.00	20.9	0	0.0	
Office 4						0	0.02	20.9	0	0.0	
Office 3						0	0.02	20.9	0	0.0	

Office 2							0	0.02	20.9	0	0.0	
Office 1							15	0.00	20.9	0	0.0	
Office 8							15	0.02	20.9	0	0.0	
Weighbridge							5	0.00	20.9	0	0.0	
Meal Room							15	0.00	20.9	0	0.0	
Conference Room							20	0.00	20.9	0	0.0	
Lobby							0	0.02	20.9	0	0.0	
Male Toilet 2							10	0.02	20.9	0	0.0	
Female Toilet 2							5	0.02	20.9	0	0.0	
Unisex Toilet							0	0.02	20.9	0	0.0	
Locker Room							10	0.02	20.9	0	0.0	
<b>Stramit</b>												
Stormwater Pit 1							30	0.00	20.9	0	0.0	
Stormwater Pit 2							40	0.00	20.9	0	0.0	
Stormwater Pit 3							55	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							45	0.00	20.9	0	0.0	
Stormwater Pit 6							25	0.00	20.9	0	0.0	
Site: Erskine Park												Date: 18/06/24 Start time: 0800 Finish time: 1600
Monitoring personnel: LS / MS												Bump test: Yes
Monitoring equipment: RK Eagle II												
Atmospheric pressure at start (mb): 1005												Rising or falling: Rising Weather and ground conditions: 14C, cloudy, dry. Wet ground
Location ID												Stable Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 7							0	0.00	20.9	0	0.0	
Weighbridge							15	0.00	20.9	0	0.0	
Men Toilet 1							0	0.00	20.9	0	0.0	
Lunch Room 1							0	0.04	20.9	0	0.0	
Men Toilet 2							50	0.00	20.9	0	0.0	
Lunch Room 2							40	0.04	20.9	0	0.0	
<b>Stockland/Viscount Pooling</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							10	0.00	20.9	0	0.0	
Stormwater Pit 8							15	0.00	20.9	0	0.0	
Stormwater Pit 9							10	0.00	20.9	0	0.0	
Stormwater Pit 10							0	0.00	20.9	0	0.0	
Stormwater Pit 11							0	0.00	20.9	0	0.0	
Stormwater Pit 12							0	0.00	20.9	0	0.0	
Stormwater Pit 13							0	0.00	20.9	0	0.0	
Stormwater Pit 14							0	0.00	20.9	0	0.0	
Change Room							0	0.00	20.9	0	0.0	
Lunch Room							15	0.00	20.9	0	0.0	
Toilet							55	0.00	20.9	0	0.0	
Warehouse							30	0.00	20.9	0	0.0	
<b>Dinet</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							40	0.00	20.9	0	0.0	
Stormwater Pit 3							25	0.00	20.9	0	0.0	
Site: Erskine Park												Date: 18/06/24 Start time: 0800 Finish time: 1600
Monitoring personnel: LS / MS												Bump test: Yes
Monitoring equipment: RK Eagle II												
Atmospheric pressure at start (mb): 1005												Rising or falling: Rising Weather and ground conditions: 14C, cloudy, dry. Wet ground
Location ID												Stable Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							15	0.00	20.9	0	0.0	
Stormwater Pit 8							0	0.00	20.9	0	0.0	
Dispatch Office							10	0.00	20.9	0	0.0	
Toilet 1							65	0.00	20.9	0	0.0	
Electrical Room							15	0.00	20.9	0	0.0	
Toilet 2							0	0.00	20.9	0	0.0	
<b>Saputo</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							30	0.00	20.9	0	0.0	
Stormwater Pit 3							15	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							40	0.00	20.9	0	0.0	
Electrical Pit 1							130	0.00	20.9	0	0.0	
Electrical Pit 2							40	0.00	20.9	0	0.0	
Electrical Pit 3							90	0.00	20.9	0	0.0	
Electrical Pit 4							30	0.00	20.9	0	0.0	
Electrical Pit 5							35	0.00	20.9	0	0.0	
Electrical Pit 6							50	0.00	20.9	0	0.0	
Electrical Pit 7							0	0.00	20.9	0	0.0	
Electrical Pit 8							0	0.00	20.9	0	0.0	
<b>LOSCAM</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	

Stormwater Pit 2										30	0.00	20.9	0	0.0	
Stormwater Pit 3										15	0.00	20.9	0	0.0	
Stormwater Pit 4															No access
Site: Erskine Park										Date: 18/06/24			Start time: 0800	Finish time: 1600	
Monitoring personnel: LS / MS										Monitoring equipment: RK Eagle II					Bump test: Yes
Atmospheric pressure at start (mb): 1005										Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry, Wet ground		
Location ID															
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max		CO		H2S		CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
Stormwater Pit 5										0	0.00	20.9	0	0.0	
Stormwater Pit 6										0	0.00	20.9	0	0.0	
Stormwater Pit 7										0	0.00	20.9	0	0.0	
Stormwater Pit 8										0	0.00	20.9	0	0.0	
Wash Bay										0	0.00	20.9	0	0.0	
Storage Shed										0	0.00	20.9	0	0.0	
Toilet 1 - Male										0	0.00	20.9	0	0.0	
Toilet 2 - Female										0	0.00	20.9	0	0.0	
Lunch Room										0	0.04	20.9	0	0.0	
Toilet 3										0	0.00	20.9	0	0.0	
<b>Mainfreight</b>															
Stormwater Pit 1															No access. Change in tenant. Need to organise next event in advance.
Stormwater Pit 2															
Stormwater Pit 3															
Stormwater Pit 4															
Stormwater Pit 5															
Stormwater Pit 6															
Stormwater Pit 7															
Dispatch office															
Lunchroom															
Toilet															
<b>Mulgoa Quarries</b>															
Stormwater Pit 1										0	0.00	20.9	0	0.0	
Stormwater Pit 2										0	0.00	20.9	0	0.0	
Stormwater Pit 3										0	0.00	20.9	0	0.0	
Stormwater Pit 4										55	0.00	20.9	0	0.0	
Stormwater Pit 5										35	0.00	20.9	0	0.0	
Stormwater Pit 6										10	0.00	20.9	0	0.0	
Stormwater Pit 7										5	0.00	20.9	0	0.0	
Stormwater Pit 8										20	0.00	20.9	0	0.0	
Stormwater Pit 9										0	0.00	20.9	0	0.0	
Site: Erskine Park										Date: 18/06/24			Start time: 0800	Finish time: 1600	
Monitoring personnel: LS / MS										Monitoring equipment: RK Eagle II					Bump test: Yes
Atmospheric pressure at start (mb): 1005										Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry, Wet ground		
Location ID															
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max		CO		H2S		CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
Stormwater Pit 10										0	0.00	20.9	0	0.0	
Stormwater Pit 11										5	0.00	20.9	0	0.0	
Stormwater Pit 12										0	0.00	20.9	0	0.0	
Stormwater Pit 13										0	0.00	20.9	0	0.0	
Stormwater Pit 14										10	0.00	20.9	0	0.0	
Stormwater Pit 15										0	0.00	20.9	0	0.0	
Wash Bay										0	0.00	20.9	0	0.0	
Toilet										0	0.00	20.9	0	0.0	
Lunch Room										0	0.00	20.9	0	0.0	
Kitchen										0	0.00	20.9	0	0.0	
<b>Darley Aluminium</b>															
Stormwater Pit 1										0	0.00	20.9	0	0.0	
Stormwater Pit 2										0	0.00	20.9	0	0.0	
Stormwater Pit 3										0	0.00	20.9	0	0.0	
Stormwater Pit 4										0	0.00	20.9	0	0.0	
Stormwater Pit 5										0	0.00	20.9	0	0.0	
Stormwater Pit 6										0	0.00	20.9	0	0.0	
Stormwater Pit 7										0	0.00	20.9	0	0.0	
Stormwater Pit 8										0	0.00	20.9	0	0.0	No access to test
Lunch Room										0	0.00	20.9	0	0.0	
Warehouse										0	0.00	20.9	0	0.0	
Office										0	0.00	20.9	0	0.0	
Toilet										5	0.00	20.9	0	0.0	
Toilet 2										0	0.00	20.9	0	0.0	
<b>ORAFOL/EHI</b>															
Stormwater Pit 1										0	0.00	20.9	0	0.0	
Stormwater Pit 2										0	0.00	20.9	0	0.0	
Stormwater Pit 3										0	0.00	20.9	0	0.0	
Stormwater Pit 4										0	0.00	20.9	0	0.0	
Stormwater Pit 5										0	0.00	20.9	0	0.0	
Stormwater Pit 6										15	0.00	20.9	0	0.0	
Electrical 1										0	0.00	20.9	0	0.0	
Stormwater Pit 7										0	0.00	20.9	0	0.0	
Stormwater Pit 8										0	0.00	20.9	0	0.0	
Site: Erskine Park										Date: 18/06/24			Start time: 0800	Finish time: 1600	
Monitoring personnel: LS / MS										Monitoring equipment: RK Eagle II					Bump test: Yes
Atmospheric pressure at start (mb): 1005										Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry, Wet ground		

Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Electrical 2						0	0.00	20.9	0	0.0	
Stormwater Pit 9						5	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15						0	0.00	20.9	0	0.0	
Stormwater Pit 16						0	0.00	20.9	0	0.0	
Bluescope Steel											
Service Pit 1						0	0.00	20.9	0	0.0	
Electrical Pit 1						0	0.00	20.9	0	0.0	
Service Pit 2						0	0.00	20.9	0	0.0	
Electrical Pit 2						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Shower						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						1	0.00	20.9	0	0.0	
Stormwater Pit 3						1	0.00	20.9	0	0.0	
Stormwater Pit 4						1	0.00	20.9	0	0.0	
Stormwater Pit 5						1	0.00	20.9	0	0.0	
Stormwater Pit 6						1	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Pump Room						0	0.00	20.9	0	0.0	

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence
6/02/2025	6/02/2025	23-25/09/2024	Inside all buildings or other enclosed structures within 250m of deposited waste.

Site: Erskine Park  
Monitoring personnel: LS  
Monitoring equipment: RK Eagle II  
Bump test: Yes  
Atmospheric pressure at start (mb): 1005  
Rising or falling: Rising  
Weather and ground conditions: 14C, cloudy, dry.

Location ID	Date	Time	Max			Stable					Comments	
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S		
Cleanaway												
Emergency shower	2024-09-25	9:18:00	-	-	-	0	0	21	0	0	-	-
Male Toilet 1	2024-09-25	9:19:00	-	-	-	65	0	21	0	0	-	-
Female Toilet 2	2024-09-25	9:26:00	-	-	-	60	0	21	0	0	-	-
Handicapped Toilet	2024-09-25	9:20:00	-	-	-	55	0	21	0	0	-	-
Office 7	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-	-
Server room	2024-09-25	9:20:00	-	-	-	0	0	21	0	0	-	-
Office 6	2024-09-25	9:20:00	-	-	-	0	0	21	0	0	-	-
Office 5	2024-09-25	9:20:00	-	-	-	0	0	21	0	0	-	-
Office 4	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-	-
Office 3	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-	-
Office 2	2024-09-25	9:22:00	-	-	-	0	0	21	0	0	-	-
Office 1	2024-09-25	9:24:00	-	-	-	0	0	21	0	0	-	-
Office 8	2024-09-25	9:24:00	-	-	-	20	0	21	0	0	-	-
Weighbridge	2024-09-25	9:24:00	-	-	-	30	0	21	0	0	-	-
Lunch Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-	-
Conference Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-	-
Lobby	2024-09-25	9:22:00	-	-	-	0	0	21	0	0	-	-
Male Toilet 2	2024-09-25	9:26:00	-	-	-	65	0	21	0	0	-	-
Female Toilet 2	2024-09-25	9:26:00	-	-	-	60	0	21	0	0	-	-
Handicapped Toilet 2	2024-09-25	9:26:00	-	-	-	30	0	21	0	0	-	-
Locker Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-	-
Stramit												
SW1	2024-09-24	12:32:15	-	-	-	0	0	21	0	0	-	-
SW2	2024-09-24	12:33:58	-	-	-	0	0	21	0	0	-	-
SW3	2024-09-24	12:35:43	-	-	-	0	0	21	0	0	-	-
SW4	2024-09-24	12:38:00	-	-	-	35	0	21	0	0	-	-
SW5	2024-09-24	12:39:40	-	-	-	55	0	21	0	0	-	-

Site: Erskine Park  
Monitoring personnel: LS  
Monitoring equipment: RK Eagle II  
Bump test: Yes  
Atmospheric pressure at start (mb): 1005  
Rising or falling: Rising  
Weather and ground conditions: 14C, cloudy, dry.

Location ID	Date	Time	Max			Stable					Comments	
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S		
SW6	2024-09-24	12:42:31	-	-	-	0	0	21	0	0	-	-
SW7	2024-09-24	12:42:31	-	-	-	0	0	21	0	0	-	-
WB	2024-09-24	13:51:49	-	-	-	5	0	21	0	0	-	-
MT 1	2024-09-24	12:57:21	-	-	-	95	0	21	0	0	-	-
LR 1	2024-09-24	12:55:09	-	-	-	85	0	21	0	0	-	-
MT 2	2024-09-24	12:49:33	-	-	-	0	0	21	0	0	-	-
LR 2	2024-09-24	12:46:50	-	-	-	20	0	21	0	0	-	-
Stockland Viscount Pooling												
SW1	2024-09-24	13:29:26	-	-	-	0	0	21	0	0	-	-
SW2	2024-09-24	13:30:40	-	-	-	0	0	21	0	0	-	-
SW3	2024-09-24	13:32:03	-	-	-	35	0	21	0	0	-	-
SW4	2024-09-24	13:33:05	-	-	-	0	0	21	0	0	-	-

SW5	2024-09-24	13:34:58	-	-	-	0	0	21	0	0	-
SW6	2024-09-24	13:36:21	-	-	-	35	0	21	0	0	-
SW7	2024-09-24	13:39:01	-	-	-	0	0	21	0	0	-
SW8	2024-09-24	13:39:51	-	-	-	5	0	21	0	0	-
SW9	2024-09-24	13:43:33	-	-	-	20	0	21	0	0	-
SW10	2024-09-24	13:45:20	-	-	-	15	0	21	0	0	-
Change Room			-	-	-	-	-	-	-	-	-
Lunchroom	2024-09-24	13:56:51	-	-	-	0	0	21	0	0	-
Male Toilet	2024-09-24	13:57:52	-	-	-	120	0	21	0	0	-
Warehouse	2024-09-24	13:42:44	-	-	-	25	0	21	0	0	-
Dincol			-	-	-	-	-	-	-	-	-
SW1	2024-09-24	14:16:34	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	14:17:41	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	14:19:17	-	-	-	0	0	21	0	0	-
SW4	2024-09-24	14:25:48	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	13:47:02	-	-	-	20	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: LS						Monitoring equipment: RK Eagle II				Bump test: Yes	
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry.	
Location ID	Date	Time	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
SW6	2024-09-24	13:49:42	-	-	-	15	0	21	0	0	-
SW7	2024-09-24	13:52:23	-	-	-	0	0	21	0	0	-
SW8	2024-09-24	14:27:43	-	-	-	0	0	0	0	0	-
Dispatch	2024-09-24	14:22:49	-	-	-	30	0	21	0	0	-
Toilet 1	2024-09-24	14:23:28	-	-	-	60	0	21	0	0	-
Elect Room	2024-09-24	14:10:36	-	-	-	20	0	21	0	0	-
Toilet 2	2024-09-24	15:17:56	-	-	-	55	0	21	0	0	-
Saputo			-	-	-	-	-	-	-	-	-
SW1	2024-09-24	7:34:36	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	7:31:59	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	7:47:00	-	-	-	15	0	21	0	0	-
SW4	2024-09-24	7:48:42	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	7:51:55	-	-	-	250	0	21	0	0	-
SW6	2024-09-24	7:59:12	-	-	-	35	0	21	0	0	-
E1	2024-09-24	7:36:39	-	-	-	15	0	21	0	0	-
E2	2024-09-24	7:37:58	-	-	-	5	0	21	0	0	-
E3	2024-09-24	7:39:47	-	-	-	35	0	21	0	0	-
E4	2024-09-24	7:41:50	-	-	-	0	0	21	0	0	-
E5	2024-09-24	7:53:57	-	-	-	65	0	21	0	0	-
E6	2024-09-24	7:55:48	-	-	-	40	0	21	0	0	-
LOSCAM			-	-	-	-	-	-	-	-	-
SW1	2024-09-24	10:35:58	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	10:36:34	-	-	-	0	0	21	0	0	-
SW3	-	-	-	-	-	-	-	-	-	-	-
SW4	2024-09-24	10:23:28	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	10:27:03	-	-	-	0	0	21	0	0	-
SW6	2024-09-24	10:29:45	-	-	-	0	0	0	0	0	-
SW7	2024-09-24	10:31:22	-	-	-	0	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: LS						Monitoring equipment: RK Eagle II				Bump test: Yes	
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry.	
Location ID	Date	Time	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
SW8	-	-	-	-	-	-	-	-	-	-	-
Wash Bay	2024-09-24	10:21:35	-	-	-	60	0	21	0	0	-
Male Toilet	2024-09-24	10:39:39	-	-	-	10	0	21	0	0	-
Warehouse Ambient	2024-09-24	10:22:40	-	-	-	0	0	21	0	0	-
Mainfreight			-	-	-	-	-	-	-	-	-
SW1	-	-	-	-	-	-	-	-	-	-	No Access
SW2	-	-	-	-	-	-	-	-	-	-	No Access
SW3	-	-	-	-	-	-	-	-	-	-	No Access
SW4	-	-	-	-	-	-	-	-	-	-	No Access
SW5	-	-	-	-	-	-	-	-	-	-	No Access
SW6	-	-	-	-	-	-	-	-	-	-	No Access
SW7	-	-	-	-	-	-	-	-	-	-	No Access
Dispatch office	-	-	-	-	-	-	-	-	-	-	No Access
Lunchroom	-	-	-	-	-	-	-	-	-	-	No Access
Toilet	-	-	-	-	-	-	-	-	-	-	No Access
Mulgoa Quarries			-	-	-	-	-	-	-	-	-
SW1	2024-09-24	9:16:00	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	9:17:10	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	9:18:33	-	-	-	0	0	21	0	0	-
SW4	2024-09-24	9:19:30	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	9:20:19	-	-	-	0	0	21	0	0	-
SW6	2024-09-24	9:21:30	-	-	-	0	0	21	0	0	-
SW7	2024-09-24	9:22:30	-	-	-	0	0	21	0	0	-
SW8	2024-09-24	9:23:33	-	-	-	0	0	21	0	0	-
SW9	2024-09-24	9:24:47	-	-	-	0	0	21	0	0	-
SW10	2024-09-24	9:25:28	-	-	-	0	0	21	0	0	-
SW11	2024-09-24	9:26:35	-	-	-	0	0	21	0	0	-
SW12	2024-09-24	9:28:05	-	-	-	0	0	21	0	0	-
SW13	2024-09-24	9:29:04	-	-	-	0	0	21	0	0	-

SW14	2024-09-24	9:30:28	-	-	-	25	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: LS						Monitoring equipment: RK Eagle II			Bump test: Yes		
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry.		
Location ID	Date	Time	CH4 PPM	Max CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
SW15	2024-09-24	9:31:34	-	-	-	15	0	21	0	0	-
Wash Bay	2024-09-24	9:40:22	-	-	-	45	0	21	0	0	-
Male Toilet	2024-09-24	9:38:44	-	-	-	55	0	21	0	0	-
Lunch Room	2024-09-24	9:35:13	-	-	-	0	0	21	0	0	-
<b>Darley Aluminium</b>											
SW1	2024-09-23	8:35:36	-	-	-	5	0	21	0	0	-
SW2	2024-09-23	8:36:51	-	-	-	0	0	21	0	0	-
SW3	2024-09-23	8:38:02	-	-	-	10	0	21	0	0	-
SW4	2024-09-23	8:39:10	-	-	-	0	0	21	0	0	-
SW5	2024-09-23	8:43:55	-	-	-	0	0	21	0	0	-
SW6	2024-09-23	8:45:39	-	-	-	0	0	21	0	0	-
SW7	2024-09-23	8:46:32	-	-	-	0	0	21	0	0	-
SW8	2024-09-23	8:42:32	-	-	-	0	0	21	0	0	-
Lunch Room	2024-09-23	8:49:07	-	-	-	15	0	21	0	0	-
Male Toilet	2024-09-23	8:52:34	-	-	-	55	0	21	0	0	-
<b>ORAFOL/EH1</b>											
SW1	2024-09-23	8:10:41	-	-	-	35	0	21	0	0	-
SW2	2024-09-23	8:09:41	-	-	-	40	0	21	0	0	-
SW3	2024-09-23	8:08:29	-	-	-	0	0	21	0	0	-
SW4	2024-09-23	8:06:42	-	-	-	0	0	21	0	0	-
SW5	2024-09-23	8:04:36	-	-	-	85	0	21	0	0	-
SW6	2024-09-23	8:02:32	-	-	-	60	0	21	0	0	-
SW7	2024-09-23	8:01:33	-	-	-	0	0	21	0	0	-
SW8	2024-09-23	8:00:13	-	-	-	5	0	21	0	0	-
SW9	2024-09-23	7:51:26	-	-	-	20	0	21	0	0	-
SW10	2024-09-23	7:50:29	-	-	-	0	0	21	0	0	-
SW11	2024-09-23	7:49:41	-	-	-	5	0	21	0	0	-
SW12	2024-09-23	7:47:36	-	-	-	0	0	21	0	0	-
SW13	2024-09-23	7:46:22	-	-	-	35	0	21	0	0	-
SW14	2024-09-23	7:45:18	-	-	-	15	0	21	0	0	-
SW15	2024-09-23	7:44:30	-	-	-	0	0	21	0	0	-
SW16	2024-09-23	7:53:17	-	-	-	0	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: LS						Monitoring equipment: RK Eagle II			Bump test: Yes		
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry.		
Location ID	Date	Time	CH4 PPM	Max CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
SW17	2024-09-23	7:57:01	-	-	-	0	0	21	0	0	-
<b>Bluescope Steel</b>											
Service Pit 1	2024-09-23	7:20:28	-	-	-	80	0	21	0	0	-
Electrical Pit 1	2024-09-23	7:13:37	-	-	-	60	0	21	0	0	-
Indoor cart celler	2024-09-23	7:11:12	-	-	-	0	0	21	0	0	-
Office	2024-09-23	7:18:19	-	-	-	0	0	21	0	0	-
Shower	2024-09-23	7:09:01	-	-	-	0	0	21	0	0	-
Toilet	2024-09-23	7:08:28	-	-	-	0	0	21	0	0	-
SW Pit	2024-09-23	7:03:30	-	-	-	0	0	21	0	0	-
SW pit adjacent service road 1	2024-09-23	6:44:57	-	-	-	10	0	21	0	0	-
SW pit adjacent service road 2	2024-09-23	6:46:25	-	-	-	35	0	21	0	0	-
SW pit adjacent service road 3	2024-09-23	6:47:42	-	-	-	30	0	21	0	0	-
SW pit adjacent service road 4	2024-09-23	6:48:57	-	-	-	10	0	21	10	0	-
SW Pit 5	2024-09-23	6:50:40	-	-	-	60	0	21	0	0	-
SW Pit 6	2024-09-23	6:52:51	-	-	-	30	0	21	0	0	-
SW Pit 7	2024-09-23	6:54:33	-	-	-	35	0	21	0	0	-
SW Pit 8	2024-09-23	6:55:49	-	-	-	0	0	21	0	0	-
SW Pit 9	2024-09-23	8:55:18	-	-	-	0	0	21	0	0	-
SW Pit	2024-09-23	7:03:30	-	-	-	0	0	21	0	0	-
<b>Date Monitoring Data Uploaded</b>	<b>Date Monitoring Data Obtained</b>	<b>Date Monitored</b>	<b>Sampled Point as per Licence</b>								
6/02/2025	6/02/2025	16-19/12/2024	Inside all buildings or other enclosed structures within 250m of deposited waste.								
Site: Erskine Park											
Monitoring personnel: JB						Monitoring equipment: RK Eagle II			Bump test: Yes		
Atmospheric pressure at start (mb): 1015						Rising or falling: Falling			Weather and ground conditions: 17C, clear, dry.		
Location ID	Date	Time	CH4 PPM	Max CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
<b>Cleanaway</b>											
Emergency shower	2024-12-16	6:18:48 AM	-	-	-	0	0	21	0	0	-
Male Toilet 1	2024-12-16	6:18:37 AM	-	-	-	0	0	21	0	0	-
Female Toilet 2	2024-12-16	6:20:50 AM	-	-	-	0	0	21	0	0	-
Handicapped Toilet	2024-12-16	6:18:15 AM	-	-	-	0	0	21	0	0	-
Office 7	2024-12-16	6:17:31 AM	-	-	-	0	0	21	0	0	-
Server room	2024-12-16	6:18:01 AM	-	-	-	0	0	21	0	0	-
Office 6	2024-12-16	6:17:43 AM	-	-	-	0	0	21	0	0	-
Office 5	-	-	-	-	-	-	-	-	-	-	-
Office 4	2024-12-16	6:17:19 AM	-	-	-	0	0	21	0	0	-
Office 3	-	-	-	-	-	-	-	-	-	-	-
Office 2	2024-12-16	6:16:56 AM	-	-	-	0	0	21	0	0	-
Office 1	2024-12-16	6:19:45 AM	-	-	-	0	0	21	0	0	-



Office 8	2024-12-16	6:19:22 AM	-	-	-	0	0	21	0	0	-
Weighbridge	2024-12-16	6:19:34 AM	-	-	-	0	0	21	0	0	-
Lunch Room	2024-12-16	6:20:08 AM	-	-	-	0	0	21	0	0	-
Conference Room	2024-12-16	6:19:57 AM	-	-	-	0	0	21	0	0	-
Lobby	2024-12-16	6:16:27 AM	-	-	-	0	0	21	0	0	-
Male Toilet 2	2024-12-16	6:20:19 AM	-	-	-	0	0	21	0	0	-
Female Toilet 2	2024-12-16	6:20:50 AM	-	-	-	0	0	21	0	0	-
Handicapped Toilet 2	2024-12-16	6:20:29 AM	-	-	-	0	0	21	0	0	-
Locker Room	2024-12-16	6:11:43 AM	-	-	-	45	0	21	0	0	-
Stramit											
SW1	2024-12-16	8:09:56 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-16	8:10:25 AM	-	-	-	0	0	21	0	0	-
SW3	2024-12-16	8:10:41 AM	-	-	-	0	0	21	0	0	-
SW4	2024-12-16	8:10:54 AM	-	-	-	0	0	21	0	0	-

Site: Erskine Park

Monitoring personnel: JB Monitoring equipment: RK Eagle II Bump test: Yes  
 Atmospheric pressure at start (mb): 1015 Rising or falling: Falling Weather and ground conditions: 17C, clear, dry.

Location ID	Date	Time	CH4 PPM	Max			Stable				Comments
				CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
SW5	2024-12-16	8:11:05 AM	-	-	-	0	0	21	0	0	-
SW6	2024-12-16	8:11:17 AM	-	-	-	0	0	21	0	0	-
SW7	-	-	-	-	-	-	-	-	-	-	-
WB	2024-12-16	8:09:46 AM	-	-	-	0	0	21	0	0	-
MT 1	2024-12-16	8:08:42 AM	-	-	-	120	0	21	0	0	-
LR 1	2024-12-16	8:09:33 AM	-	-	-	0	0	21	0	0	-
MT 2	2024-12-16	8:08:07 AM	-	-	-	55	0	21	0	0	-
LR 2	2024-12-16	8:09:21 AM	-	-	-	0	0	21	0	0	-
Stockland Viscount Pooling											
SW1	2024-12-19	10:39:12 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-19	10:39:35 AM	-	-	-	0	0	21	0	0	-
SW3	2024-12-19	10:39:55 AM	-	-	-	0	0	21	0	0	-
SW4	2024-12-19	10:40:28 AM	-	-	-	0	0	21	0	0	-
SW5	2024-12-19	10:40:51 AM	-	-	-	0	0	21	0	0	-
SW6	2024-12-19	10:41:03 AM	-	-	-	20	0	21	0	0	-
SW7	2024-12-19	10:41:36 AM	-	-	-	15	0	21	0	0	-
SW8	2024-12-19	10:41:57 AM	-	-	-	25	0	21	0	0	-
SW9	2024-12-19	10:42:27 AM	-	-	-	15	0	21	0	0	-
SW10	2024-12-19	10:43:43 AM	-	-	-	0	0	21	0	0	-
Change Room	-	-	-	-	-	-	-	-	-	-	-
Lunchroom	2024-12-19	10:45:57 AM	-	-	-	0	0	21	0	0	-
Male Toilet	2024-12-19	10:46:16 AM	-	-	-	0	0	21	0	0	-
Warehouse	2024-12-19	10:44:13 AM	-	-	-	0	0	21	0	0	-
Dinzel											
SW1	2024-12-16	7:20:00 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-16	7:19:49 AM	-	-	-	0	0	21	0	0	-
SW3	2024-12-16	7:20:37 AM	-	-	-	10	0	21	0	0	-

Site: Erskine Park

Monitoring personnel: JB Monitoring equipment: RK Eagle II Bump test: Yes  
 Atmospheric pressure at start (mb): 1015 Rising or falling: Falling Weather and ground conditions: 17C, clear, dry.

Location ID	Date	Time	CH4 PPM	Max			Stable				Comments
				CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
SW4	2024-12-16	7:17:15 AM	-	-	-	10	0	21	0	0	-
SW5	2024-12-16	7:08:39 AM	-	-	-	10	0	21	0	0	-
SW6	2024-12-16	7:18:33 AM	-	-	-	0	0	21	0	0	-
SW7	2024-12-16	7:18:14 AM	-	-	-	0	0	21	0	0	-
SW8	2024-12-16	7:19:05 AM	-	-	-	0	0	21	0	0	-
Dispatch	2024-12-16	7:19:37 AM	-	-	-	0	0	21	0	0	-
Toilet 1	-	-	-	-	-	-	-	-	-	-	-
Elct. Room	2024-12-16	7:18:00 AM	-	-	-	0	0	21	0	0	-
Toilet 2	-	-	-	-	-	-	-	-	-	-	-
Saputo											
SW1	2024-12-19	10:08:20 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-19	10:08:36 AM	-	-	-	0	0	21	0	0	-
SW3	2024-12-19	10:10:31 AM	-	-	-	0	0	21	0	0	-
SW4	2024-12-19	10:02:03 AM	-	-	-	0	0	21	0	0	-
SW5	2024-12-19	10:10:10 AM	-	-	-	0	0	21	0	0	-
SW6	2024-12-19	10:10:20 AM	-	-	-	5	0	21	0	0	-
E1	2024-12-19	10:11:13 AM	-	-	-	0	0	21	0	0	-
E2	2024-12-19	10:11:01 AM	-	-	-	0	0	21	0	0	-
E3	2024-12-19	10:10:51 AM	-	-	-	0	0	21	0	0	-
E4	2024-12-19	10:10:41 AM	-	-	-	0	0	21	0	0	-
E5	2024-12-19	10:03:27 AM	-	-	-	25	0	21	0	0	-
E6	2024-12-19	10:05:01 AM	-	-	-	0	0	21	0	0	-
LOSCAM											
SW1	2024-12-17	10:21:14 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-17	10:21:26 AM	-	-	-	0	0	21	0	0	-
SW3	-	-	-	-	-	-	-	-	-	-	-
SW4	2024-12-17	10:22:00 AM	-	-	-	0	0	21	0	0	-

Site: Erskine Park

Monitoring personnel: JB Monitoring equipment: RK Eagle II Bump test: Yes  
 Atmospheric pressure at start (mb): 1015 Rising or falling: Falling Weather and ground conditions: 17C, clear, dry.

Location ID	Date	Time	CH4 PPM	Max	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
-------------	------	------	---------	-----	-------------	----------------	---------	-------------	----------------	----	-----	----------

Location ID	Date	Time	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Rising or falling: Falling		Stable			Comments
						CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
SW5	2024-12-17	10:21:11 AM	-	-	-	0	0	21	0	0	-
SW6	2024-12-17	10:22:43 AM	-	-	-	0	0	21	0	0	-
SW7	2024-12-17	10:22:33 AM	-	-	-	0	0	21	0	0	-
SW8	-	-	-	-	-	-	-	-	-	-	-
Wash Bay	2024-12-17	10:21:38 AM	-	-	-	0	0	21	0	0	-
Male Toilet	2024-12-17	10:20:59 AM	-	-	-	0	0	21	0	0	-
Warehouse Ambient	2024-12-17	10:21:49 AM	-	-	-	0	0	21	0	0	-
<b>Mainfreight</b>											
SW1	-	-	-	-	-	-	-	-	-	-	No Access
SW2	-	-	-	-	-	-	-	-	-	-	No Access
SW3	-	-	-	-	-	-	-	-	-	-	No Access
SW4	-	-	-	-	-	-	-	-	-	-	No Access
SW5	-	-	-	-	-	-	-	-	-	-	No Access
SW6	-	-	-	-	-	-	-	-	-	-	No Access
SW7	-	-	-	-	-	-	-	-	-	-	No Access
Dispatch office	-	-	-	-	-	-	-	-	-	-	No Access
Lunchroom	-	-	-	-	-	-	-	-	-	-	No Access
Toilet	-	-	-	-	-	-	-	-	-	-	No Access
<b>Mulgoa Quarries</b>											
SW1	2024-12-16	8:47:26 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-16	8:47:37 AM	-	-	-	0	0	21	0	0	-
SW3	2024-12-16	8:47:49 AM	-	-	-	0	0	21	0	0	-
SW4	2024-12-16	8:47:59 AM	-	-	-	0	0	21	0	0	-
SW5	2024-12-16	8:48:08 AM	-	-	-	0	0	21	0	0	-
SW6	2024-12-16	8:48:19 AM	-	-	-	0	0	21	0	0	-
SW7	2024-12-16	8:48:28 AM	-	-	-	0	0	21	0	0	-
SW8	2024-12-16	8:48:38 AM	-	-	-	0	0	21	0	0	-
SW9	2024-12-16	8:49:09 AM	-	-	-	0	0	21	0	0	-
SW10	2024-12-16	8:48:59 AM	-	-	-	0	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: JB						Monitoring equipment: RK Eagle II			Bump test: Yes		
Atmospheric pressure at start (mb): 1015						Rising or falling: Falling			Weather and ground conditions: 17C, clear, dry.		
Location ID	Date	Time	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
SW11	2024-12-16	8:48:48 AM	-	-	-	0	0	21	0	0	-
SW12	2024-12-16	8:40:35 AM	-	-	-	10	0	21	0	0	-
SW13	2024-12-16	8:49:29 AM	-	-	-	0	0	21	0	0	-
SW14	2024-12-16	8:49:41 AM	-	-	-	0	0	21	0	0	-
SW15	2024-12-16	8:49:51 AM	-	-	-	0	0	21	0	0	-
Wash Bay	2024-12-16	8:50:05 AM	-	-	-	0	0	21	0	0	-
Male Toilet	2024-12-16	8:47:15 AM	-	-	-	0	0	21	0	0	-
Lunch Room	2024-12-16	8:46:52 AM	-	-	-	0	0	21	0	0	-
<b>Darley Aluminium</b>											
SW1	2024-12-17	9:18:04 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-17	9:20:04 AM	-	-	-	0	0	21	0	0	-
SW3	2024-12-17	9:20:15 AM	-	-	-	0	0	21	0	0	-
SW4	2024-12-17	9:20:26 AM	-	-	-	0	0	21	0	0	-
SW5	2024-12-17	9:20:37 AM	-	-	-	0	0	21	0	0	-
SW6	2024-12-17	9:20:54 AM	-	-	-	0	0	21	0	0	-
SW7	2024-12-17	9:21:04 AM	-	-	-	0	0	21	0	0	-
SW8	2024-12-17	9:37:00 AM	-	-	-	0	0	21	0	0	-
Lunch Room	2024-12-17	9:17:42 AM	-	-	-	0	0	21	0	0	-
Male Toilet	2024-12-17	9:17:17 AM	-	-	-	0	0	21	0	0	-
<b>ORAFOL/EH</b>											
SW1	2024-12-17	9:52:22 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-17	9:52:12 AM	-	-	-	0	0	21	0	0	-
SW3	2024-12-17	9:52:01 AM	-	-	-	0	0	21	0	0	-
SW4	2024-12-17	9:51:51 AM	-	-	-	0	0	21	0	0	-
SW5	2024-12-17	9:51:41 AM	-	-	-	0	0	21	0	0	-
SW6	2024-12-17	9:51:31 AM	-	-	-	0	0	21	0	0	-
SW7	2024-12-17	9:51:21 AM	-	-	-	0	0	21	0	0	-
SW8	2024-12-17	9:51:11 AM	-	-	-	0	0	21	0	0	-
SW9	2024-12-17	9:42:30 AM	-	-	-	35	0	21	0	0	-
SW10	2024-12-17	9:50:39 AM	-	-	-	0	0	21	0	0	-
SW11	2024-12-17	9:50:20 AM	-	-	-	0	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: JB						Monitoring equipment: RK Eagle II			Bump test: Yes		
Atmospheric pressure at start (mb): 1015						Rising or falling: Falling			Weather and ground conditions: 17C, clear, dry.		
Location ID	Date	Time	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
SW12	2024-12-17	9:50:10 AM	-	-	-	0	0	21	0	0	-
SW13	2024-12-17	9:49:48 AM	-	-	-	0	0	21	0	0	-
SW14	2024-12-17	9:49:39 AM	-	-	-	0	0	21	0	0	-
SW15	2024-12-17	9:49:26 AM	-	-	-	0	0	21	0	0	-
SW16	2024-12-17	9:49:59 AM	-	-	-	0	0	21	0	0	-
SW17	2024-12-17	9:51:00 AM	-	-	-	0	0	21	0	0	-
<b>Bluescope Steel</b>											
Service Pit 1	2024-12-19	9:36:01 AM	-	-	-	0	0	21	0	0	-
Electrical Pit 1	2024-12-19	9:34:32 AM	-	-	-	0	0	21	0	0	-
Indoor cart celler	2024-12-19	9:34:42 AM	-	-	-	0	0	21	0	0	-
Office	2024-12-19	9:35:50 AM	-	-	-	0	0	21	0	0	-

Shower	2024-12-19	9:35:37 AM	-	-	-	0	0	21	0	0	-
Toilet	2024-12-19	9:35:28 AM	-	-	-	0	0	21	0	0	-
SW Pit	2024-12-19	9:37:44 AM	-	-	-	0	0	21	0	0	-
SW pit adjacent service road 1	2024-12-19	9:01:37 AM	-	-	-	5	0	21	0	0	-
SW pit adjacent service road 2	-	-	-	-	-	-	-	-	-	-	-
SW pit adjacent service road 3	2024-12-19	9:02:47 AM	-	-	-	15	0	21	0	0	-
SW pit adjacent service road 4	2024-12-19	9:36:48 AM	-	-	-	0	0	21	0	0	-
SW Pit 5	2024-12-19	9:36:37 AM	-	-	-	0	0	21	0	0	-
SW Pit 6	2024-12-19	9:36:26 AM	-	-	-	0	0	21	0	0	-
SW Pit 7	2024-12-19	9:36:11 AM	-	-	-	0	0	21	0	0	-
SW Pit 8	2024-12-19	9:07:37 AM	-	-	-	10	0	21	0	0	-
SW Pit 9	-	-	-	-	-	-	-	-	-	-	-
SW Pit	2024-12-19	9:37:44 AM	-	-	-	0	0	21	0	0	-