



## Pollutant Monitoring Results - Gas Accumulation - Onsite Buildings 2020- December 2023

EPL No:	4865
Entity Name	Enviroguard Pty Ltd
Site:	4 Quarry Road, Erskine Park NSW
Monitoring Frequency:	Quarterly
Link to NSW EPA Register:	<a href="#">Click Here</a>

Disclaimer - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the requirements issued in writing by the Environment Protection Authority. To the best of Cleanaway's knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior consent from Cleanaway. For more details on publication of pollution monitoring data refer to the NSW EPA Website [www.epa.nsw.gov.au](http://www.epa.nsw.gov.au)

	Maximum Building Accumulation Readings, CH4 ppm v/v		
	Workshop	Transfer Station	Administration Building
29-Sep-20	5	5	5
9-Dec-20	5	5	5
4-Mar-21	5	5	5
9-Jun-21	5	5	5
27-Sep-21	5	5	5
13-Dec-21	5	5	5
22-Mar-22	5	5	5
25-Jul-22	5	5	5
21-Sep-22	5	5	5
21-Dec-22	5	5	5
13-Mar-23	5	5	5
19-Jun-23	5	5	5

\*Note NSW EPA guidance criteria for further action is 10.000 ppm v/v

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence									
6/02/2025		27/09/2023	Inside all buildings or other enclosed structures within 250m of deposited waste,									
Site: Erskine Park		Date: 27/09/23	Start time: 0800 Finish time: 1600									
Monitoring personnel: SW / JC		Monitoring equipment: RK Eagle II	Bump test: Yes									
Atmospheric pressure at start (mb):		Rising or falling:	Weather and ground conditions: 18C, Sunny, Dry, Dry Ground									
Location ID	Max			Stable					Comments			
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)		CO	H2S	
Cleanaway												
Emergency Shower						0	0.00	20.9	0	0.0		
Male Toilet						0	0.00	20.9	0	0.0		
Female Toilet						0	0.00	20.9	0	0.0		
Handicap Toilet						0	0.00	20.9	0	0.0		
Office 7						0	0.00	20.9	0	0.0		
Server room						0	0.00	20.9	0	0.0		
Office 6						0	0.00	20.9	0	0.0		
Office 5						0	0.00	20.9	0	0.0		
Office 4						0	0.00	20.9	0	0.0		
Office 3						0	0.00	20.9	0	0.0		
Office 2						0	0.00	20.9	0	0.0		
Office 1						0	0.00	20.9	0	0.0		
Office 8						0	0.00	20.9	0	0.0		
Weighbridge						0	0.00	20.9	0	0.0		
Meal Room						0	0.00	20.9	0	0.0		
Conference Room						0	0.00	20.9	0	0.0		
Lobby						0	0.00	20.9	0	0.0		
Male Toilet 2						0	0.00	20.9	0	0.0		
Female Toilet 2						0	0.00	20.9	0	0.0		
Unisex Toilet						0	0.00	20.9	0	0.0		
Locker Room						0	0.00	20.9	0	0.0		
Stramit												
Stormwater Pit 1												No Access to site
Stormwater Pit 2												No Access to site

Stormwater Pit 3																		No Access to site			
Stormwater Pit 4																		No Access to site			
Stormwater Pit 5																		No Access to site			
Stormwater Pit 6																		No Access to site			
Stormwater Pit 7																		No Access to site			
Site: Erskine Park										Date: 27/09/23			Start time: 0800		Finish time: 1600						
Monitoring personnel: SW / JC					Monitoring equipment: RK Eagle II								Bump test: Yes								
Atmospheric pressure at start (mb):										Rising or falling:			Weather and ground conditions: 18C, Sunny, Dry, Dry Ground								
Location ID	CH4 PPM		CO2 (% v/v)		Max Min O2 (% v/v)		CO		H2S		Stable CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)		CO		H2S		Comments
Weighbridge																					No Access to site
Men Toilet 1																					No Access to site
Lunch Room 1																					No Access to site
Men Toilet 2																					No Access to site
Lunch Room 2																					No Access to site
<b>Stockland/Viscount Pooling</b>																					
Stormwater Pit 1											0	0.00	20.9	0	0.0						
Stormwater Pit 2											0	0.00	20.9	0	0.0						
Stormwater Pit 3											0	0.00	20.9	0	0.0						
Stormwater Pit 4											0	0.00	20.9	0	0.0						
Stormwater Pit 5											0	0.00	20.9	0	0.0						
Stormwater Pit 6											0	0.00	20.9	0	0.0						
Stormwater Pit 7											0	0.00	20.9	0	0.0						
Stormwater Pit 8											0	0.00	20.9	0	0.0						
Stormwater Pit 9											0	0.00	20.9	0	0.0						
Stormwater Pit 10											0	0.00	20.9	0	0.0						
Stormwater Pit 11											0	0.00	20.9	0	0.0						
Stormwater Pit 12											0	0.00	20.9	0	0.0						
Stormwater Pit 13	10		0.00		20.9		0		0.0		0	0.00	20.9	0	0.0						
Stormwater Pit 14											0	0.00	20.9	0	0.0						
Change Room											0	0.00	20.9	0	0.0						
Lunch Room											0	0.00	20.9	0	0.0						
Toilet											0	0.00	20.9	0	0.0						
Warehouse											0	0.00	20.9	0	0.0						
<b>Dintel</b>																					
Stormwater Pit 1											0	0.00	20.9	0	0.0						
Stormwater Pit 2											0	0.00	20.9	0	0.0						
Stormwater Pit 3											0	0.00	20.9	0	0.0						
Stormwater Pit 4											0	0.00	20.9	0	0.0						
Stormwater Pit 5											0	0.00	20.9	0	0.0						
Site: Erskine Park										Date: 27/09/23			Start time: 0800		Finish time: 1600						
Monitoring personnel: SW / JC					Monitoring equipment: RK Eagle II								Bump test: Yes								
Atmospheric pressure at start (mb):										Rising or falling:			Weather and ground conditions: 18C, Sunny, Dry, Dry Ground								
Location ID	CH4 PPM		CO2 (% v/v)		Max Min O2 (% v/v)		CO		H2S		Stable CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)		CO		H2S		Comments
Stormwater Pit 6											0	0.00	20.9	0	0.0						
Stormwater Pit 7											0	0.00	20.9	0	0.0						
Stormwater Pit 8											0	0.00	20.9	0	0.0						
Dispatch Office											0	0.00	20.9	0	0.0						
Toilet 1											0	0.00	20.9	0	0.0						
Electrical Room											15	0.00	20.9	0	0.0						
Toilet 2											0	0.00	20.9	0	0.0						
<b>Saputo</b>																					
Stormwater Pit 1											0	0.00	20.9	0	0.0						
Stormwater Pit 2											0	0.00	20.9	0	0.0						
Stormwater Pit 3											0	0.00	20.9	0	0.0						
Stormwater Pit 4											0	0.00	20.9	0	0.0						
Stormwater Pit 5											0	0.00	20.9	0	0.0						
Stormwater Pit 6											0	0.00	20.9	0	0.0						
Electrical Pit 1											0	0.00	20.9	0	0.0						
Electrical Pit 2											0	0.00	20.9	0	0.0						
Electrical Pit 3											55	0.02	20.9	0	0.0						
Electrical Pit 4											0	0.00	20.9	0	0.0						
Electrical Pit 5	1200		1.04		19.7		0		0.0		410	0.42	20.9	0	0.0						

Electrical Pit 6						0	0.00	20.9	0	0.0	
Electrical Pit 7						0	0.00	20.9	0	0.0	
Electrical Pit 8						0	0.00	20.9	0	0.0	
<b>LOSCAM</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2	15	0.00	20.9	0	0.0	10	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6	5	0.00	20.9	0	0.0	0	0.00	20.9	0	0.0	
Stormwater Pit 7						5	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 27/09/23	Start time: 0800			Finish time: 1600	
Monitoring personnel: SW / JC	Monitoring equipment: RK Eagle II								Bump test: Yes		
Atmospheric pressure at start (mb):						Rising or falling:			Weather and ground conditions: 18C, Sunny, Dry, Dry Ground		
Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 8	15	0.00	20.9	0	0.0	5	0.00	20.9	0	0.0	
Wash Bay						0	0.00	20.9	0	0.0	
Storage Shed						0	0.00	20.9	0	0.0	
Toilet 1 - Male						30	0.00	20.9	0	0.0	
Toilet 2 - Female						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Toilet 3						0	0.00	20.9	0	0.0	
<b>Mainfreight</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2	10	0.02	20.9	0	0.0	5	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6	45	0.00	20.9	0	0.0	30	0.00	20.9	0	0.0	
Stormwater Pit 7	30	0.00	20.9	0	0.0	15	0.00	20.9	0	0.0	
Dispatch office						0	0.00	20.9	0	0.0	
Lunchroom						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
<b>Mulgoa Quarries</b>											
Stormwater Pit 1	10	0.00	20.9	0	0.0	5	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7	5	0.00	20.9	0	0.0	0	0.00	20.9	0	0.0	
Stormwater Pit 8						5	0.00	20.9	0	0.0	
Stormwater Pit 9	10	0.00	20.9	0	0.0	5	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 27/09/23	Start time: 0800			Finish time: 1600	
Monitoring personnel: SW / JC	Monitoring equipment: RK Eagle II								Bump test: Yes		
Atmospheric pressure at start (mb):						Rising or falling:			Weather and ground conditions: 18C, Sunny, Dry, Dry Ground		
Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 14	10	0.00	20.9	0	0.0	5	0.00	20.9	0	0.0	
Stormwater Pit 15	5	0.00	20.9	0	0.0	0	0.00	20.9	0	0.0	
Wash Bay						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Kitchen						0	0.00	20.9	0	0.0	
<b>Darley Aluminium</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3	5	0.00	20.9	0	0.0	0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7	15	0.00	20.9	0	0.0	5	0.00	20.9	0	0.0	
Stormwater Pit 8	35	0.00	20.9	0	0.0	15	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Warehouse						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Toilet 2						35	0.00	20.9	0	0.0	

Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5	5	0.00	20.9	0	0.0	0	0.00	20.9	0	0.0	
Stormwater Pit 6	55	0.00	20.9	0	0.0	0	0.00	20.9	0	0.0	
Electrical 1						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						15	0.00	20.9	0	0.0	
Electrical 2						140	0.78	20.3	0	0.0	
Stormwater Pit 9						15	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 27/09/23		Start time: 0800		Finish time: 1600	
Monitoring personnel: SW / JC			Monitoring equipment: RK Eagle II						Bump test: Yes		
Atmospheric pressure at start (mb):						Rising or falling:			Weather and ground conditions: 18C, Sunny, Dry, Dry Ground		
Max											
Stable											
Comments											
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15	10	0.00	20.9	0	0.0	0	0.00	20.9	0	0.0	
Stormwater Pit 16						35	0.00	20.9	0	0.0	
<b>Bluescope Steel</b>											
Service Pit 1						0	0.00	20.9	0	0.0	
Electrical Pit 1						0	0.00	20.9	0	0.0	
Service Pit 2						0	0.00	20.9	0	0.0	
Electrical Pit 2						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Shower						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3	16	0.00	20.9	0	0.0	10	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5	5	0.00	20.9	0	0.0	0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Pump Room											No Access - Construction

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence
6/02/2025		27/09/2023	Inside all buildings or other enclosed structures within 250m of deposited waste,

Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
<b>Cleanaway</b>											
Emergency Shower						0	0.00	20.9	0	0.0	
Male Toilet						0	0.00	20.9	0	0.0	
Female Toilet						0	0.00	20.9	0	0.0	
Handicap Toilet						0	0.00	20.9	0	0.0	
Office 7						0	0.00	20.9	0	0.0	
Server room						0	0.00	20.9	0	0.0	
Office 6						0	0.00	20.9	0	0.0	
Office 5						0	0.00	20.9	0	0.0	
Office 4						0	0.00	20.9	0	0.0	
Office 3						0	0.00	20.9	0	0.0	
Office 2						0	0.00	20.9	0	0.0	
Office 1						0	0.00	20.9	0	0.0	
Office 8						0	0.00	20.9	0	0.0	
Weighbridge						0	0.00	20.9	0	0.0	
Meal Room						0	0.00	20.9	0	0.0	
Conference Room						0	0.00	20.9	0	0.0	
Lobby						0	0.00	20.9	0	0.0	
Male Toilet 2						0	0.00	20.9	0	0.0	
Female Toilet 2						0	0.00	20.9	0	0.0	
Unisex Toilet						0	0.00	20.9	0	0.0	
Locker Room						0	0.00	20.9	0	0.0	

<b>Stramit</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 14/12/23	Start time: 0800			Finish time:		
Monitoring personnel: JC			Monitoring equipment: RK Eagle II			Rising or falling: Falling			Weather and ground conditions: Rain, cloud, hot 24C			
Atmospheric pressure at start (mb): 1006						Rising or falling: Falling			Weather and ground conditions: Rain, cloud, hot 24C			
Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	Stable				Comments	
							CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		H2S
Stormwater Pit 7							0	0.00	20.9	0	0.0	
Weighbridge							0	0.00	20.9	0	0.0	
Men Toilet 1							0	0.00	20.9	0	0.0	
Lunch Room 1							0	0.00	20.9	0	0.0	
Men Toilet 2							0	0.00	20.9	0	0.0	
Lunch Room 2							0	0.00	20.9	0	0.0	
<b>Stockland/Viscount</b>												
<b>Pooling</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							0	0.00	20.9	0	0.0	
Stormwater Pit 8							0	0.00	20.9	0	0.0	
Stormwater Pit 9							0	0.00	20.9	0	0.0	
Stormwater Pit 10							0	0.00	20.9	0	0.0	
Stormwater Pit 11							0	0.00	20.9	0	0.0	
Stormwater Pit 12							0	0.00	20.9	0	0.0	
Stormwater Pit 13							0	0.00	20.9	0	0.0	
Stormwater Pit 14							0	0.00	20.9	0	0.0	
Change Room							0	0.00	20.9	0	0.0	
Lunch Room							0	0.00	20.9	0	0.0	
Toilet							0	0.00	20.9	0	0.0	
Warehouse							0	0.00	20.9	0	0.0	
<b>Dintel</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 14/12/23	Start time: 0800			Finish time:		
Monitoring personnel: JC			Monitoring equipment: RK Eagle II			Rising or falling: Falling			Weather and ground conditions: Rain, cloud, hot 24C			
Atmospheric pressure at start (mb): 1006						Rising or falling: Falling			Weather and ground conditions: Rain, cloud, hot 24C			
Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	Stable				Comments	
							CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		H2S
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							0	0.00	20.9	0	0.0	
Stormwater Pit 8							80	0.00	20.9	0	0.0	
Dispatch Office							0	0.00	20.9	0	0.0	
Toilet 1							0	0.00	20.9	0	0.0	
Electrical Room							0	0.00	20.9	0	0.0	
Toilet 2							0	0.00	20.9	0	0.0	
<b>Saputo</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Electrical Pit 1							0	0.00	20.9	0	0.0	
Electrical Pit 2							0	0.00	20.9	0	0.0	
Electrical Pit 3							0	0.00	20.9	0	0.0	
Electrical Pit 4							0	0.00	20.9	0	0.0	
Electrical Pit 5							0	0.00	20.9	0	0.0	
Electrical Pit 6							0	0.00	20.9	0	0.0	
Electrical Pit 7							0	0.00	20.9	0	0.0	
Electrical Pit 8							0	0.00	20.9	0	0.0	
<b>LOSCAM</b>												
Stormwater Pit 1							0	0.00	20.9	0	0.0	

Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Site: Erskine Park											
Monitoring personnel: JC		Monitoring equipment: RK Eagle II				Date: 14/12/23		Start time: 0800		Finish time:	
Atmospheric pressure at start (mb): 1006				Rising or falling: Falling				Weather and ground conditions: Rain, cloud, hot 24C		Bump test: Yes	
Location ID		Max						Stable		Comments	
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Wash Bay						0	0.00	20.9	0	0.0	
Storage Shed						0	0.00	20.9	0	0.0	
Toilet 1 - Male						0	0.00	20.9	0	0.0	
Toilet 2 - Female						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Toilet 3						0	0.00	20.9	0	0.0	
<b>Mainfreight</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Dispatch office						0	0.00	20.9	0	0.0	
Lunchroom						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
<b>Mulgoa Quarries</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 14/12/23		Start time: 0800		Finish time:	
Monitoring personnel: JC		Monitoring equipment: RK Eagle II						Weather and ground conditions: Rain, cloud, hot 24C		Bump test: Yes	
Atmospheric pressure at start (mb): 1006				Rising or falling: Falling							
Location ID		Max						Stable		Comments	
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15						0	0.00	20.9	0	0.0	
Wash Bay						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Kitchen						0	0.00	20.9	0	0.0	
<b>Darley Aluminium</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Warehouse						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Toilet 2						0	0.00	20.9	0	0.0	
<b>ORAFOL/EHI</b>											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	

Stormwater Pit 6						0	0.00	20.9	0	0.0		
Electrical 1						0	0.00	20.9	0	0.0		
Stormwater Pit 7						0	0.00	20.9	0	0.0		
Stormwater Pit 8						0	0.00	20.9	0	0.0		
Site: Erskine Park						Date: 14/12/23	Start time: 0800		Finish time:			
Monitoring personnel: JC		Monitoring equipment: RK Eagle II			Rising or falling: Falling			Weather and ground conditions: Rain, cloud, hot 24C				
Atmospheric pressure at start (mb): 1006								Bump test: Yes				
Location ID	Max				Stable					Comments		
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		H2S	
Electrical 2						0	0.00	20.9	0	0.0		
Stormwater Pit 9						0	0.00	20.9	0	0.0		
Stormwater Pit 10						0	0.00	20.9	0	0.0		
Stormwater Pit 11						0	0.00	20.9	0	0.0		
Stormwater Pit 12						0	0.00	20.9	0	0.0		
Stormwater Pit 13						0	0.00	20.9	0	0.0		
Stormwater Pit 14						0	0.00	20.9	0	0.0		
Stormwater Pit 15						0	0.00	20.9	0	0.0		
Stormwater Pit 16						0	0.00	20.9	0	0.0		
<b>Bluescope Steel</b>												
Service Pit 1						0	0.00	20.9	0	0.0		
Electrical Pit 1						0	0.00	20.9	0	0.0		
Service Pit 2						0	0.00	20.9	0	0.0		
Electrical Pit 2						0	0.00	20.9	0	0.0		
Office						0	0.00	20.9	0	0.0		
Shower						0	0.00	20.9	0	0.0		
Toilet						0	0.00	20.9	0	0.0		
Stormwater Pit 1						0	0.00	20.9	0	0.0		
Stormwater Pit 2						0	0.00	20.9	0	0.0		
Stormwater Pit 3						0	0.00	20.9	0	0.0		
Stormwater Pit 4						0	0.00	20.9	0	0.0		
Stormwater Pit 5						0	0.00	20.9	0	0.0		
Stormwater Pit 6						0	0.00	20.9	0	0.0		
Stormwater Pit 7						0	0.00	20.9	0	0.0		
Stormwater Pit 8						0	0.00	20.9	0	0.0		
Stormwater Pit 9						0	0.00	20.9	0	0.0		
Stormwater Pit 10						0	0.00	20.9	0	0.0		
Pump Room						0	0.00	20.9	0	0.0		