



Pollutant Monitoring Results - Gas Accumulation Monitoring

EPL No:	4865
Entity Name	Enviroguard Pty Ltd
Site:	4 Quarry Road, Erskine Park NSW
Monitoring Frequency:	Quarterly
Link to NSW EPA Register:	Click Here

Disclaimer - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the requirements issued in writing by the Environment Protection Authority. To the best of Cleanaway's knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior consent from Cleanaway. For more details on publication of pollution monitoring data refer to the NSW EPA Website www.epa.nsw.gov.au

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence										Comments
6/02/2025	11/04/2024	20/03/2024	Inside all buildings or other enclosed structures within 250m of deposited waste.										
Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments	
Cleanaway													
Emergency Shower							0	0.00	20.9	0	0.0		
Male Toilet							0	0.00	20.9	0	0.0		
Female Toilet							0	0.00	20.9	0	0.0		
Handicap Toilet							0	0.00	20.9	0	0.0		
Office 7							0	0.00	20.9	0	0.0		
Server room							0	0.00	20.9	0	0.0		
Office 6							0	0.00	20.9	0	0.0		
Office 5							0	0.00	20.9	0	0.0		
Office 4							0	0.00	20.9	0	0.0		
Office 3							0	0.00	20.9	0	0.0		
Office 2							0	0.00	20.9	0	0.0		
Office 1							0	0.00	20.9	0	0.0		
Office 8							0	0.00	20.9	0	0.0		
Weighbridge							0	0.00	20.9	0	0.0		
Meal Room							0	0.00	20.9	0	0.0		
Conference Room							0	0.00	20.9	0	0.0		
Lobby							0	0.00	20.9	0	0.0		
Male Toilet 2							0	0.00	20.9	0	0.0		
Female Toilet 2							0	0.00	20.9	0	0.0		
Unisex Toilet							0	0.00	20.9	0	0.0		
Locker Room							0	0.00	20.9	0	0.0		
Stramit													
Stormwater Pit 1							10	0.00	20.9	0	0.0		
Stormwater Pit 2							0	0.00	20.9	0	0.0		
Stormwater Pit 3							0	0.00	20.9	0	0.0		
Stormwater Pit 4							5	0.00	20.9	0	0.0		
Stormwater Pit 5							15	0.00	20.9	0	0.0		
Stormwater Pit 6							0	0.00	20.9	0	0.0		
Site: Erskine Park						Date: 20/03/24	Start time: 1000			Finish time: 1600			
Monitoring personnel: JC						Monitoring equipment: RK Eagle II						Bump test: Yes	
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising						Weather and ground conditions: 20C, sunny, dry, some cloud	
Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments	
Stormwater Pit 7							0	0.00	20.9	0	0.0		
Weighbridge							0	0.00	20.9	0	0.0		
Men Toilet 1							0	0.00	20.9	0	0.0		
Lunch Room 1							0	0.00	20.9	0	0.0		
Men Toilet 2							0	0.00	20.9	0	0.0		
Lunch Room 2							0	0.00	20.9	0	0.0		
Stockland/Viscount Pooling													
Stormwater Pit 1							0	0.00	20.9	0	0.0		
Stormwater Pit 2							0	0.00	20.9	0	0.0		
Stormwater Pit 3							0	0.00	20.9	0	0.0		
Stormwater Pit 4							0	0.00	20.9	0	0.0		
Stormwater Pit 5							0	0.00	20.9	0	0.0		
Stormwater Pit 6							0	0.00	20.9	0	0.0		
Stormwater Pit 7							0	0.00	20.9	0	0.0		
Stormwater Pit 8							0	0.00	20.9	0	0.0		
Stormwater Pit 9							0	0.00	20.9	0	0.0		
Stormwater Pit 10							0	0.00	20.9	0	0.0		
Stormwater Pit 11							0	0.00	20.9	0	0.0		
Stormwater Pit 12							0	0.00	20.9	0	0.0		
Stormwater Pit 13							0	0.00	20.9	0	0.0		
Stormwater Pit 14							0	0.00	20.9	0	0.0		
Change Room							0	0.00	20.9	0	0.0		
Lunch Room							0	0.00	20.9	0	0.0		
Toilet							0	0.00	20.9	0	0.0		
Warehouse							0	0.00	20.9	0	0.0		
Dincol													
Stormwater Pit 1							0	0.00	20.9	0	0.0		
Stormwater Pit 2							0	0.00	20.9	0	0.0		
Stormwater Pit 3							0	0.00	20.9	0	0.0		
Site: Erskine Park						Date: 20/03/24	Start time: 1000			Finish time: 1600			
Monitoring personnel: JC						Monitoring equipment: RK Eagle II						Bump test: Yes	
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising						Weather and ground conditions: 20C, sunny, dry, some cloud	
Location ID	Max					Stable					Comments		

	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 4						5	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						20	0.00	20.9	0	0.0	
Dispatch Office						0	0.00	20.9	0	0.0	
Toilet 1						0	0.00	20.9	0	0.0	
Electrical Room						0	0.00	20.9	0	0.0	
Toilet 2						0	0.00	20.9	0	0.0	
Saputo											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						10	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Electrical Pit 1						0	0.00	20.9	0	0.0	
Electrical Pit 2						0	0.00	20.9	0	0.0	
Electrical Pit 3						0	0.00	20.9	0	0.0	
Electrical Pit 4						0	0.36	20.9	0	0.0	
Electrical Pit 5						0	0.12	20.9	0	0.0	
Electrical Pit 6						0	0.00	20.9	0	0.0	
Electrical Pit 7						0	0.00	20.9	0	0.0	
Electrical Pit 8						0	0.00	20.9	0	0.0	
LOSCAM											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 20/03/24		Start time: 1000		Finish time: 1600	
Monitoring personnel: JC			Monitoring equipment: RK Eagle II			Bump test: Yes					
Atmospheric pressure at start (mb): 1005				Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud					
Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Wash Bay						0	0.00	20.9	0	0.0	
Storage Shed						0	0.00	20.9	0	0.0	
Toilet 1 - Male						0	0.00	20.9	0	0.0	
Toilet 2 - Female						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Toilet 3						0	0.00	20.9	0	0.0	
Mainfreight											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Dispatch office						0	0.00	20.9	0	0.0	
Lunchroom						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Mulgaa Quarries											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 20/03/24		Start time: 1000		Finish time: 1600	
Monitoring personnel: JC			Monitoring equipment: RK Eagle II			Bump test: Yes					
Atmospheric pressure at start (mb): 1005				Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud					
Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15						0	0.00	20.9	0	0.0	
Wash Bay						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Kitchen						0	0.00	20.9	0	0.0	
Darley Aluminium											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	

Stormwater Pit 3						0	0.00	20.9	0	0.0		
Stormwater Pit 4						0	0.00	20.9	0	0.0		
Stormwater Pit 5						0	0.00	20.9	0	0.0		
Stormwater Pit 6						0	0.00	20.9	0	0.0		
Stormwater Pit 7						0	0.00	20.9	0	0.0		
Stormwater Pit 8						0	0.00	20.9	0	0.0		
Lunch Room						0	0.00	20.9	0	0.0		
Warehouse						0	0.00	20.9	0	0.0		
Office						0	0.00	20.9	0	0.0		
Toilet						0	0.00	20.9	0	0.0		
Toilet 2						0	0.00	20.9	0	0.0		
ORAFOL/EHI												
Stormwater Pit 1						0	0.00	20.9	0	0.0		
Stormwater Pit 2						0	0.00	20.9	0	0.0		
Stormwater Pit 3						0	0.00	20.9	0	0.0		
Stormwater Pit 4						0	0.00	20.9	0	0.0		
Stormwater Pit 5						0	0.00	20.9	0	0.0		
Stormwater Pit 6						0	0.00	20.9	0	0.0		
Electrical 1						0	0.00	20.9	0	0.0		
Stormwater Pit 7						0	0.00	20.9	0	0.0		
Star Enkine Park												
Monitoring personnel: JC						Date: 20/03/24		Start time: 1000		Finish time: 1600		
Atmospheric pressure at start (mb): 1005						Monitoring equipment: RK Eagle II		Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud		
Location ID	Max					Stable					Comments	
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)		CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		H2S
Stormwater Pit 8							0	0.00	20.9	0	0.0	
Electrical 2							0	0.00	20.9	0	0.0	
Stormwater Pit 9							0	0.00	20.9	0	0.0	
Stormwater Pit 10							0	0.00	20.9	0	0.0	
Stormwater Pit 11							0	0.00	20.9	0	0.0	
Stormwater Pit 12							0	0.00	20.9	0	0.0	
Stormwater Pit 13							0	0.00	20.9	0	0.0	
Stormwater Pit 14							0	0.00	20.9	0	0.0	
Stormwater Pit 15							0	0.00	20.9	0	0.0	
Stormwater Pit 16							0	0.00	20.9	0	0.0	
Bluescope Steel												
Service Pit 1							0	0.00	20.9	0	0.0	
Electrical Pit 1							0	0.00	20.9	0	0.0	
Service Pit 2							0	0.00	20.9	0	0.0	
Electrical Pit 2							0	0.00	20.9	0	0.0	
Office							0	0.00	20.9	0	0.0	
Shower							0	0.00	20.9	0	0.0	
Toilet							0	0.00	20.9	0	0.0	
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							0	0.00	20.9	0	0.0	
Stormwater Pit 8							0	0.00	20.9	0	0.0	
Stormwater Pit 9							0	0.00	20.9	0	0.0	
Stormwater Pit 10							0	0.00	20.9	0	0.0	
Pump Room							0	0.00	20.9	0	0.0	

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence
6/02/2025	9/07/2024	18/06/2024	Inside all buildings or other enclosed structures within 250m of deposited waste.

Location ID	Max					Stable					Comments	
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)		CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		H2S
Cleanaway												
Emergency Shower							10	0.02	20.9	0	0.0	
Male Toilet							10	0.04	20.9	0	0.0	
Female Toilet							10	0.04	20.9	0	0.0	
Handicap Toilet							5	0.02	20.9	0	0.0	
Office 7							0	0.04	20.9	0	0.0	
Server room							0	0.00	20.9	0	0.0	
Office 6							5	0.02	20.9	0	0.0	
Office 5							0	0.00	20.9	0	0.0	
Office 4							0	0.02	20.9	0	0.0	
Office 3							0	0.02	20.9	0	0.0	
Office 2							0	0.02	20.9	0	0.0	
Office 1							15	0.00	20.9	0	0.0	
Office 8							15	0.02	20.9	0	0.0	
Weighbridge							5	0.00	20.9	0	0.0	
Meal Room							15	0.00	20.9	0	0.0	
Conference Room							20	0.00	20.9	0	0.0	
Lobby							0	0.02	20.9	0	0.0	
Male Toilet 2							10	0.02	20.9	0	0.0	
Female Toilet 2							5	0.02	20.9	0	0.0	
Unisex Toilet							0	0.02	20.9	0	0.0	
Locker Room							10	0.02	20.9	0	0.0	
Stramit												
Stormwater Pit 1							30	0.00	20.9	0	0.0	
Stormwater Pit 2							40	0.00	20.9	0	0.0	
Stormwater Pit 3							55	0.00	20.9	0	0.0	

Stormwater Pit 4								0	0.00	20.9	0	0.0	
Stormwater Pit 5								45	0.00	20.9	0	0.0	
Stormwater Pit 6								25	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 18/06/24		Start time: 0800		Finish time: 1600			
Monitoring personnel: LS / MS						Monitoring equipment: RK Eagle II				Bump test: Yes			
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry, Wet ground			
Location ID													
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments	
Stormwater Pit 7							0	0.00	20.9	0	0.0		
Weighbridge							15	0.00	20.9	0	0.0		
Men Toilet 1							0	0.00	20.9	0	0.0		
Lunch Room 1							0	0.04	20.9	0	0.0		
Men Toilet 2							50	0.00	20.9	0	0.0		
Lunch Room 2							40	0.04	20.9	0	0.0		
Streckland/Viscount Pooling													
Stormwater Pit 1							0	0.00	20.9	0	0.0		
Stormwater Pit 2							0	0.00	20.9	0	0.0		
Stormwater Pit 3							0	0.00	20.9	0	0.0		
Stormwater Pit 4							0	0.00	20.9	0	0.0		
Stormwater Pit 5							0	0.00	20.9	0	0.0		
Stormwater Pit 6							0	0.00	20.9	0	0.0		
Stormwater Pit 7							10	0.00	20.9	0	0.0		
Stormwater Pit 8							15	0.00	20.9	0	0.0		
Stormwater Pit 9							10	0.00	20.9	0	0.0		
Stormwater Pit 10							0	0.00	20.9	0	0.0		
Stormwater Pit 11							0	0.00	20.9	0	0.0		
Stormwater Pit 12							0	0.00	20.9	0	0.0		
Stormwater Pit 13							0	0.00	20.9	0	0.0		
Stormwater Pit 14							0	0.00	20.9	0	0.0		
Change Room							0	0.00	20.9	0	0.0		
Lunch Room							15	0.00	20.9	0	0.0		
Toilet							55	0.00	20.9	0	0.0		
Warehouse							30	0.00	20.9	0	0.0		
Dincol													
Stormwater Pit 1							0	0.00	20.9	0	0.0		
Stormwater Pit 2							40	0.00	20.9	0	0.0		
Stormwater Pit 3							25	0.00	20.9	0	0.0		
Site: Erskine Park						Date: 18/06/24		Start time: 0800		Finish time: 1600			
Monitoring personnel: LS / MS						Monitoring equipment: RK Eagle II				Bump test: Yes			
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry, Wet ground			
Location ID													
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments	
Stormwater Pit 4							0	0.00	20.9	0	0.0		
Stormwater Pit 5							0	0.00	20.9	0	0.0		
Stormwater Pit 6							0	0.00	20.9	0	0.0		
Stormwater Pit 7							15	0.00	20.9	0	0.0		
Stormwater Pit 8							0	0.00	20.9	0	0.0		
Dispatch Office							10	0.00	20.9	0	0.0		
Toilet 1							65	0.00	20.9	0	0.0		
Electrical Room							15	0.00	20.9	0	0.0		
Toilet 2							0	0.00	20.9	0	0.0		
Saputo													
Stormwater Pit 1							0	0.00	20.9	0	0.0		
Stormwater Pit 2							30	0.00	20.9	0	0.0		
Stormwater Pit 3							15	0.00	20.9	0	0.0		
Stormwater Pit 4							0	0.00	20.9	0	0.0		
Stormwater Pit 5							0	0.00	20.9	0	0.0		
Stormwater Pit 6							40	0.00	20.9	0	0.0		
Electrical Pit 1							130	0.00	20.9	0	0.0		
Electrical Pit 2							40	0.00	20.9	0	0.0		
Electrical Pit 3							90	0.00	20.9	0	0.0		
Electrical Pit 4							30	0.00	20.9	0	0.0		
Electrical Pit 5							35	0.00	20.9	0	0.0		
Electrical Pit 6							50	0.00	20.9	0	0.0		
Electrical Pit 7							0	0.00	20.9	0	0.0		
Electrical Pit 8							0	0.00	20.9	0	0.0		
LOSCAM													
Stormwater Pit 1							0	0.00	20.9	0	0.0		
Stormwater Pit 2							30	0.00	20.9	0	0.0		
Stormwater Pit 3							15	0.00	20.9	0	0.0		
Stormwater Pit 4												No access	
Site: Erskine Park						Date: 18/06/24		Start time: 0800		Finish time: 1600			
Monitoring personnel: LS / MS						Monitoring equipment: RK Eagle II				Bump test: Yes			
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry, Wet ground			
Location ID													
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments	
Stormwater Pit 5							0	0.00	20.9	0	0.0		
Stormwater Pit 6							0	0.00	20.9	0	0.0		
Stormwater Pit 7							0	0.00	20.9	0	0.0		
Stormwater Pit 8							0	0.00	20.9	0	0.0		
Wash Bay							0	0.00	20.9	0	0.0		
Storage Shed							0	0.00	20.9	0	0.0		
Toilet 1 - Male							0	0.00	20.9	0	0.0		
Toilet 2 - Female							0	0.00	20.9	0	0.0		
Lunch Room							0	0.04	20.9	0	0.0		

Toilet 3									0	0.00	20.9	0	0.0	
Mainfreight														
Stormwater Pit 1														No access. Change in
Stormwater Pit 2														
Stormwater Pit 3														
Stormwater Pit 4														
Stormwater Pit 5														
Stormwater Pit 6														
Stormwater Pit 7														
Dispatch office														
Lunchroom														
Toilet														
Mulgoa Quarries														
Stormwater Pit 1									0	0.00	20.9	0	0.0	
Stormwater Pit 2									0	0.00	20.9	0	0.0	
Stormwater Pit 3									0	0.00	20.9	0	0.0	
Stormwater Pit 4									55	0.00	20.9	0	0.0	
Stormwater Pit 5									35	0.00	20.9	0	0.0	
Stormwater Pit 6									10	0.00	20.9	0	0.0	
Stormwater Pit 7									5	0.00	20.9	0	0.0	
Stormwater Pit 8									20	0.00	20.9	0	0.0	
Stormwater Pit 9									0	0.00	20.9	0	0.0	
Site: Erskine Park									Date: 18/06/24		Start time: 0800		Finish time: 1600	
Monitoring personnel: LS / MS						Monitoring equipment: RK Eagle II						Bump test: Yes		
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry. Wet ground					
Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments		
Stormwater Pit 10							0	0.00	20.9	0	0.0			
Stormwater Pit 11							5	0.00	20.9	0	0.0			
Stormwater Pit 12							0	0.00	20.9	0	0.0			
Stormwater Pit 13							0	0.00	20.9	0	0.0			
Stormwater Pit 14							10	0.00	20.9	0	0.0			
Stormwater Pit 15							0	0.00	20.9	0	0.0			
Wash Bay							0	0.00	20.9	0	0.0			
Toilet							0	0.00	20.9	0	0.0			
Lunch Room							0	0.00	20.9	0	0.0			
Kitchen							0	0.00	20.9	0	0.0			
Darley Aluminium														
Stormwater Pit 1							0	0.00	20.9	0	0.0			
Stormwater Pit 2							0	0.00	20.9	0	0.0			
Stormwater Pit 3							0	0.00	20.9	0	0.0			
Stormwater Pit 4							0	0.00	20.9	0	0.0			
Stormwater Pit 5							0	0.00	20.9	0	0.0			
Stormwater Pit 6							0	0.00	20.9	0	0.0			
Stormwater Pit 7							0	0.00	20.9	0	0.0			
Stormwater Pit 8												No access to test		
Lunch Room							0	0.00	20.9	0	0.0			
Warehouse							0	0.00	20.9	0	0.0			
Office							0	0.00	20.9	0	0.0			
Toilet							5	0.00	20.9	0	0.0			
Toilet 2							0	0.00	20.9	0	0.0			
ORAFOL/ENI														
Stormwater Pit 1							0	0.00	20.9	0	0.0			
Stormwater Pit 2							0	0.00	20.9	0	0.0			
Stormwater Pit 3							0	0.00	20.9	0	0.0			
Stormwater Pit 4							0	0.00	20.9	0	0.0			
Stormwater Pit 5							0	0.00	20.9	0	0.0			
Stormwater Pit 6							15	0.00	20.9	0	0.0			
Electrical 1							0	0.00	20.9	0	0.0			
Stormwater Pit 7							0	0.00	20.9	0	0.0			
Stormwater Pit 8							0	0.00	20.9	0	0.0			
Site: Erskine Park							Date: 18/06/24		Start time: 0800		Finish time: 1600			
Monitoring personnel: LS / MS						Monitoring equipment: RK Eagle II					Bump test: Yes			
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry. Wet ground					
Location ID	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	Max	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments		
Electrical 2							0	0.00	20.9	0	0.0			
Stormwater Pit 9							5	0.00	20.9	0	0.0			
Stormwater Pit 10							0	0.00	20.9	0	0.0			
Stormwater Pit 11							0	0.00	20.9	0	0.0			
Stormwater Pit 12							0	0.00	20.9	0	0.0			
Stormwater Pit 13							0	0.00	20.9	0	0.0			
Stormwater Pit 14							0	0.00	20.9	0	0.0			
Stormwater Pit 15							0	0.00	20.9	0	0.0			
Stormwater Pit 16							0	0.00	20.9	0	0.0			
Bluescope Steel														
Service Pit 1							0	0.00	20.9	0	0.0			
Electrical Pit 1							0	0.00	20.9	0	0.0			
Service Pit 2							0	0.00	20.9	0	0.0			
Electrical Pit 2							0	0.00	20.9	0	0.0			
Office							0	0.00	20.9	0	0.0			
Shower							0	0.00	20.9	0	0.0			

Toilet						0	0.00	20.9	0	0.0	
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						1	0.00	20.9	0	0.0	
Stormwater Pit 3						1	0.00	20.9	0	0.0	
Stormwater Pit 4						1	0.00	20.9	0	0.0	
Stormwater Pit 5						1	0.00	20.9	0	0.0	
Stormwater Pit 6						1	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Pump Room						0	0.00	20.9	0	0.0	

Date Monitoring Data Uploaded		Date Monitoring Data Obtained		Date Monitored		Sampled Point as per Licence									
6/02/2025		6/02/2025		23-25/09/2024		Inside all buildings or other enclosed structures within 250m of deposited waste,									
Location ID	Date	Time	Max				Stable					Comments			
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S					
Cleanaway															
Emergency shower	2024-09-25	9:18:00	-	-	-	0	0	21	0	0	-				
Male Toilet 1	2024-09-25	9:19:00	-	-	-	65	0	21	0	0	-				
Female Toilet 2	2024-09-25	9:26:00	-	-	-	60	0	21	0	0	-				
Handicapped Toilet	2024-09-25	9:20:00	-	-	-	55	0	21	0	0	-				
Office 7	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-				
Server room	2024-09-25	9:20:00	-	-	-	0	0	21	0	0	-				
Office 6	2024-09-25	9:20:00	-	-	-	0	0	21	0	0	-				
Office 5	-	-	-	-	-	-	-	-	-	-	-				
Office 4	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-				
Office 3	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-				
Office 2	2024-09-25	9:22:00	-	-	-	0	0	21	0	0	-				
Office 1	2024-09-25	9:24:00	-	-	-	0	0	21	0	0	-				
Office 8	2024-09-25	9:24:00	-	-	-	20	0	21	0	0	-				
Weighbridge	2024-09-25	9:24:00	-	-	-	30	0	21	0	0	-				
Lunch Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-				
Conference Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-				
Lobby	2024-09-25	9:22:00	-	-	-	0	0	21	0	0	-				
Male Toilet 2	2024-09-25	9:26:00	-	-	-	65	0	21	0	0	-				
Female Toilet 2	2024-09-25	9:26:00	-	-	-	60	0	21	0	0	-				
Handicapped Toilet 2	2024-09-25	9:26:00	-	-	-	30	0	21	0	0	-				
Locker Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-				
Strammit															
SW1	2024-09-24	12:32:15	-	-	-	0	0	21	0	0	-				
SW2	2024-09-24	12:33:58	-	-	-	0	0	21	0	0	-				
SW3	2024-09-24	12:35:43	-	-	-	0	0	21	0	0	-				
SW4	2024-09-24	12:38:00	-	-	-	35	0	21	0	0	-				
SW5	2024-09-24	12:39:40	-	-	-	55	0	21	0	0	-				
Site: Erakine Park															
Monitoring personnel: LS						Monitoring equipment: RK Eagle II					Bump test: Yes				
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising					Weather and ground conditions: 14C, cloudy, dry.				
Location ID	Date	Time	Max				Stable					Comments			
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S					
SW6	2024-09-24	12:42:31	-	-	-	0	0	21	0	0	-				
SW7	-	-	-	-	-	-	-	-	-	-	-				
WB	2024-09-24	13:51:49	-	-	-	5	0	21	0	0	-				
MT 1	2024-09-24	12:57:21	-	-	-	95	0	21	0	0	-				
LR 1	2024-09-24	12:55:09	-	-	-	85	0	21	0	0	-				
MT 2	2024-09-24	12:49:33	-	-	-	0	70	21	0	0	-				
LR 2	2024-09-24	12:46:50	-	-	-	20	0	21	0	0	-				
Stockland Viscount Pooling															
SW1	2024-09-24	13:29:26	-	-	-	0	0	21	0	0	-				
SW2	2024-09-24	13:30:40	-	-	-	0	0	21	0	0	-				
SW3	2024-09-24	13:32:03	-	-	-	35	0	21	0	0	-				
SW4	2024-09-24	13:33:05	-	-	-	0	0	21	0	0	-				
SW5	2024-09-24	13:34:58	-	-	-	0	0	21	0	0	-				
SW6	2024-09-24	13:36:21	-	-	-	35	0	21	0	0	-				
SW7	2024-09-24	13:39:01	-	-	-	0	0	21	0	0	-				
SW8	2024-09-24	13:39:51	-	-	-	5	0	21	0	0	-				
SW9	2024-09-24	13:43:33	-	-	-	20	0	21	0	0	-				
SW10	2024-09-24	13:45:20	-	-	-	15	0	21	0	0	-				
Change Room	-	-	-	-	-	-	-	-	-	-	-				
Lunchroom	2024-09-24	13:56:51	-	-	-	0	0	21	0	0	-				
Male Toilet	2024-09-24	13:57:52	-	-	-	120	0	21	0	0	-				
Warehouse	2024-09-24	13:42:44	-	-	-	25	0	21	0	0	-				
Dintel															
SW1	2024-09-24	14:16:34	-	-	-	0	0	21	0	0	-				
SW2	2024-09-24	14:17:41	-	-	-	0	0	21	0	0	-				
SW3	2024-09-24	14:19:17	-	-	-	0	0	21	0	0	-				
SW4	2024-09-24	14:25:48	-	-	-	0	0	21	0	0	-				
SW5	2024-09-24	13:47:02	-	-	-	20	0	21	0	0	-				
Site: Erakine Park															
Monitoring personnel: LS						Monitoring equipment: RK Eagle II					Bump test: Yes				
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising					Weather and ground conditions: 14C, cloudy, dry.				
Location ID	Date	Time	Max				Stable					Comments			
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S					
SW6	2024-09-24	13:49:42	-	-	-	15	0	21	0	0	-				

SW7	2024-09-24	13:52:23	-	-	-	-	0	0	21	0	0	-
SW8	2024-09-24	14:27:43	-	-	-	-	0	0	0	0	0	-
Dispatch	2024-09-24	14:22:49	-	-	-	-	30	0	21	0	0	-
Toilet 1	2024-09-24	14:23:28	-	-	-	-	60	0	21	0	0	-
Elec Room	2024-09-24	14:10:36	-	-	-	-	20	0	21	0	0	-
Toilet 2	2024-09-24	15:17:56	-	-	-	-	55	0	21	0	0	-
Sepulco												
SW1	2024-09-24	7:34:36	-	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	7:31:59	-	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	7:47:00	-	-	-	-	15	0	21	0	0	-
SW4	2024-09-24	7:48:42	-	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	7:51:55	-	-	-	-	250	0	21	0	0	-
SW6	2024-09-24	7:59:12	-	-	-	-	35	0	21	0	0	-
E1	2024-09-24	7:36:39	-	-	-	-	15	0	21	0	0	-
E2	2024-09-24	7:37:58	-	-	-	-	5	0	21	0	0	-
E3	2024-09-24	7:39:47	-	-	-	-	35	0	21	0	0	-
E4	2024-09-24	7:41:50	-	-	-	-	0	0	21	0	0	-
E5	2024-09-24	7:53:57	-	-	-	-	85	0	21	0	0	-
E6	2024-09-24	7:55:48	-	-	-	-	40	0	21	0	0	-
LOSCAM												
SW1	2024-09-24	10:35:58	-	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	10:36:34	-	-	-	-	0	0	21	0	0	-
SW3	-	-	-	-	-	-	-	-	-	-	-	-
SW4	2024-09-24	10:23:28	-	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	10:27:03	-	-	-	-	0	0	21	0	0	-
SW6	2024-09-24	10:29:45	-	-	-	-	0	0	0	0	0	-
SW7	2024-09-24	10:31:22	-	-	-	-	0	0	21	0	0	-
Site: Erskine Park												
Monitoring personnel: L5						Monitoring equipment: RK Eagle II				Bump test: Yes		
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry.		
Location ID	Date	Time	Max			Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
SW8	-	-	-	-	-	-	-	-	-	-	-	-
Wash Bay	2024-09-24	10:21:35	-	-	-	-	60	0	21	0	0	-
Male Toilet	2024-09-24	10:39:39	-	-	-	-	10	0	21	0	0	-
Warehouse Ambient	2024-09-24	10:22:40	-	-	-	-	0	0	21	0	0	-
Mainfreight												
SW1	-	-	-	-	-	-	-	-	-	-	-	No Access
SW2	-	-	-	-	-	-	-	-	-	-	-	No Access
SW3	-	-	-	-	-	-	-	-	-	-	-	No Access
SW4	-	-	-	-	-	-	-	-	-	-	-	No Access
SW5	-	-	-	-	-	-	-	-	-	-	-	No Access
SW6	-	-	-	-	-	-	-	-	-	-	-	No Access
SW7	-	-	-	-	-	-	-	-	-	-	-	No Access
Dispatch office	-	-	-	-	-	-	-	-	-	-	-	No Access
Lunchroom	-	-	-	-	-	-	-	-	-	-	-	No Access
Toilet	-	-	-	-	-	-	-	-	-	-	-	No Access
Mulgoa Quarries												
SW1	2024-09-24	9:16:00	-	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	9:17:10	-	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	9:18:33	-	-	-	-	0	0	21	0	0	-
SW4	2024-09-24	9:19:30	-	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	9:20:19	-	-	-	-	0	0	21	0	0	-
SW6	2024-09-24	9:21:30	-	-	-	-	0	0	21	0	0	-
SW7	2024-09-24	9:22:30	-	-	-	-	0	0	21	0	0	-
SW8	2024-09-24	9:23:33	-	-	-	-	0	0	21	0	0	-
SW9	2024-09-24	9:24:47	-	-	-	-	0	0	21	0	0	-
SW10	2024-09-24	9:25:28	-	-	-	-	0	0	21	0	0	-
SW11	2024-09-24	9:26:35	-	-	-	-	0	0	21	0	0	-
SW12	2024-09-24	9:28:05	-	-	-	-	0	0	21	0	0	-
SW13	2024-09-24	9:29:04	-	-	-	-	0	0	21	0	0	-
SW14	2024-09-24	9:30:28	-	-	-	-	25	0	21	0	0	-
Site: Erskine Park												
Monitoring personnel: L5						Monitoring equipment: RK Eagle II				Bump test: Yes		
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry.		
Location ID	Date	Time	Max			Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
SW15	2024-09-24	9:31:34	-	-	-	-	15	0	21	0	0	-
Wash Bay	2024-09-24	9:40:22	-	-	-	-	45	0	21	0	0	-
Male Toilet	2024-09-24	9:38:44	-	-	-	-	55	0	21	0	0	-
Lunch Room	2024-09-24	9:35:13	-	-	-	-	0	0	21	0	0	-
Darley Aluminium												
SW1	2024-09-23	8:35:36	-	-	-	-	5	0	21	0	0	-
SW2	2024-09-23	8:36:51	-	-	-	-	0	0	21	0	0	-
SW3	2024-09-23	8:38:02	-	-	-	-	10	0	21	0	0	-
SW4	2024-09-23	8:39:10	-	-	-	-	0	0	0	0	0	-
SW5	2024-09-23	8:43:55	-	-	-	-	0	0	21	0	0	-
SW6	2024-09-23	8:45:39	-	-	-	-	0	0	21	0	0	-
SW7	2024-09-23	8:46:32	-	-	-	-	0	0	21	0	0	-
SW8	2024-09-23	8:47:32	-	-	-	-	0	0	21	0	0	-
Lunch Room	2024-09-23	8:49:07	-	-	-	-	15	0	21	0	0	-
Male Toilet	2024-09-23	8:52:34	-	-	-	-	55	0	21	0	0	-
ORAFOL/EHI												

SW1	2024-09-23	8:10:41	-	-	-	35	0	21	0	0	-
SW2	2024-09-23	8:09:41	-	-	-	40	0	21	0	0	-
SW3	2024-09-23	8:08:29	-	-	-	0	0	21	0	0	-
SW4	2024-09-23	8:06:42	-	-	-	0	0	21	0	0	-
SW5	2024-09-23	8:04:36	-	-	-	85	0	21	0	0	-
SW6	2024-09-23	8:02:32	-	-	-	60	0	21	0	0	-
SW7	2024-09-23	8:01:33	-	-	-	0	0	21	0	0	-
SW8	2024-09-23	8:00:13	-	-	-	5	0	21	0	0	-
SW9	2024-09-23	7:51:26	-	-	-	20	0	21	0	0	-
SW10	2024-09-23	7:50:29	-	-	-	0	0	21	0	0	-
SW11	2024-09-23	7:49:41	-	-	-	5	0	21	0	0	-
SW12	2024-09-23	7:47:36	-	-	-	0	0	21	0	0	-
SW13	2024-09-23	7:46:22	-	-	-	35	0	21	0	0	-
SW14	2024-09-23	7:45:18	-	-	-	15	0	21	0	0	-
SW15	2024-09-23	7:44:30	-	-	-	0	0	21	0	0	-
SW16	2024-09-23	7:53:17	-	-	-	0	0	21	0	0	-

Site: Erskine Park											Monitoring equipment: RK Eagle II		Bump test: Yes	
Monitoring personnel: LS											Rising or falling: Rising		Weather and ground conditions: 14C, cloudy, dry.	
Atmospheric pressure at start (mb): 1005														
Location ID	Date	Time	CH4 PPM	Max	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments		
SW17	2024-09-23	7:57:01	-		-	-	0	0	21	0	0	-		
Bluescope Steel														
	2024-09-23	7:20:28	-	-	-	-	80	0	21	0	0	-		
Service Pit 1	2024-09-23	7:13:37	-	-	-	-	60	0	21	0	0	-		
Electrical Pit 1	2024-09-23	7:11:12	-	-	-	-	0	0	21	0	0	-		
Indoor cart celler	2024-09-23	7:18:19	-	-	-	-	0	0	21	0	0	-		
Office	2024-09-23	7:09:01	-	-	-	-	0	0	21	0	0	-		
Shower	2024-09-23	7:08:28	-	-	-	-	0	0	21	0	0	-		
Toilet	2024-09-23	7:03:30	-	-	-	-	0	0	21	0	0	-		
SW Pit	2024-09-23	6:44:57	-	-	-	-	10	0	21	0	0	-		
SW pit adjacent service road 1	2024-09-23	6:46:25	-	-	-	-	35	0	21	0	0	-		
SW pit adjacent service road 2	2024-09-23	6:47:42	-	-	-	-	30	0	21	0	0	-		
SW pit adjacent service road 3	2024-09-23	6:48:57	-	-	-	-	10	0	21	10	0	-		
SW pit adjacent service road 4	2024-09-23	6:50:40	-	-	-	-	60	0	21	0	0	-		
SW Pit 5	2024-09-23	6:52:51	-	-	-	-	30	0	21	0	0	-		
SW Pit 6	2024-09-23	6:54:33	-	-	-	-	35	0	21	0	0	-		
SW Pit 7	2024-09-23	6:55:49	-	-	-	-	0	0	21	0	0	-		
SW Pit 8	2024-09-23	8:55:18	-	-	-	-	0	0	21	0	0	-		
SW Pit 9	2024-09-23	7:03:30	-	-	-	-	0	0	21	0	0	-		
SW Pit														

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence									
6/02/2025	6/02/2025	16-19/12/2024	Inside all buildings or other enclosed structures within 250m of deposited waste.									
Location ID	Date	Time	CH4 PPM	Max	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments
Cleanaway												
Emergency Shower	2024-12-16	6:18:48 AM	-	-	-	-	0	0	21	0	0	-
Male Toilet 1	2024-12-16	6:18:37 AM	-	-	-	-	0	0	21	0	0	-
Female Toilet 2	2024-12-16	6:20:50 AM	-	-	-	-	0	0	21	0	0	-
Handicapped Toilet	2024-12-16	6:18:15 AM	-	-	-	-	0	0	21	0	0	-
Office 7	2024-12-16	6:17:31 AM	-	-	-	-	0	0	21	0	0	-
Server room	2024-12-16	6:18:01 AM	-	-	-	-	0	0	21	0	0	-
Office 6	2024-12-16	6:17:43 AM	-	-	-	-	0	0	21	0	0	-
Office 5	-	-	-	-	-	-	-	-	-	-	-	-
Office 4	2024-12-16	6:17:19 AM	-	-	-	-	0	0	21	0	0	-
Office 3	-	-	-	-	-	-	-	-	-	-	-	-
Office 2	2024-12-16	6:16:56 AM	-	-	-	-	0	0	21	0	0	-
Office 1	2024-12-16	6:19:45 AM	-	-	-	-	0	0	21	0	0	-
Office 8	2024-12-16	6:19:22 AM	-	-	-	-	0	0	21	0	0	-
Weighbridge	2024-12-16	6:19:34 AM	-	-	-	-	0	0	21	0	0	-
Lunch Room	2024-12-16	6:20:08 AM	-	-	-	-	0	0	21	0	0	-
Conference Room	2024-12-16	6:19:57 AM	-	-	-	-	0	0	21	0	0	-
Lobby	2024-12-16	6:16:27 AM	-	-	-	-	0	0	21	0	0	-
Male Toilet 2	2024-12-16	6:20:19 AM	-	-	-	-	0	0	21	0	0	-
Female Toilet 2	2024-12-16	6:20:50 AM	-	-	-	-	0	0	21	0	0	-
Handicapped Toilet 2	2024-12-16	6:20:29 AM	-	-	-	-	0	0	21	0	0	-
Locker Room	2024-12-16	6:11:41 AM	-	-	-	-	45	0	21	0	0	-
Stramit												
SW1	2024-12-16	8:09:56 AM	-	-	-	-	0	0	21	0	0	-
SW2	2024-12-16	8:10:25 AM	-	-	-	-	0	0	21	0	0	-
SW3	2024-12-16	8:10:41 AM	-	-	-	-	0	0	21	0	0	-
SW4	2024-12-16	8:10:54 AM	-	-	-	-	0	0	21	0	0	-

Site: Erskine Park												Monitoring equipment: RK Eagle II			Bump test: Yes	
Monitoring personnel: JB												Rising or falling: Falling			Weather and ground conditions: 17C, clear, dry.	
Atmospheric pressure at start (mb): 1015																
Location ID	Date	Time	CH4 PPM	Max			CO2 (% v/v)	Min O2 (% v/v)	Stable			CO	H2S	Comments		
SW5	2024-12-16	8:11:05 AM	-	-	-	-	-	0	0	21	0	0	-			
SW6	2024-12-16	8:11:17 AM	-	-	-	-	-	0	0	21	0	0	-			
SW7			-	-	-	-	-	-	-	-	-	-	-			
	2024-12-16	8:09:46 AM	-	-	-	-	-	0	0	21	0	0	-			
MT 1	2024-12-16	8:08:42 AM	-	-	-	-	-	120	0	21	0	0	-			
LR 1	2024-12-16	8:09:33 AM	-	-	-	-	-	0	0	21	0	0	-			
MT 2	2024-12-16	8:08:07 AM	-	-	-	-	-	55	0	21	0	0	-			
LR 2	2024-12-16	8:09:21 AM	-	-	-	-	-	0	0	21	0	0	-			

Stockland Viscount Pooling																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
----------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

SW9	2024-12-16	8:49:09 AM	-	-	-	0	0	21	0	0	-		
SW10	2024-12-16	8:48:59 AM	-	-	-	0	0	21	0	0	-		
Site: Erskine Park													
Monitoring personnel: JB						Monitoring equipment: RK Eagle II				Bump test: Yes			
Atmospheric pressure at start (mb): 1015						Rising or falling: Falling				Weather and ground conditions: 17C, clear, dry.			
Location ID				Max									
	Date	Time	CH4 PPM		CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments	
SW11	2024-12-16	8:48:48 AM	-		-	-	0	0	21	0	0	-	
SW12	2024-12-16	8:40:35 AM	-		-	-	10	0	21	0	0	-	
SW13	2024-12-16	8:49:29 AM	-		-	-	0	0	21	0	0	-	
SW14	2024-12-16	8:49:41 AM	-		-	-	0	0	21	0	0	-	
SW15	2024-12-16	8:49:51 AM	-		-	-	0	0	21	0	0	-	
Wash Bay	2024-12-16	8:50:01 AM	-		-	-	0	0	21	0	0	-	
Male Toilet	2024-12-16	8:47:15 AM	-		-	-	0	0	21	0	0	-	
Lunch Room	2024-12-16	8:46:52 AM	-		-	-	0	0	21	0	0	-	
Darley Aluminium													
SW1	2024-12-17	9:18:04 AM	-		-	-	0	0	21	0	0	-	
SW2	2024-12-17	9:20:04 AM	-		-	-	0	0	21	0	0	-	
SW3	2024-12-17	9:20:15 AM	-		-	-	0	0	21	0	0	-	
SW4	2024-12-17	9:20:26 AM	-		-	-	0	0	21	0	0	-	
SW5	2024-12-17	9:20:37 AM	-		-	-	0	0	21	0	0	-	
SW6	2024-12-17	9:20:54 AM	-		-	-	0	0	21	0	0	-	
SW7	2024-12-17	9:21:04 AM	-		-	-	0	0	21	0	0	-	
SW8	2024-12-17	9:17:00 AM	-		-	-	0	0	21	0	0	-	
Lunch Room	2024-12-17	9:17:42 AM	-		-	-	0	0	21	0	0	-	
Male Toilet	2024-12-17	9:17:17 AM	-		-	-	0	0	21	0	0	-	
ORAFOL/EHI													
SW1	2024-12-17	9:52:22 AM	-		-	-	0	0	21	0	0	-	
SW2	2024-12-17	9:52:12 AM	-		-	-	0	0	21	0	0	-	
SW3	2024-12-17	9:52:01 AM	-		-	-	0	0	21	0	0	-	
SW4	2024-12-17	9:51:51 AM	-		-	-	0	0	21	0	0	-	
SW5	2024-12-17	9:51:41 AM	-		-	-	0	0	21	0	0	-	
SW6	2024-12-17	9:51:31 AM	-		-	-	0	0	21	0	0	-	
SW7	2024-12-17	9:51:21 AM	-		-	-	0	0	21	0	0	-	
SW8	2024-12-17	9:51:11 AM	-		-	-	0	0	21	0	0	-	
SW9	2024-12-17	9:42:30 AM	-		-	-	35	0	21	0	0	-	
SW10	2024-12-17	9:50:39 AM	-		-	-	0	0	21	0	0	-	
SW11	2024-12-17	9:50:20 AM	-		-	-	0	0	21	0	0	-	
Site: Erskine Park													
Monitoring personnel: JB						Monitoring equipment: RK Eagle II				Bump test: Yes			
Atmospheric pressure at start (mb): 1015						Rising or falling: Falling				Weather and ground conditions: 17C, clear, dry.			
Location ID				Max									
	Date	Time	CH4 PPM		CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	Comments	
SW12	2024-12-17	9:50:10 AM	-		-	-	0	0	21	0	0	-	
SW13	2024-12-17	9:49:48 AM	-		-	-	0	0	21	0	0	-	
SW14	2024-12-17	9:49:39 AM	-		-	-	0	0	21	0	0	-	
SW15	2024-12-17	9:49:26 AM	-		-	-	0	0	21	0	0	-	
SW16	2024-12-17	9:49:59 AM	-		-	-	0	0	21	0	0	-	
SW17	2024-12-17	9:51:00 AM	-		-	-	0	0	21	0	0	-	
Bluescope Steel													
Service Pit 1	2024-12-19	9:36:01 AM	-		-	-	0	0	21	0	0	-	
Electrical Pit 1	2024-12-19	9:34:32 AM	-		-	-	0	0	21	0	0	-	
Indoor cart celler	2024-12-19	9:34:42 AM	-		-	-	0	0	21	0	0	-	
Office	2024-12-19	9:35:50 AM	-		-	-	0	0	21	0	0	-	
Shower	2024-12-19	9:35:37 AM	-		-	-	0	0	21	0	0	-	
Toilet	2024-12-19	9:35:28 AM	-		-	-	0	0	21	0	0	-	
SW Pit	2024-12-19	9:37:44 AM	-		-	-	0	0	21	0	0	-	
SW pit adjacent service road 1	2024-12-19	9:01:37 AM	-		-	-	5	0	21	0	0	-	
SW pit adjacent service road 2	-	-	-		-	-	-	-	-	-	-	-	
SW pit adjacent service road 3	2024-12-19	9:02:47 AM	-		-	-	15	0	21	0	0	-	
SW pit adjacent service road 4	2024-12-19	9:36:48 AM	-		-	-	0	0	21	0	0	-	
SW Pit 5	2024-12-19	9:36:37 AM	-		-	-	0	0	21	0	0	-	
SW Pit 6	2024-12-19	9:36:26 AM	-		-	-	0	0	21	0	0	-	
SW Pit 7	2024-12-19	9:36:11 AM	-		-	-	0	0	21	0	0	-	
SW Pit 8	2024-12-19	9:07:37 AM	-		-	-	10	0	21	0	0	-	
SW Pit 9	-	-	-		-	-	-	-	-	-	-	-	
SW Pit	2024-12-19	9:37:44 AM	-		-	-	0	0	21	0	0	-	
Date Monitoring Data Uploaded				Date Monitoring Data Obtained		Date Monitored		Sampled Point as per Licence					
7/05/2025				1/05/2025		27/03/2025		Inside all buildings or other enclosed structures within 250m of deposited waste.					
Location ID	Date	Time	Max					Stable				Comments	
			CH4 PPM		CO2 (% v/v)		Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Cleanaway													
Emergency shower	2025-03-26	7:13:42 AM	-	-	-	-	10	0	20.9	0	0	0	
Male Toilet 1	2025-03-26	7:14:03 AM	-	-	-	-	0	0	20.9	0	0	0	
Female Toilet 2	2025-03-26	7:19:10 AM	-	-	-	-	0	0	20.9	0	0	0	
Handicapped Toilet	2025-03-26	7:11:58 AM	-	-	-	-	0	0	20.9	0	0	0	
Office 7	2025-03-26	7:11:00 AM	-	-	-	-	0	0	20.9	0	0	0	
Server room	2025-03-26	7:12:44 AM	-	-	-	-	5	0	20.9	0	0	0	
Office 6	2025-03-26	7:11:11 AM	-	-	-	-	0	0	20.9	0	0	0	
Office 5	-	-	-	-	-	-	-	-	-	-	-	-	No Access
Office 4	2025-03-26	7:10:05 AM	-	-	-	-	0	0	20.9	0	0	0	

SW7	-	-	-	-	-	-	-	-	-	-	-	No Access
Dispatch office	-	-	-	-	-	-	-	-	-	-	-	No Access
Lunchroom	-	-	-	-	-	-	-	-	-	-	-	No Access
Toilet	-	-	-	-	-	-	-	-	-	-	-	No Access
Mulgoa Quarries												
SW1	2025-03-27	9:13:51 AM	-	-	-	0	0	20.9	0	0	-	
SW2	2025-03-27	9:14:22 AM	-	-	-	0	0	20.9	0	0	-	
SW3	2025-03-27	10:02:31 AM	-	-	-	0	0	20.9	0	0	-	
SW4	2025-03-27	10:02:21 AM	-	-	-	0	0	20.9	0	0	-	
SW5	2025-03-27	10:02:10 AM	-	-	-	0	0	20.9	0	0	-	
SW6	2025-03-27	10:02:01 AM	-	-	-	0	0	20.9	0	0	-	
SW7	2025-03-27	10:01:51 AM	-	-	-	0	0	20.9	0	0	-	
SW8	2025-03-27	9:16:41 AM	-	-	-	15	0	20.9	0	0	-	
SW9	2025-03-27	9:17:38 AM	-	-	-	0	0	20.9	0	0	-	
SW10	2025-03-27	9:17:50 AM	-	-	-	0	0	20.9	0	0	-	
SW11	2025-03-27	9:18:05 AM	-	-	-	0	0	20.9	0	0	-	
SW12	2025-03-27	9:18:31 AM	-	-	-	0	0	20.9	0	0	-	
SW13	2025-03-27	9:18:57 AM	-	-	-	0	0	20.9	0	0	-	
SW14	2025-03-27	9:19:43 AM	-	-	-	0	0	20.9	0	0	-	
SW15	2025-03-27	9:20:02 AM	-	-	-	0	0	20.9	0	0	-	
Wash Bay	2025-03-27	9:20:19 AM	-	-	-	0	0	20.9	0	0	-	
Male Toilet	2025-03-27	9:21:01 AM	-	-	-	0	0	20.9	0	0	-	
Lunch Room	2025-03-27	9:20:46 AM	-	-	-	0	0	20.9	0	0	-	
Darley Aluminium												
SW1	2025-03-27	7:19:04 AM	-	-	-	0	0	20.9	0	0	-	
SW2	2025-03-27	7:19:30 AM	-	-	-	0	0	20.9	0	0	-	
SW3	2025-03-27	7:19:40 AM	-	-	-	0	0	20.9	0	0	-	
SW4	2025-03-27	7:19:53 AM	-	-	-	0	0	20.9	0	0	-	
SW5	2025-03-27	7:20:15 AM	-	-	-	0	0	20.9	0	0	-	
SW6	2025-03-27	7:20:26 AM	-	-	-	0	0	20.9	0	0	-	
SW7	2025-03-27	7:20:36 AM	-	-	-	0	0	20.9	0	0	-	
SW8	2025-03-27	7:20:05 AM	-	-	-	0	0	20.9	0	0	-	
Lunch Room	2025-03-27	7:20:47 AM	-	-	-	0	0	20.9	0	0	-	
Male Toilet	2025-03-27	7:20:56 AM	-	-	-	0	0	20.9	0	0	-	
ORAFOL/EHI												
SW1	2025-03-27	7:40:11 AM	-	-	-	0	0	20.9	0	0	-	
SW2	2025-03-27	7:40:43 AM	-	-	-	0	0	20.9	0	0	-	
SW3	2025-03-27	7:41:15 AM	-	-	-	0	0	20.9	0	0	-	
SW4	2025-03-27	7:41:47 AM	-	-	-	0	0	20.9	0	0	-	
SW5	2025-03-27	7:42:11 AM	-	-	-	0	0	20.9	0	0	-	
SW6	2025-03-27	7:42:33 AM	-	-	-	0	0	20.9	0	0	-	
SW7	2025-03-27	7:42:56 AM	-	-	-	0	0	20.9	0	0	-	
SW8	2025-03-27	7:43:11 AM	-	-	-	0	0	20.9	0	0	-	
SW9	2025-03-27	7:45:13 AM	-	-	-	0	0	20.9	0	0	-	
SW10	2025-03-27	7:47:35 AM	-	-	-	0	0	20.9	0	0	-	
SW11	2025-03-27	7:45:31 AM	-	-	-	0	0	20.9	0	0	-	
SW12	2025-03-27	7:45:45 AM	-	-	-	0	0	20.9	0	0	-	
SW13	2025-03-27	7:46:13 AM	-	-	-	0	0	20.9	0	0	-	
SW14	2025-03-27	7:46:30 AM	-	-	-	0	0	20.9	0	0	-	
SW15	2025-03-27	7:46:42 AM	-	-	-	0	0	20.9	0	0	-	
SW16	2025-03-27	7:45:56 AM	-	-	-	0	0	20.9	0	0	-	
SW17	2025-03-27	7:43:29 AM	-	-	-	0	0	20.9	0	0	-	
Bluescope Steel												
Service Pit 1	2025-03-28	12:22:50 PM	-	-	-	0	0	20.9	0	0	-	
Electrical Pit 1	2025-03-28	12:01:23 PM	-	-	-	20	0	20.9	0	0	-	
Indoor cart celler	2025-03-28	12:23:04 PM	-	-	-	0	0	20.9	0	0	-	
Office	2025-03-28	12:09:46 PM	-	-	-	0	0	20.9	0	0	-	
Shower	2025-03-28	12:23:30 PM	-	-	-	0	0	20.9	0	0	-	
Toilet	2025-03-28	12:23:17 PM	-	-	-	0	0	20.9	0	0	-	
SW Pit	2025-03-28	12:23:51 PM	-	-	-	0	0	20.9	0	0	-	
SW pit adjacent service road 1	2025-03-28	12:21:04 PM	-	-	-	0	0	20.9	0	0	-	
SW pit adjacent service road 2	2025-03-28	12:20:53 PM	-	-	-	0	0	20.9	0	0	-	
SW pit adjacent service road 3	2025-03-28	12:21:17 PM	-	-	-	0	0	20.9	0	0	-	
SW pit adjacent service road 4	2025-03-28	12:08:29 PM	-	-	-	0	0	20.9	0	0	-	
SW Pit 5	2025-03-28	12:08:50 PM	-	-	-	0	0	20.9	0	0	-	
SW Pit 6	2025-03-28	12:08:50 PM	-	-	-	0	0	20.9	0	0	-	
SW Pit 7	2025-03-28	12:09:02 PM	-	-	-	0	0	20.9	0	0	-	
SW Pit 8	2025-03-28	12:02:17 PM	-	-	-	15	0	20.9	0	0	-	
SW Pit 9	2025-03-28	12:07:39 PM	-	-	-	0	0	20.9	0	0	-	
SW Pit	2025-03-28	12:23:51 PM	-	-	-	0	0	20.9	0	0	-	