



Pollutant Monitoring Results - Gas Accumulation Monitoring

EPL No:	4865
Entity Name	Enviroguard Pty Ltd
Site:	4 Quarry Road,
Monitoring Frequency:	Quarterly
Link to NSW EPA Register:	Click Here

Disclaimer - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the requirements issued in writing by the Environment Protection Authority. To the best of Cleanaway's knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior consent from Cleanaway. For more details on publication of pollution monitoring data refer to the NSW EPA Website www.epa.nsw.gov.au

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence								
6/02/2025	11/04/2024	20/03/2024	Inside all buildings or other enclosed structures within 250m of deposited waste,								
Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Cleanaway											
Emergency Shower						0	0.00	20.9	0	0.0	
Male Toilet						0	0.00	20.9	0	0.0	
Female Toilet						0	0.00	20.9	0	0.0	
Handicap Toilet						0	0.00	20.9	0	0.0	
Office 7						0	0.00	20.9	0	0.0	
Server room						0	0.00	20.9	0	0.0	
Office 6						0	0.00	20.9	0	0.0	
Office 5						0	0.00	20.9	0	0.0	
Office 4						0	0.00	20.9	0	0.0	
Office 3						0	0.00	20.9	0	0.0	
Office 2						0	0.00	20.9	0	0.0	
Office 1						0	0.00	20.9	0	0.0	
Office 8						0	0.00	20.9	0	0.0	
Weighbridge						0	0.00	20.9	0	0.0	
Meal Room						0	0.00	20.9	0	0.0	
Conference Room						0	0.00	20.9	0	0.0	
Lobby						0	0.00	20.9	0	0.0	
Male Toilet 2						0	0.00	20.9	0	0.0	
Female Toilet 2						0	0.00	20.9	0	0.0	
Unisex Toilet						0	0.00	20.9	0	0.0	
Locker Room						0	0.00	20.9	0	0.0	
Stramit											
Stormwater Pit 1						10	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						5	0.00	20.9	0	0.0	
Stormwater Pit 5						15	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Site: Erskine Park					Date: 20/03/24	Start time: 1000			Finish time: 1600		
Monitoring personnel: JC		Monitoring equipment: RK Eagle II			Bump test: Yes						
Atmospheric pressure at start (mb): 1005					Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud				
Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Weighbridge						0	0.00	20.9	0	0.0	
Men Toilet 1						0	0.00	20.9	0	0.0	
Lunch Room 1						0	0.00	20.9	0	0.0	
Men Toilet 2						0	0.00	20.9	0	0.0	
Lunch Room 2						0	0.00	20.9	0	0.0	
Stockland/Viscount Pooling											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Change Room						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	

Toilet						0	0.00	20.9	0	0.0		
Warehouse						0	0.00	20.9	0	0.0		
Dincol												
Stormwater Pit 1						0	0.00	20.9	0	0.0		
Stormwater Pit 2						0	0.00	20.9	0	0.0		
Stormwater Pit 3						0	0.00	20.9	0	0.0		
Site: Erskine Park						Date: 20/03/24		Start time: 1000		Finish time: 1600		
Monitoring personnel: JC			Monitoring equipment: RK Eagle II						Bump test: Yes			
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud				
Location ID			Max				Stable				Comments	
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)		CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		H2S
Stormwater Pit 4							5	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							0	0.00	20.9	0	0.0	
Stormwater Pit 8							20	0.00	20.9	0	0.0	
Dispatch Office							0	0.00	20.9	0	0.0	
Toilet 1							0	0.00	20.9	0	0.0	
Electrical Room							0	0.00	20.9	0	0.0	
Toilet 2							0	0.00	20.9	0	0.0	
Saputo												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							10	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Electrical Pit 1							0	0.00	20.9	0	0.0	
Electrical Pit 2							0	0.00	20.9	0	0.0	
Electrical Pit 3							0	0.00	20.9	0	0.0	
Electrical Pit 4							0	0.36	20.9	0	0.0	
Electrical Pit 5							0	0.12	20.9	0	0.0	
Electrical Pit 6							0	0.00	20.9	0	0.0	
Electrical Pit 7							0	0.00	20.9	0	0.0	
Electrical Pit 8							0	0.00	20.9	0	0.0	
LOSCAM												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Site: Erskine Park							Date: 20/03/24		Start time: 1000		Finish time: 1600	
Monitoring personnel: JC			Monitoring equipment: RK Eagle II						Bump test: Yes			
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud				
Location ID			Max				Stable				Comments	
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)		CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		H2S
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							0	0.00	20.9	0	0.0	
Stormwater Pit 8							0	0.00	20.9	0	0.0	
Wash Bay							0	0.00	20.9	0	0.0	
Storage Shed							0	0.00	20.9	0	0.0	
Toilet 1 - Male							0	0.00	20.9	0	0.0	
Toilet 2 - Female							0	0.00	20.9	0	0.0	
Lunch Room							0	0.00	20.9	0	0.0	
Toilet 3							0	0.00	20.9	0	0.0	
Mainfreight												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							0	0.00	20.9	0	0.0	
Dispatch office							0	0.00	20.9	0	0.0	
Lunchroom							0	0.00	20.9	0	0.0	
Toilet							0	0.00	20.9	0	0.0	
Mulgoa Quarries												
Stormwater Pit 1							0	0.00	20.9	0	0.0	
Stormwater Pit 2							0	0.00	20.9	0	0.0	
Stormwater Pit 3							0	0.00	20.9	0	0.0	
Stormwater Pit 4							0	0.00	20.9	0	0.0	
Stormwater Pit 5							0	0.00	20.9	0	0.0	
Stormwater Pit 6							0	0.00	20.9	0	0.0	
Stormwater Pit 7							0	0.00	20.9	0	0.0	

Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 20/03/24		Start time: 1000		Finish time: 1600	
Monitoring personnel: JC			Monitoring equipment: RK Eagle II			Bump test: Yes					
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud			
Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15						0	0.00	20.9	0	0.0	
Wash Bay						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Kitchen						0	0.00	20.9	0	0.0	
Darley Aluminium											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Warehouse						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Toilet 2						0	0.00	20.9	0	0.0	
ORAFOL/EHI											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Electrical 1						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 20/03/24		Start time: 1000		Finish time: 1600	
Monitoring personnel: JC			Monitoring equipment: RK Eagle II			Bump test: Yes					
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising		Weather and ground conditions: 20C, sunny, dry, some cloud			
Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Electrical 2						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15						0	0.00	20.9	0	0.0	
Stormwater Pit 16						0	0.00	20.9	0	0.0	
Bluescope Steel											
Service Pit 1						0	0.00	20.9	0	0.0	
Electrical Pit 1						0	0.00	20.9	0	0.0	
Service Pit 2						0	0.00	20.9	0	0.0	
Electrical Pit 2						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Shower						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Pump Room						0	0.00	20.9	0	0.0	

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence
-------------------------------	-------------------------------	----------------	------------------------------

6/02/2025	9/07/2024	18/06/2024	Inside all buildings or other enclosed structures within 250m of deposited waste.								
Location ID			Max					Stable			Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Cleanaway											
Emergency Shower						10	0.02	20.9	0	0.0	
Male Toilet						10	0.04	20.9	0	0.0	
Female Toilet						10	0.04	20.9	0	0.0	
Handicap Toilet						5	0.02	20.9	0	0.0	
Office 7						0	0.04	20.9	0	0.0	
Server room						0	0.00	20.9	0	0.0	
Office 6						5	0.02	20.9	0	0.0	
Office 5						0	0.00	20.9	0	0.0	
Office 4						0	0.02	20.9	0	0.0	
Office 3						0	0.02	20.9	0	0.0	
Office 2						0	0.02	20.9	0	0.0	
Office 1						15	0.00	20.9	0	0.0	
Office 8						15	0.02	20.9	0	0.0	
Weighbridge						5	0.00	20.9	0	0.0	
Meal Room						15	0.00	20.9	0	0.0	
Conference Room						20	0.00	20.9	0	0.0	
Lobby						0	0.02	20.9	0	0.0	
Male Toilet 2						10	0.02	20.9	0	0.0	
Female Toilet 2						5	0.02	20.9	0	0.0	
Unisex Toilet						0	0.02	20.9	0	0.0	
Locker Room						10	0.02	20.9	0	0.0	
Stramit											
Stormwater Pit 1						30	0.00	20.9	0	0.0	
Stormwater Pit 2						40	0.00	20.9	0	0.0	
Stormwater Pit 3						55	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						45	0.00	20.9	0	0.0	
Stormwater Pit 6						25	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 18/06/24		Start time: 0800		Finish time: 1600	
Monitoring personnel: LS / MS		Monitoring equipment: RK Eagle II			Bump test: Yes						
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry. Wet ground		
Location ID			Max					Stable			Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Weighbridge						15	0.00	20.9	0	0.0	
Men Toilet 1						0	0.00	20.9	0	0.0	
Lunch Room 1						0	0.04	20.9	0	0.0	
Men Toilet 2						50	0.00	20.9	0	0.0	
Lunch Room 2						40	0.04	20.9	0	0.0	
Stockland/Viscount Pooling											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						10	0.00	20.9	0	0.0	
Stormwater Pit 8						15	0.00	20.9	0	0.0	
Stormwater Pit 9						10	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Change Room						0	0.00	20.9	0	0.0	
Lunch Room						15	0.00	20.9	0	0.0	
Toilet						55	0.00	20.9	0	0.0	
Warehouse						30	0.00	20.9	0	0.0	
Dincol											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						40	0.00	20.9	0	0.0	
Stormwater Pit 3						25	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 18/06/24		Start time: 0800		Finish time: 1600	
Monitoring personnel: LS / MS		Monitoring equipment: RK Eagle II			Bump test: Yes						
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry. Wet ground		
Location ID			Max					Stable			Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						15	0.00	20.9	0	0.0	

Stormwater Pit 8							0	0.00	20.9	0	0.0				
Dispatch Office							10	0.00	20.9	0	0.0				
Toilet 1							65	0.00	20.9	0	0.0				
Electrical Room							15	0.00	20.9	0	0.0				
Toilet 2							0	0.00	20.9	0	0.0				
Saputo															
Stormwater Pit 1							0	0.00	20.9	0	0.0				
Stormwater Pit 2							30	0.00	20.9	0	0.0				
Stormwater Pit 3							15	0.00	20.9	0	0.0				
Stormwater Pit 4							0	0.00	20.9	0	0.0				
Stormwater Pit 5							0	0.00	20.9	0	0.0				
Stormwater Pit 6							40	0.00	20.9	0	0.0				
Electrical Pit 1							130	0.00	20.9	0	0.0				
Electrical Pit 2							40	0.00	20.9	0	0.0				
Electrical Pit 3							90	0.00	20.9	0	0.0				
Electrical Pit 4							30	0.00	20.9	0	0.0				
Electrical Pit 5							35	0.00	20.9	0	0.0				
Electrical Pit 6							50	0.00	20.9	0	0.0				
Electrical Pit 7							0	0.00	20.9	0	0.0				
Electrical Pit 8							0	0.00	20.9	0	0.0				
LOSCAM															
Stormwater Pit 1							0	0.00	20.9	0	0.0				
Stormwater Pit 2							30	0.00	20.9	0	0.0				
Stormwater Pit 3							15	0.00	20.9	0	0.0				
Stormwater Pit 4												No access			
Site: Erskine Park						Date: 18/06/24			Start time: 0800		Finish time: 1600				
Monitoring personnel: LS / MS				Monitoring equipment: RK Eagle II				Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry, Wet ground				
Location ID		CH4 PPM		CO2 (% v/v)		Max Min O2 (% v/v)		CO		H2S		Stable CH4 PPM CO2 (% v/v) Min O2 (% v/v) CO H2S		Comments	
Stormwater Pit 5												0 0.00 20.9 0 0.0			
Stormwater Pit 6												0 0.00 20.9 0 0.0			
Stormwater Pit 7												0 0.00 20.9 0 0.0			
Stormwater Pit 8												0 0.00 20.9 0 0.0			
Wash Bay												0 0.00 20.9 0 0.0			
Storage Shed												0 0.00 20.9 0 0.0			
Toilet 1 - Male												0 0.00 20.9 0 0.0			
Toilet 2 - Female												0 0.00 20.9 0 0.0			
Lunch Room												0 0.04 20.9 0 0.0			
Toilet 3												0 0.00 20.9 0 0.0			
Mainfreight															
Stormwater Pit 1														No access. Change in tenant. Need to	
Stormwater Pit 2															
Stormwater Pit 3															
Stormwater Pit 4															
Stormwater Pit 5															
Stormwater Pit 6															
Stormwater Pit 7															
Dispatch office															
Lunchroom															
Toilet															
Mulgoa Quarries															
Stormwater Pit 1												0 0.00 20.9 0 0.0			
Stormwater Pit 2												0 0.00 20.9 0 0.0			
Stormwater Pit 3												0 0.00 20.9 0 0.0			
Stormwater Pit 4												55 0.00 20.9 0 0.0			
Stormwater Pit 5												35 0.00 20.9 0 0.0			
Stormwater Pit 6												10 0.00 20.9 0 0.0			
Stormwater Pit 7												5 0.00 20.9 0 0.0			
Stormwater Pit 8												20 0.00 20.9 0 0.0			
Stormwater Pit 9												0 0.00 20.9 0 0.0			
Site: Erskine Park						Date: 18/06/24			Start time: 0800			Finish time: 1600			
Monitoring personnel: LS / MS				Monitoring equipment: RK Eagle II				Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry, Wet ground			Bump test: Yes	
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry, Wet ground						
Location ID		CH4 PPM		CO2 (% v/v)		Max Min O2 (% v/v)		CO		H2S		Stable CH4 PPM CO2 (% v/v) Min O2 (% v/v) CO H2S		Comments	
Stormwater Pit 10												0 0.00 20.9 0 0.0			
Stormwater Pit 11												5 0.00 20.9 0 0.0			
Stormwater Pit 12												0 0.00 20.9 0 0.0			
Stormwater Pit 13												0 0.00 20.9 0 0.0			
Stormwater Pit 14												10 0.00 20.9 0 0.0			
Stormwater Pit 15												0 0.00 20.9 0 0.0			
Wash Bay												0 0.00 20.9 0 0.0			

Toilet						0	0.00	20.9	0	0.0	
Lunch Room						0	0.00	20.9	0	0.0	
Kitchen						0	0.00	20.9	0	0.0	
Darley Aluminium											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8											No access to test
Lunch Room						0	0.00	20.9	0	0.0	
Warehouse						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Toilet						5	0.00	20.9	0	0.0	
Toilet 2						0	0.00	20.9	0	0.0	
ORAFOL/EHI											
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						0	0.00	20.9	0	0.0	
Stormwater Pit 3						0	0.00	20.9	0	0.0	
Stormwater Pit 4						0	0.00	20.9	0	0.0	
Stormwater Pit 5						0	0.00	20.9	0	0.0	
Stormwater Pit 6						15	0.00	20.9	0	0.0	
Electrical 1						0	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Site: Erskine Park						Date: 18/06/24			Start time: 0800		Finish time: 1600
Monitoring personnel: LS / MS			Monitoring equipment: RK Eagle II			Bump test: Yes					
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry, Wet ground		
Location ID	Max					Stable					Comments
	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Electrical 2						0	0.00	20.9	0	0.0	
Stormwater Pit 9						5	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Stormwater Pit 11						0	0.00	20.9	0	0.0	
Stormwater Pit 12						0	0.00	20.9	0	0.0	
Stormwater Pit 13						0	0.00	20.9	0	0.0	
Stormwater Pit 14						0	0.00	20.9	0	0.0	
Stormwater Pit 15						0	0.00	20.9	0	0.0	
Stormwater Pit 16						0	0.00	20.9	0	0.0	
Bluescope Steel											
Service Pit 1						0	0.00	20.9	0	0.0	
Electrical Pit 1						0	0.00	20.9	0	0.0	
Service Pit 2						0	0.00	20.9	0	0.0	
Electrical Pit 2						0	0.00	20.9	0	0.0	
Office						0	0.00	20.9	0	0.0	
Shower						0	0.00	20.9	0	0.0	
Toilet						0	0.00	20.9	0	0.0	
Stormwater Pit 1						0	0.00	20.9	0	0.0	
Stormwater Pit 2						1	0.00	20.9	0	0.0	
Stormwater Pit 3						1	0.00	20.9	0	0.0	
Stormwater Pit 4						1	0.00	20.9	0	0.0	
Stormwater Pit 5						1	0.00	20.9	0	0.0	
Stormwater Pit 6						1	0.00	20.9	0	0.0	
Stormwater Pit 7						0	0.00	20.9	0	0.0	
Stormwater Pit 8						0	0.00	20.9	0	0.0	
Stormwater Pit 9						0	0.00	20.9	0	0.0	
Stormwater Pit 10						0	0.00	20.9	0	0.0	
Pump Room						0	0.00	20.9	0	0.0	

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence								
6/02/2025	6/02/2025	23-25/09/2024	Inside all buildings or other enclosed structures within 250m of deposited waste,								
Location ID	Date	Time	Max			Stable					Comments
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Cleanaway											
Emergency shower	2024-09-25	9:18:00	-	-	-	0	0	21	0	0	-
Male Toilet 1	2024-09-25	9:19:00	-	-	-	65	0	21	0	0	-
Female Toilet 2	2024-09-25	9:26:00	-	-	-	60	0	21	0	0	-
Handicapped Toilet	2024-09-25	9:20:00	-	-	-	55	0	21	0	0	-
Office 7	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-
Server room	2024-09-25	9:20:00	-	-	-	0	0	21	0	0	-
Office 6	2024-09-25	9:20:00	-	-	-	0	0	21	0	0	-
Office 5	-	-	-	-	-	-	-	-	-	-	-
Office 4	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-

Office 3	2024-09-25	9:21:00	-	-	-	0	0	21	0	0	-
Office 2	2024-09-25	9:22:00	-	-	-	0	0	21	0	0	-
Office 1	2024-09-25	9:24:00	-	-	-	0	0	21	0	0	-
Office 8	2024-09-25	9:24:00	-	-	-	20	0	21	0	0	-
Weighbridge	2024-09-25	9:24:00	-	-	-	30	0	21	0	0	-
Lunch Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-
Conference Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-
Lobby	2024-09-25	9:22:00	-	-	-	0	0	21	0	0	-
Male Toilet 2	2024-09-25	9:26:00	-	-	-	65	0	21	0	0	-
Female Toilet 2	2024-09-25	9:26:00	-	-	-	60	0	21	0	0	-
Handicapped Toilet 2	2024-09-25	9:26:00	-	-	-	30	0	21	0	0	-
Locker Room	2024-09-25	9:25:00	-	-	-	0	0	21	0	0	-
Strammit											
SW1	2024-09-24	12:32:15	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	12:33:58	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	12:35:43	-	-	-	0	0	21	0	0	-
SW4	2024-09-24	12:38:00	-	-	-	35	0	21	0	0	-
SW5	2024-09-24	12:39:40	-	-	-	55	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: LS						Monitoring equipment: RK Eagle II				Bump test: Yes	
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry.	
Location ID	Date	Time	Max			Stable				Comments	
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
SW6	2024-09-24	12:42:31	-	-	-	0	0	21	0	0	-
SW7	-	-	-	-	-	-	-	-	-	-	-
WB	2024-09-24	12:51:49	-	-	-	5	0	21	0	0	-
MT 1	2024-09-24	12:57:21	-	-	-	95	0	21	0	0	-
LR 1	2024-09-24	12:55:09	-	-	-	85	0	21	0	0	-
MT 2	2024-09-24	12:49:33	-	-	-	0	70	21	0	0	-
LR 2	2024-09-24	12:46:50	-	-	-	20	0	21	0	0	-
Stockland Viscount Pooling											
SW1	2024-09-24	13:29:26	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	13:30:40	-	-	-	0	0	0	0	0	-
SW3	2024-09-24	13:32:03	-	-	-	35	0	21	0	0	-
SW4	2024-09-24	13:33:05	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	13:34:58	-	-	-	0	0	21	0	0	-
SW6	2024-09-24	13:36:21	-	-	-	35	0	21	0	0	-
SW7	2024-09-24	13:39:01	-	-	-	0	0	21	0	0	-
SW8	2024-09-24	13:39:51	-	-	-	5	0	21	0	0	-
SW9	2024-09-24	13:43:33	-	-	-	20	0	21	0	0	-
SW10	2024-09-24	13:45:20	-	-	-	15	0	21	0	0	-
Change Room	-	-	-	-	-	-	-	-	-	-	-
Lunchroom	2024-09-24	13:56:51	-	-	-	0	0	21	0	0	-
Male Toilet	2024-09-24	13:57:52	-	-	-	120	0	21	0	0	-
Warehouse	2024-09-24	13:42:44	-	-	-	25	0	21	0	0	-
Dincol											
SW1	2024-09-24	14:16:34	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	14:17:41	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	14:19:17	-	-	-	0	0	21	0	0	-
SW4	2024-09-24	14:25:48	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	13:47:02	-	-	-	20	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: LS						Monitoring equipment: RK Eagle II				Bump test: Yes	
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry.	
Location ID	Date	Time	Max			Stable				Comments	
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
SW6	2024-09-24	13:49:42	-	-	-	15	0	21	0	0	-
SW7	2024-09-24	13:52:23	-	-	-	0	0	21	0	0	-
SW8	2024-09-24	14:27:43	-	-	-	0	0	0	0	0	-
Dispatch	2024-09-24	14:22:49	-	-	-	30	0	21	0	0	-
Toilet 1	2024-09-24	14:23:28	-	-	-	60	0	21	0	0	-
Elec Room	2024-09-24	14:10:36	-	-	-	20	0	21	0	0	-
Toilet 2	2024-09-24	15:17:56	-	-	-	55	0	21	0	0	-
Saputo											
SW1	2024-09-24	7:34:36	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	7:31:59	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	7:47:00	-	-	-	15	0	21	0	0	-
SW4	2024-09-24	7:48:42	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	7:51:55	-	-	-	250	0	21	0	0	-
SW6	2024-09-24	7:59:12	-	-	-	35	0	21	0	0	-
F1	2024-09-24	7:36:39	-	-	-	15	0	21	0	0	-
F2	2024-09-24	7:37:58	-	-	-	5	0	21	0	0	-
F3	2024-09-24	7:39:47	-	-	-	35	0	21	0	0	-
E4	2024-09-24	7:41:50	-	-	-	0	0	21	0	0	-
E5	2024-09-24	7:53:57	-	-	-	65	0	21	0	0	-

E6	2024-09-24	7:55:48	-	-	-	40	0	21	0	0	-
LOSCAM											
SW1	2024-09-24	10:35:58	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	10:36:34	-	-	-	0	0	21	0	0	-
SW3	-	-	-	-	-	-	-	-	-	-	-
SW4	2024-09-24	10:23:28	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	10:27:03	-	-	-	0	0	21	0	0	-
SW6	2024-09-24	10:29:45	-	-	-	0	0	0	0	0	-
SW7	2024-09-24	10:31:22	-	-	-	0	0	21	0	0	-
Site: Erskine Park						Monitoring equipment: RK Eagle II			Bump test: Yes		
Monitoring personnel: LS						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry.		
Location ID	Date	Time	Max			Stable					Comments
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
SW8	-	-	-	-	-	-	-	-	-	-	-
Wash Bay	2024-09-24	10:21:35	-	-	-	60	0	21	0	0	-
Male Toilet	2024-09-24	10:39:39	-	-	-	10	0	21	0	0	-
Warehouse Ambient	2024-09-24	10:22:40	-	-	-	0	0	21	0	0	-
Mainfreight											
SW1	-	-	-	-	-	-	-	-	-	-	No Access
SW2	-	-	-	-	-	-	-	-	-	-	No Access
SW3	-	-	-	-	-	-	-	-	-	-	No Access
SW4	-	-	-	-	-	-	-	-	-	-	No Access
SW5	-	-	-	-	-	-	-	-	-	-	No Access
SW6	-	-	-	-	-	-	-	-	-	-	No Access
SW7	-	-	-	-	-	-	-	-	-	-	No Access
Dispatch office	-	-	-	-	-	-	-	-	-	-	No Access
Lunchroom	-	-	-	-	-	-	-	-	-	-	No Access
Toilet	-	-	-	-	-	-	-	-	-	-	No Access
Mulgoa Quarries											
SW1	2024-09-24	9:16:00	-	-	-	0	0	21	0	0	-
SW2	2024-09-24	9:17:10	-	-	-	0	0	21	0	0	-
SW3	2024-09-24	9:18:33	-	-	-	0	0	21	0	0	-
SW4	2024-09-24	9:19:30	-	-	-	0	0	21	0	0	-
SW5	2024-09-24	9:20:19	-	-	-	0	0	21	0	0	-
SW6	2024-09-24	9:21:30	-	-	-	0	0	21	0	0	-
SW7	2024-09-24	9:22:30	-	-	-	0	0	21	0	0	-
SW8	2024-09-24	9:23:33	-	-	-	0	0	21	0	0	-
SW9	2024-09-24	9:24:47	-	-	-	0	0	21	0	0	-
SW10	2024-09-24	9:25:28	-	-	-	0	0	21	0	0	-
SW11	2024-09-24	9:26:35	-	-	-	0	0	21	0	0	-
SW12	2024-09-24	9:28:05	-	-	-	0	0	21	0	0	-
SW13	2024-09-24	9:29:04	-	-	-	0	0	21	0	0	-
SW14	2024-09-24	9:30:28	-	-	-	25	0	21	0	0	-
Site: Erskine Park						Monitoring equipment: RK Eagle II			Bump test: Yes		
Monitoring personnel: LS						Rising or falling: Rising			Weather and ground conditions: 14C, cloudy, dry.		
Location ID	Date	Time	Max			Stable					Comments
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
SW15	2024-09-24	9:31:34	-	-	-	15	0	21	0	0	-
Wash Bay	2024-09-24	9:40:22	-	-	-	45	0	21	0	0	-
Male Toilet	2024-09-24	9:38:44	-	-	-	55	0	21	0	0	-
Lunch Room	2024-09-24	9:35:13	-	-	-	0	0	21	0	0	-
Darley Aluminium											
SW1	2024-09-23	8:35:36	-	-	-	5	0	21	0	0	-
SW2	2024-09-23	8:36:51	-	-	-	0	0	21	0	0	-
SW3	2024-09-23	8:38:02	-	-	-	10	0	21	0	0	-
SW4	2024-09-23	8:39:10	-	-	-	0	0	0	0	0	-
SW5	2024-09-23	8:43:55	-	-	-	0	0	21	0	0	-
SW6	2024-09-23	8:45:39	-	-	-	0	0	21	0	0	-
SW7	2024-09-23	8:46:32	-	-	-	0	0	21	0	0	-
SW8	2024-09-23	8:42:32	-	-	-	0	0	21	0	0	-
Lunch Room	2024-09-23	8:49:07	-	-	-	15	0	21	0	0	-
Male Toilet	2024-09-23	8:52:34	-	-	-	55	0	21	0	0	-
ORAFOL/EHI											
SW1	2024-09-23	8:10:41	-	-	-	35	0	21	0	0	-
SW2	2024-09-23	8:09:41	-	-	-	40	0	21	0	0	-
SW3	2024-09-23	8:08:29	-	-	-	0	0	21	0	0	-
SW4	2024-09-23	8:06:42	-	-	-	0	0	21	0	0	-
SW5	2024-09-23	8:04:36	-	-	-	85	0	21	0	0	-
SW6	2024-09-23	8:02:32	-	-	-	60	0	21	0	0	-
SW7	2024-09-23	8:01:33	-	-	-	0	0	21	0	0	-
SW8	2024-09-23	8:00:13	-	-	-	5	0	21	0	0	-
SW9	2024-09-23	7:51:26	-	-	-	20	0	21	0	0	-

SW10	2024-09-23	7:50:29	-	-	-	0	0	21	0	0	-
SW11	2024-09-23	7:49:41	-	-	-	5	0	21	0	0	-
SW12	2024-09-23	7:47:36	-	-	-	0	0	21	0	0	-
SW13	2024-09-23	7:46:22	-	-	-	35	0	21	0	0	-
SW14	2024-09-23	7:45:18	-	-	-	15	0	21	0	0	-
SW15	2024-09-23	7:44:30	-	-	-	0	0	21	0	0	-
SW16	2024-09-23	7:53:17	-	-	-	0	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: LS						Monitoring equipment: RK Eagle II				Bump test: Yes	
Atmospheric pressure at start (mb): 1005						Rising or falling: Rising				Weather and ground conditions: 14C, cloudy, dry.	
Location ID	Date	Time	Max			Stable				H2S	Comments
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		
SW17	2024-09-23	7:57:01	-	-	-	0	0	21	0	0	-
Bluescope Steel											
Service Pit 1	2024-09-23	7:20:28	-	-	-	80	0	21	0	0	-
Electrical Pit 1	2024-09-23	7:13:37	-	-	-	60	0	21	0	0	-
Indoor cart celler	2024-09-23	7:11:12	-	-	-	0	0	21	0	0	-
Office	2024-09-23	7:18:19	-	-	-	0	0	21	0	0	-
Shower	2024-09-23	7:09:01	-	-	-	0	0	21	0	0	-
Toilet	2024-09-23	7:08:28	-	-	-	0	0	21	0	0	-
SW Pit	2024-09-23	7:03:30	-	-	-	0	0	21	0	0	-
SW pit adjacent service road 1	2024-09-23	6:44:57	-	-	-	10	0	21	0	0	-
SW pit adjacent service road 2	2024-09-23	6:46:25	-	-	-	35	0	21	0	0	-
SW pit adjacent service road 3	2024-09-23	6:47:42	-	-	-	30	0	21	0	0	-
SW pit adjacent service road 4	2024-09-23	6:48:57	-	-	-	10	0	21	10	0	-
SW Pit 5	2024-09-23	6:50:40	-	-	-	60	0	21	0	0	-
SW Pit 6	2024-09-23	6:52:51	-	-	-	30	0	21	0	0	-
SW Pit 7	2024-09-23	6:54:33	-	-	-	35	0	21	0	0	-
SW Pit 8	2024-09-23	6:55:49	-	-	-	0	0	21	0	0	-
SW Pit 9	2024-09-23	8:55:18	-	-	-	0	0	21	0	0	-
SW Pit	2024-09-23	7:03:30	-	-	-	0	0	21	0	0	-
Date Monitoring Data Uploaded		Date Monitoring Data Obtained		Date Monitored		Sampled Point as per Licence					
6/02/2025		6/02/2025		16-19/12/2024		Inside all buildings or other enclosed structures within 250m of deposited waste.					
Location ID	Date	Time	Max			Stable				H2S	Comments
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		
Cleanaway											
Emergency shower	2024-12-16	6:18:48 AM	-	-	-	0	0	21	0	0	-
Male Toilet 1	2024-12-16	6:18:37 AM	-	-	-	0	0	21	0	0	-
Female Toilet 2	2024-12-16	6:20:50 AM	-	-	-	0	0	21	0	0	-
Handicapped Toilet	2024-12-16	6:18:15 AM	-	-	-	0	0	21	0	0	-
Office 7	2024-12-16	6:17:31 AM	-	-	-	0	0	21	0	0	-
Server room	2024-12-16	6:18:01 AM	-	-	-	0	0	21	0	0	-
Office 6	2024-12-16	6:17:43 AM	-	-	-	0	0	21	0	0	-
Office 5	-	-	-	-	-	-	-	-	-	-	-
Office 4	2024-12-16	6:17:19 AM	-	-	-	0	0	21	0	0	-
Office 3	-	-	-	-	-	-	-	-	-	-	-
Office 2	2024-12-16	6:16:56 AM	-	-	-	0	0	21	0	0	-
Office 1	2024-12-16	6:19:45 AM	-	-	-	0	0	21	0	0	-
Office 8	2024-12-16	6:19:22 AM	-	-	-	0	0	21	0	0	-
Weighbridge	2024-12-16	6:19:34 AM	-	-	-	0	0	21	0	0	-
Lunch Room	2024-12-16	6:20:08 AM	-	-	-	0	0	21	0	0	-
Conference Room	2024-12-16	6:19:57 AM	-	-	-	0	0	21	0	0	-
Lobby	2024-12-16	6:16:27 AM	-	-	-	0	0	21	0	0	-
Male Toilet 2	2024-12-16	6:20:19 AM	-	-	-	0	0	21	0	0	-
Female Toilet 2	2024-12-16	6:20:50 AM	-	-	-	0	0	21	0	0	-
Handicapped Toilet 2	2024-12-16	6:20:29 AM	-	-	-	0	0	21	0	0	-
Locker Room	2024-12-16	6:11:41 AM	-	-	-	45	0	21	0	0	-
Strammit											
SW1	2024-12-16	8:09:56 AM	-	-	-	0	0	21	0	0	-
SW2	2024-12-16	8:10:25 AM	-	-	-	0	0	21	0	0	-
SW3	2024-12-16	8:10:41 AM	-	-	-	0	0	21	0	0	-
SW4	2024-12-16	8:10:54 AM	-	-	-	0	0	21	0	0	-
Site: Erskine Park											
Monitoring personnel: JB						Monitoring equipment: RK Eagle II				Bump test: Yes	
Atmospheric pressure at start (mb): 1015						Rising or falling: Falling				Weather and ground conditions: 17C, clear, dry.	
Location ID	Date	Time	Max			Stable				H2S	Comments
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO		
SW5	2024-12-16	8:11:05 AM	-	-	-	0	0	21	0	0	-
SW6	2024-12-16	8:11:17 AM	-	-	-	0	0	21	0	0	-
SW7	-	-	-	-	-	-	-	-	-	-	-
WB	2024-12-16	8:09:46 AM	-	-	-	0	0	21	0	0	-
MT 1	2024-12-16	8:08:42 AM	-	-	-	120	0	21	0	0	-
LR 1	2024-12-16	8:09:33 AM	-	-	-	0	0	21	0	0	-
MT 2	2024-12-16	8:08:07 AM	-	-	-	55	0	21	0	0	-
LR 2	2024-12-16	8:09:21 AM	-	-	-	0	0	21	0	0	-

[illegible]

[illegible]

SW PR	2024-12-19	9:37:44 AM	-	-	-	0	0	21	0	0	-
Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence								
7/05/2025	1/05/2025	27/03/2025	Inside all buildings or other enclosed structures within 250m of deposited waste,								
Location ID	Date	Time	Max			Stable					Comments
			CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CH4 PPM	CO2 (% v/v)	Min O2 (% v/v)	CO	H2S	
Cleanaway											
Emergency shower	2025-03-26	7:13:42 AM	-	-	-	10	0	20.9	0	0	-
Male Toilet 1	2025-03-26	7:14:03 AM	-	-	-	0	0	20.9	0	0	-
Female Toilet 2	2025-03-26	7:19:10 AM	-	-	-	0	0	20.9	0	0	-
Handicapped Toilet	2025-03-26	7:11:58 AM	-	-	-	0	0	20.9	0	0	-
Office 7	2025-03-26	7:11:00 AM	-	-	-	0	0	20.9	0	0	-
Server room	2025-03-26	7:12:44 AM	-	-	-	5	0	20.9	0	0	-
Office 6	2025-03-26	7:11:11 AM	-	-	-	0	0	20.9	0	0	-
Office 5			-	-	-	-	-	-	-	-	No Access
Office 4	2025-03-26	7:10:05 AM	-	-	-	0	0	20.9	0	0	-
Office 3	2025-03-26	7:09:30 AM	-	-	-	0	0	20.9	0	0	-
Office 2	2025-03-26	7:08:46 AM	-	-	-	0	0.04	20.9	0	0	-
Office 1	2025-03-26	7:15:55 AM	-	-	-	0	0	20.9	0	0	-
Office 8	2025-03-26	7:15:34 AM	-	-	-	0	0	20.9	0	0	-
Weighbridge	2025-03-26	7:15:45 AM	-	-	-	0	0	20.9	0	0	-
Lunch Room	2025-03-26	7:16:07 AM	-	-	-	0	0	20.9	0	0	-
Conference Room	2025-03-26	7:16:58 AM	-	-	-	0	0	20.9	0	0	-
Lobby	2025-03-26	7:19:34 AM	-	-	-	0	0	20.9	0	0	-
Male Toilet 2	2025-03-26	7:17:48 AM	-	-	-	15	0	20.9	0	0	-
Female Toilet 2	2025-03-26	7:19:10 AM	-	-	-	0	0	20.9	0	0	-
Handicapped Toilet 2	2025-03-26	7:18:31 AM	-	-	-	0	0	20.9	0	0	-
Locker Room	2025-03-26	7:17:19 AM	-	-	-	0	0	20.9	0	0	-
Strammit											
SW1	2025-03-26	8:06:56 AM	-	-	-	0	0	20.9	0	0	-
SW2	2025-03-26	8:06:37 AM	-	-	-	5	0	20.9	0	0	-
SW3	2025-03-26	8:07:08 AM	-	-	-	0	0	20.9	0	0	-
SW4	2025-03-26	8:07:38 AM	-	-	-	0	0	20.9	0	0	-
SW5	2025-03-26	8:23:14 AM	-	-	-	0	0	20.9	0	0	-
SW6	2025-03-26	8:09:31 AM	-	-	-	0	0	20.9	0	0	-
SW7	2025-03-26	8:09:32 AM	-	-	-	0	0	20.9	0	0	-
WB	2025-03-26	8:13:03 AM	-	-	-	0	0	20.9	0	0	-
MT 1	2025-03-26	8:22:51 AM	-	-	-	0	0.04	20.9	0	0	-
LR 1	2025-03-26	8:22:40 AM	-	-	-	0	0	20.9	0	0	-
MT 2	2025-03-26	8:12:50 AM	-	-	-	0	0	20.9	0	0	-
LR 2	2025-03-26	8:11:50 AM	-	-	-	0	0.02	20.9	0	0	-
Stockland Viscount Pooling											
SW1	2025-03-27	8:07:18 AM	-	-	-	0	0	20.9	0	0	-
SW2	2025-03-27	8:07:30 AM	-	-	-	0	0	20.9	0	0	-
SW3	2025-03-27	8:07:41 AM	-	-	-	0	0	20.9	0	0	-
SW4	2025-03-27	8:07:51 AM	-	-	-	0	0	20.9	0	0	-
SW5	2025-03-27	8:08:09 AM	-	-	-	0	0	20.9	0	0	-
SW6	2025-03-27	8:08:18 AM	-	-	-	0	0	20.9	0	0	-
SW7	2025-03-27	8:08:39 AM	-	-	-	0	0	20.9	0	0	-
SW8	2025-03-27	8:08:49 AM	-	-	-	0	0	20.9	0	0	-
SW9	2025-03-27	8:09:02 AM	-	-	-	5	0	20.9	0	0	-
SW10	2025-03-27	8:09:18 AM	-	-	-	0	0	20.9	0	0	-
Change Room	-	-	-	-	-	-	-	-	-	-	No Access
Lunchroom	2025-03-27	8:09:51 AM	-	-	-	0	0	20.9	0	0	-
Male Toilet	-	-	-	-	-	-	-	-	-	-	No Access
Warehouse	2025-03-27	8:08:29 AM	-	-	-	0	0	20.9	0	0	-
Dintel											
SW1	2025-03-27	8:18:43 AM	-	-	-	0	0	20.9	0	0	-
SW2	2025-03-27	8:19:10 AM	-	-	-	0	0	20.9	0	0	-
SW3	2025-03-27	8:19:30 AM	-	-	-	0	0	20.9	0	0	-
SW4	2025-03-27	8:19:56 AM	-	-	-	0	0	20.9	0	0	-
SW5	2025-03-27	8:22:30 AM	-	-	-	0	0	20.9	0	0	-
SW6	2025-03-27	8:23:19 AM	-	-	-	0	0	20.9	0	0	-
SW7	2025-03-27	8:23:59 AM	-	-	-	0	0	20.9	0	0	-
SW8	2025-03-27	8:20:40 AM	-	-	-	0	0	20.9	0	0	-
Dispatch	2025-03-27	8:21:36 AM	-	-	-	0	0	20.9	0	0	-
Toilet 1	2025-03-27	8:21:47 AM	-	-	-	0	0	20.9	0	0	-
Elec. Room	2025-03-27	8:18:03 AM	-	-	-	0	0	20.9	0	0	-
Toilet 2	2025-03-27	8:17:49 AM	-	-	-	0	0	20.9	0	0	-
Saputo											
SW1	2025-03-27	8:47:39 AM	-	-	-	0	0	20.9	0	0	-
SW2	2025-03-27	8:47:25 AM	-	-	-	0	0	20.9	0	0	-
SW3	2025-03-27	8:43:16 AM	-	-	-	10	0	20.9	0	0	-

SW4	2025-03-27	8:44:21 AM	-	-	-	0	0	20.9	0	0	-
SW5	2025-03-27	8:44:40 AM	-	-	-	0	0	20.9	0	0	-
SW6	2025-03-27	8:44:56 AM	-	-	-	0	0	20.9	0	0	-
E1	2025-03-27	8:46:57 AM	-	-	-	0	0	20.9	0	0	-
E2	2025-03-27	8:46:21 AM	-	-	-	0	0	20.9	0	0	-
E3	2025-03-27	8:46:06 AM	-	-	-	0	0	20.9	0	0	-
E4	2025-03-27	8:43:49 AM	-	-	-	15	0	20.9	0	0	-
E5	2025-03-27	8:45:41 AM	-	-	-	0	0	20.9	0	0	-
E6	2025-03-27	8:45:20 AM	-	-	-	0	0	20.9	0	0	-
LOSCAM											
SW1	2025-03-26	8:48:14 AM	-	-	-	0	0	20.9	0	0	-
SW2	2025-03-26	8:47:57 AM	-	-	-	0	0	20.9	0	0	-
SW3	-	-	-	-	-	-	-	-	-	-	No Access
SW4	2025-03-26	8:47:17 AM	-	-	-	0	0	20.9	0	0	-
SW5	2025-03-26	8:46:52 AM	-	-	-	0	0	20.9	0	0	-
SW6	2025-03-26	8:46:39 AM	-	-	-	0	0	20.9	0	0	-
SW7	2025-03-26	8:50:28 AM	-	-	-	0	0	20.9	0	0	-
SW8	2025-03-26	8:47:04 AM	-	-	-	0	0	20.9	0	0	-
Wash Bay	2025-03-26	8:47:43 AM	-	-	-	0	0	20.9	0	0	-
Male Toilet	2025-03-26	8:48:25 AM	-	-	-	0	0	20.9	0	0	-
Warehouse Ambient	2025-03-26	8:47:31 AM	-	-	-	0	0	20.9	0	0	-
Mainfreight											
SW1	-	-	-	-	-	-	-	-	-	-	No Access
SW2	-	-	-	-	-	-	-	-	-	-	No Access
SW3	-	-	-	-	-	-	-	-	-	-	No Access
SW4	-	-	-	-	-	-	-	-	-	-	No Access
SW5	-	-	-	-	-	-	-	-	-	-	No Access
SW6	-	-	-	-	-	-	-	-	-	-	No Access
SW7	-	-	-	-	-	-	-	-	-	-	No Access
Dispatch office	-	-	-	-	-	-	-	-	-	-	No Access
Lunchroom	-	-	-	-	-	-	-	-	-	-	No Access
Toilet	-	-	-	-	-	-	-	-	-	-	No Access
Mulgoa Quarries											
SW1	2025-03-27	9:13:51 AM	-	-	-	0	0	20.9	0	0	-
SW2	2025-03-27	9:14:22 AM	-	-	-	0	0	20.9	0	0	-
SW3	2025-03-27	10:02:31 AM	-	-	-	0	0	20.9	0	0	-
SW4	2025-03-27	10:02:21 AM	-	-	-	0	0	20.9	0	0	-
SW5	2025-03-27	10:02:10 AM	-	-	-	0	0	20.9	0	0	-
SW6	2025-03-27	10:02:01 AM	-	-	-	0	0	20.9	0	0	-
SW7	2025-03-27	10:01:51 AM	-	-	-	0	0	20.9	0	0	-
SW8	2025-03-27	9:16:41 AM	-	-	-	15	0	20.9	0	0	-
SW9	2025-03-27	9:17:38 AM	-	-	-	0	0	20.9	0	0	-
SW10	2025-03-27	9:17:50 AM	-	-	-	0	0	20.9	0	0	-
SW11	2025-03-27	9:18:05 AM	-	-	-	0	0	20.9	0	0	-
SW12	2025-03-27	9:18:31 AM	-	-	-	0	0	20.9	0	0	-
SW13	2025-03-27	9:18:57 AM	-	-	-	0	0	20.9	0	0	-
SW14	2025-03-27	9:19:43 AM	-	-	-	0	0	20.9	0	0	-
SW15	2025-03-27	9:20:02 AM	-	-	-	0	0	20.9	0	0	-
Wash Bay	2025-03-27	9:20:19 AM	-	-	-	0	0	20.9	0	0	-
Male Toilet	2025-03-27	9:21:01 AM	-	-	-	0	0	20.9	0	0	-
Lunch Room	2025-03-27	9:20:46 AM	-	-	-	0	0	20.9	0	0	-
Darley Aluminium											
SW1	2025-03-27	7:19:04 AM	-	-	-	0	0	20.9	0	0	-
SW2	2025-03-27	7:19:30 AM	-	-	-	0	0	20.9	0	0	-
SW3	2025-03-27	7:19:40 AM	-	-	-	0	0	20.9	0	0	-
SW4	2025-03-27	7:19:53 AM	-	-	-	0	0	20.9	0	0	-
SW5	2025-03-27	7:20:15 AM	-	-	-	0	0	20.9	0	0	-
SW6	2025-03-27	7:20:26 AM	-	-	-	0	0	20.9	0	0	-
SW7	2025-03-27	7:20:36 AM	-	-	-	0	0	20.9	0	0	-
SW8	2025-03-27	7:20:05 AM	-	-	-	0	0	20.9	0	0	-
Lunch Room	2025-03-27	7:20:47 AM	-	-	-	0	0	20.9	0	0	-
Male Toilet	2025-03-27	7:20:56 AM	-	-	-	0	0	20.9	0	0	-
ORAFOL/EHI											
SW1	2025-03-27	7:40:11 AM	-	-	-	0	0	20.9	0	0	-
SW2	2025-03-27	7:40:43 AM	-	-	-	0	0	20.9	0	0	-
SW3	2025-03-27	7:41:15 AM	-	-	-	0	0	20.9	0	0	-
SW4	2025-03-27	7:41:47 AM	-	-	-	0	0	20.9	0	0	-
SW5	2025-03-27	7:42:11 AM	-	-	-	0	0	20.9	0	0	-
SW6	2025-03-27	7:42:33 AM	-	-	-	0	0	20.9	0	0	-
SW7	2025-03-27	7:42:56 AM	-	-	-	0	0	20.9	0	0	-
SW8	2025-03-27	7:43:11 AM	-	-	-	0	0	20.9	0	0	-
SW9	2025-03-27	7:45:13 AM	-	-	-	0	0	20.9	0	0	-
SW10	2025-03-27	7:47:35 AM	-	-	-	0	0	20.9	0	0	-
SW11	2025-03-27	7:45:31 AM	-	-	-	0	0	20.9	0	0	-
SW12	2025-03-27	7:45:45 AM	-	-	-	0	0	20.9	0	0	-

SW13	2025-03-27	7:46:13 AM	-	-	-	0	0	20.9	0	0	-
SW14	2025-03-27	7:46:30 AM	-	-	-	0	0	20.9	0	0	-
SW15	2025-03-27	7:46:42 AM	-	-	-	0	0	20.9	0	0	-
SW16	2025-03-27	7:45:56 AM	-	-	-	0	0	20.9	0	0	-
SW17	2025-03-27	7:43:29 AM	-	-	-	0	0	20.9	0	0	-
Bluescope Steel											-
Service Pit 1	2025-03-28	12:22:50 PM	-	-	-	0	0	20.9	0	0	-
Electrical Pit 1	2025-03-28	12:01:23 PM	-	-	-	20	0	20.9	0	0	-
Indoor cart cellar	2025-03-28	12:23:04 PM	-	-	-	0	0	20.9	0	0	-
Office	2025-03-28	12:09:46 PM	-	-	-	0	0	20.9	0	0	-
Shower	2025-03-28	12:23:30 PM	-	-	-	0	0	20.9	0	0	-
Toilet	2025-03-28	12:23:17 PM	-	-	-	0	0	20.9	0	0	-
SW Pit	2025-03-28	12:23:51 PM	-	-	-	0	0	20.9	0	0	-
SW pit adjacent service road 1	2025-03-28	12:21:04 PM	-	-	-	0	0	20.9	0	0	-
SW pit adjacent service road 2	2025-03-28	12:20:53 PM	-	-	-	0	0	20.9	0	0	-
SW pit adjacent service road 3	2025-03-28	12:21:17 PM	-	-	-	0	0	20.9	0	0	-
SW pit adjacent service road 4	2025-03-28	12:08:29 PM	-	-	-	0	0	20.9	0	0	-
SW Pit 5	2025-03-28	12:08:39 PM	-	-	-	0	0	20.9	0	0	-
SW Pit 6	2025-03-28	12:08:50 PM	-	-	-	0	0	20.9	0	0	-
SW Pit 7	2025-03-28	12:09:02 PM	-	-	-	0	0	20.9	0	0	-
SW Pit 8	2025-03-28	12:02:17 PM	-	-	-	15	0	20.9	0	0	-
SW Pit 9	2025-03-28	12:07:39 PM	-	-	-	0	0	20.9	0	0	-
SW Pit	2025-03-28	12:23:51 PM	-	-	-	0	0	20.9	0	0	-

Date Monitoring Data Uploaded	Date Monitoring Data Obtained	Date Monitored	Sampled Point as per Licence								
9/07/2025	2/07/2025	20/06/2025	Inside all buildings or other enclosed structures within 250m of deposited waste.								
Location ID	Location Description		Date	Time	Concentrations					Comments	
					CH4 PPM	CO2 (% v/v)	Min O2 (% v/)	CO	H2S		
Cleanaway											
S01	Emergency shower	CleanawayEmergency shower	-	-	-	-	-	-	-		
MT01	Male Toilet 1	CleanawayMale Toilet 1	2025-06-20	1:47:00 PM	0	0	20.9	0	0		
FT01	Female Toilet 2	CleanawayFemale Toilet 2	2025-06-20	1:52:00 PM	0	0	20.9	0	0		
HT01	Handicapped Toilet	CleanawayHandicapped Toilet	2025-06-20	1:46:00 PM	0	0	20.9	0	0		
O07	Office 7	CleanawayOffice 7	2025-06-20	1:46:00 PM	0	0	20.9	0	0		
GR01	Server room	CleanawayServer room	2025-06-20	1:47:00 PM	0	0	20.9	0	0		
O06	Office 6	CleanawayOffice 6	2025-06-20	1:46:00 PM	0	0	20.9	0	0		
O05	Office 5	CleanawayOffice 5	-	-	-	-	-	-	-	No Access	
O04	Office 4	CleanawayOffice 4	2025-06-20	1:46:00 PM	0	0	20.9	0	0		
O03	Office 3	CleanawayOffice 3	-	-	-	-	-	-	-		
O02	Office 2	CleanawayOffice 2	2025-06-20	1:45:00 PM	0	0	20.9	0	0		
O01	Office 1	CleanawayOffice 1	-	-	-	-	-	-	-		
O08	Office 8	CleanawayOffice 8	2025-06-20	1:48:00 PM	0	0	20.9	0	0		
WB01	Weighbridge	CleanawayWeighbridge	2025-06-20	1:48:00 PM	0	0	20.9	0	0		
GR02	Lunch Room	CleanawayLunch Room	2025-06-20	1:49:00 PM	0	0	20.9	0	0		
GR03	Conference Room	CleanawayConference Room	-	-	-	-	-	-	-		
GR04	Lobby	CleanawayLobby	2025-06-20	1:45:00 PM	0	0	20.9	0	0		
MT02	Male Toilet 2	CleanawayMale Toilet 2	2025-06-20	1:50:00 PM	5	0	20.9	0	0		
FT02	Female Toilet 2	CleanawayFemale Toilet 2	2025-06-20	1:52:00 PM	0	0	20.9	0	0		
HT02	Handicapped Toilet 2	CleanawayHandicapped Toilet 2	2025-06-20	1:51:00 PM	0	0	20.9	0	0		
GR05	Locker Room	CleanawayLocker Room	2025-06-20	1:49:00 PM	0	0	20.9	0	0		
GR06	Common Area	CleanawayCommon Area	-	-	-	-	-	-	-		
Strammit											
SW1	Stormwater Pit 1	StrammitSW1	2025-06-19	9:50:42 AM	0	0	20.9	0	0		
SW2	Stormwater Pit 2	StrammitSW2	2025-06-19	9:51:35 AM	0	0	20.9	0	0		
SW3	Stormwater Pit 3	StrammitSW3	2025-06-19	10:00:39 AM	0	0	20.9	0	0		
SW4	Stormwater Pit 4	StrammitSW4	2025-06-19	9:52:16 AM	0	0	20.9	0	0		
SW5	Stormwater Pit 5	StrammitSW5	2025-06-19	9:52:28 AM	0	0	20.9	0	0		
SW6	Stormwater Pit 6	StrammitSW6	2025-06-19	9:52:44 AM	0	0	20.9	0	0		
SW7	Stormwater Pit 7	StrammitSW7	-	-	-	-	-	-	-		
WB01	Weighbridge	StrammitWB01	2025-06-19	9:54:33 AM	0	0	20.9	0	0		
MT01	Male Toilet 1	StrammitMT01	2025-06-19	9:57:16 AM	0	0	20.9	0	0		
GR01	Lunch Room 1	StrammitGR01	2025-06-19	9:57:26 AM	0	0	20.9	0	0		
MT02	Male Toilet 2	StrammitMT02	2025-06-19	9:55:37 AM	0	0	20.9	0	0		
GR02	Lunch Room 2	StrammitGR02	2025-06-19	9:54:47 AM	5	0.04	20.9	0	0		
Stockland Viscount Pooling											
SW1	Stormwater Pit 1	Stockland Viscount PoolingSW1	2025-06-19	11:11:59 AM	0	0	20.9	0	0		
SW2	Stormwater Pit 2	Stockland Viscount PoolingSW2	-	-	-	-	-	-	-		
SW3	Stormwater Pit 3	Stockland Viscount PoolingSW3	2025-06-19	11:19:39 AM	0	0	20.9	0	0		
SW4	Stormwater Pit 4	Stockland Viscount PoolingSW4	2025-06-19	11:13:00 AM	0	0	20.9	0	0		
SW5	Stormwater Pit 5	Stockland Viscount PoolingSW5	2025-06-19	11:13:19 AM	0	0	20.9	0	0		
SW6	Stormwater Pit 6	Stockland Viscount PoolingSW6	2025-06-19	11:13:33 AM	0	0	20.9	0	0		
SW7	Stormwater Pit 7	Stockland Viscount PoolingSW7	2025-06-19	11:14:04 AM	0	0	20.9	0	0		
SW8	Stormwater Pit 8	Stockland Viscount PoolingSW8	2025-06-19	11:14:25 AM	5	0	20.9	0	0		
SW9	Stormwater Pit 9	Stockland Viscount PoolingSW9	2025-06-19	11:15:05 AM	0	0.02	20.9	0	0		
SW10	Stormwater Pit 10	Stockland Viscount PoolingSW10	2025-06-19	11:19:20 AM	0	0	20.9	0	0		
GR01	Change Room	Stockland Viscount PoolingChange Room	-	-	-	-	-	-	-	No Access	
GR02	Lunchroom	Stockland Viscount PoolingLunchroom	2025-06-19	11:22:20 AM	0	0	20.9	0	0		

MT01	Male Toilet	Stockland Viscount PoolingMale Toilet	2025-06-19	11:22:31 AM	0	0.02	20.9	0	0	No Access
GR03	Warehouse	Stockland Viscount PoolingWarehouse	2025-06-19	11:14:00 AM	0	0	20.9	0	0	-
Dinzel										
SW1	SW1	DinzelSW1	2025-06-19	11:47:23 AM	0	0	20.9	0	0	-
SW2	SW2	DinzelSW2	2025-06-19	11:47:13 AM	0	0	20.9	0	0	-
SW3	SW3	DinzelSW3	2025-06-19	11:47:03 AM	0	0	20.9	0	0	-
SW4	SW4	DinzelSW4	2025-06-19	11:46:14 AM	0	0	20.9	0	0	-
SW5	SW5	DinzelSW5	2025-06-19	11:43:42 AM	0	0	20.9	0	0	-
SW6	SW6	DinzelSW6	2025-06-19	11:43:28 AM	0	0	20.9	0	0	-
SW7	SW7	DinzelSW7	2025-06-19	11:42:48 AM	0	0	20.9	0	0	-
SW8	SW8	DinzelSW8	2025-06-19	11:45:17 AM	0	0	20.9	0	0	-
GR01	Dispatch	DinzelDispatch	2025-06-19	11:46:49 AM	0	0	20.9	0	0	-
T01	Toilet 1	DinzelToilet 1	-	-	-	-	-	-	-	-
GR02	Elec Room	DinzelElec Room	2025-06-19	11:42:36 AM	0	0	20.9	0	0	-
T02	Toilet 2	DinzelToilet 2	-	-	-	-	-	-	-	-
Saputo										
SW1	Stormwater Pit 1	SaputoSW1	2025-06-20	9:20:17 AM	0	0	20.9	0	0	-
SW2	Stormwater Pit 2	SaputoSW2	2025-06-20	9:20:47 AM	0	0	20.9	0	0	-
SW3	Stormwater Pit 3	SaputoSW3	2025-06-20	9:22:21 AM	0	0	20.9	0	0	-
SW4	Stormwater Pit 4	SaputoSW4	2025-06-20	9:22:51 AM	10	0	20.9	0	0	-
SW5	Stormwater Pit 5	SaputoSW5	2025-06-20	9:23:40 AM	0	0	20.9	0	0	-
SW6	Stormwater Pit 6	SaputoSW6	2025-06-20	9:24:05 AM	0	0	20.9	0	0	-
E1	Electrical Pit 1	SaputoE1	2025-06-20	9:21:06 AM	0	0	20.9	0	0	-
E2	Electrical Pit 2	SaputoE2	2025-06-20	9:21:24 AM	0	0	20.9	0	0	-
E3	Electrical Pit 3	SaputoE3	2025-06-20	9:21:42 AM	0	0	20.9	0	0	-
E4	Electrical Pit 4	SaputoE4	2025-06-20	9:21:55 AM	0	0	20.9	0	0	-
E5	Electrical Pit 5	SaputoE5	2025-06-20	9:23:27 AM	5	0	20.9	0	0	-
E6	Electrical Pit 6	SaputoE6	2025-06-20	9:23:53 AM	0	0	20.9	0	0	-
LOSCAM										
SW1	Stormwater Pit 1	LOSCAMSW1	2025-06-19	10:16:49 AM	0	0	20.9	0	0	-
SW2	Stormwater Pit 2	LOSCAMSW2	2025-06-19	10:16:35 AM	0	0	20.9	0	0	-
SW3	Stormwater Pit 3	LOSCAMSW3	-	-	-	-	-	-	-	No Access
SW4	Stormwater Pit 4	LOSCAMSW4	2025-06-19	10:14:32 AM	0	0	20.9	0	0	-
SW5	Stormwater Pit 5	LOSCAMSW5	2025-06-19	10:13:54 AM	0	0	20.9	0	0	-
SW6	Stormwater Pit 6	LOSCAMSW6	2025-06-19	10:13:10 AM	0	0	20.9	0	0	-
SW7	Stormwater Pit 7	LOSCAMSW7	2025-06-19	10:12:42 AM	0	0	20.9	0	0	-
SW8	Stormwater Pit 8	LOSCAMSW8	-	-	-	-	-	-	-	-
WB01	Wash Bay	LOSCAMWash Bay	2025-06-19	10:15:41 AM	0	0	20.9	0	0	-
MT01	Male Toilet	LOSCAMMale Toilet	2025-06-19	10:17:04 AM	0	0	20.9	0	0	-
GR01	Warehouse Ambient	LOSCAMWarehouse Ambient	2025-06-19	10:15:00 AM	0	0	20.9	0	0	-
Mainfreight										
SW1	Stormwater Pit 1	MainfreightSW1	-	-	-	-	-	-	-	No Access
SW2	Stormwater Pit 2	MainfreightSW2	-	-	-	-	-	-	-	No Access
SW3	Stormwater Pit 3	MainfreightSW3	-	-	-	-	-	-	-	No Access
SW4	Stormwater Pit 4	MainfreightSW4	-	-	-	-	-	-	-	No Access
SW5	Stormwater Pit 5	MainfreightSW5	-	-	-	-	-	-	-	No Access
SW6	Stormwater Pit 6	MainfreightSW6	-	-	-	-	-	-	-	No Access
SW7	Stormwater Pit 7	MainfreightSW7	-	-	-	-	-	-	-	No Access
GR01	Dispatch office	MainfreightDispatch office	-	-	-	-	-	-	-	No Access
GR02	Lunchroom	MainfreightLunchroom	-	-	-	-	-	-	-	No Access
T01	Toilet	MainfreightToilet	-	-	-	-	-	-	-	No Access
Mulgoa Quarries										
SW1	Stormwater Pit 1	Mulgoa QuarriesSW1	2025-06-19	10:22:37 AM	0	0	20.9	0	0	-
SW2	Stormwater Pit 2	Mulgoa QuarriesSW2	2025-06-19	10:22:54 AM	0	0	20.9	0	0	-
SW3	Stormwater Pit 3	Mulgoa QuarriesSW3	2025-06-19	10:23:22 AM	0	0	20.9	0	0	-
SW4	Stormwater Pit 4	Mulgoa QuarriesSW4	2025-06-19	10:24:01 AM	0	0	20.9	0	0	-
SW5	Stormwater Pit 5	Mulgoa QuarriesSW5	2025-06-19	10:24:31 AM	0	0	20.9	0	0	-
SW6	Stormwater Pit 6	Mulgoa QuarriesSW6	2025-06-19	10:24:46 AM	0	0	20.9	0	0	-
SW7	Stormwater Pit 7	Mulgoa QuarriesSW7	2025-06-19	10:24:59 AM	0	0	20.9	0	0	-
SW8	Stormwater Pit 8	Mulgoa QuarriesSW8	2025-06-19	10:25:18 AM	0	0	20.9	0	0	-
SW9	Stormwater Pit 9	Mulgoa QuarriesSW9	2025-06-19	10:26:23 AM	0	0	20.9	0	0	-
SW10	Stormwater Pit 10	Mulgoa QuarriesSW10	2025-06-19	10:26:04 AM	0	0	20.9	0	0	-
SW11	Stormwater Pit 11	Mulgoa QuarriesSW11	2025-06-19	10:25:49 AM	0	0	20.9	0	0	-
SW12	Stormwater Pit 12	Mulgoa QuarriesSW12	-	-	-	-	-	-	-	-
SW13	Stormwater Pit 13	Mulgoa QuarriesSW13	-	-	-	-	-	-	-	-
SW14	Stormwater Pit 14	Mulgoa QuarriesSW14	2025-06-19	10:27:18 AM	0	0	20.9	0	0	-
SW15	Stormwater Pit 15	Mulgoa QuarriesSW15	2025-06-19	10:27:42 AM	0	0	20.9	0	0	-
WB01	Wash Bay	Mulgoa QuarriesWash Bay	2025-06-19	10:28:04 AM	0	0	20.9	0	0	-
MT01	Male Toilet	Mulgoa QuarriesMale Toilet	2025-06-19	10:30:43 AM	5	0.02	20.9	0	0	-
GR01	Lunch Room	Mulgoa QuarriesLunch Room	2025-06-19	10:30:30 AM	0	0	20.9	0	0	-
Darley Aluminium										
SW1	Stormwater Pit 1	Darley AluminiumSW1	2025-06-19	10:41:09 AM	0	0	20.9	0	0	-
SW2	Stormwater Pit 2	Darley AluminiumSW2	2025-06-19	10:48:42 AM	0	0	20.9	0	0	-
SW3	Stormwater Pit 3	Darley AluminiumSW3	2025-06-19	10:42:18 AM	0	0	20.9	0	0	-
SW4	Stormwater Pit 4	Darley AluminiumSW4	2025-06-19	10:43:47 AM	0	0	20.9	0	0	-
SW5	Stormwater Pit 5	Darley AluminiumSW5	2025-06-19	10:45:16 AM	0	0	20.9	0	0	-
SW6	Stormwater Pit 6	Darley AluminiumSW6	2025-06-19	10:46:56 AM	0	0	20.9	0	0	-
SW7	Stormwater Pit 7	Darley AluminiumSW7	2025-06-19	10:48:11 AM	0	0	20.9	0	0	-
SW8	Stormwater Pit 8	Darley AluminiumSW8	2025-06-19	10:45:00 AM	0	0	20.9	0	0	-
GR01	Lunch Room	Darley AluminiumLunch Room	2025-06-19	10:49:36 AM	0	0	20.9	0	0	-

MT01	Male Toilet	Darley AluminiumMale Toilet	2025-06-19	10:49:56 AM	0	0.02	20.9	0	0	-
ORAFOL/EHI										-
SW1	Stormwater Pit 1	ORAFOL/EHISW1	2025-06-20	10:29:19 AM	0	0	20.9	0	0	-
SW2	Stormwater Pit 2	ORAFOL/EHISW2	2025-06-20	10:29:30 AM	0	0	20.9	0	0	-
SW3	Stormwater Pit 3	ORAFOL/EHISW3	2025-06-20	10:29:49 AM	0	0	20.9	0	0	-
SW4	Stormwater Pit 4	ORAFOL/EHISW4	2025-06-20	10:30:16 AM	0	0	20.9	0	0	-
SW5	Stormwater Pit 5	ORAFOL/EHISW5	2025-06-20	10:30:48 AM	0	0	20.9	0	0	-
SW6	Stormwater Pit 6	ORAFOL/EHISW6	2025-06-20	10:32:01 AM	0	0	20.9	0	0	-
SW7	Stormwater Pit 7	ORAFOL/EHISW7	-	-	-	-	-	-	-	-
SW8	Stormwater Pit 8	ORAFOL/EHISW8	2025-06-20	10:32:40 AM	0	0	20.9	0	0	-
SW9	Stormwater Pit 9	ORAFOL/EHISW9	2025-06-20	10:33:30 AM	0	0	20.9	0	0	-
SW10	Stormwater Pit 10	ORAFOL/EHISW10	2025-06-20	10:33:47 AM	0	0	20.9	0	0	-
SW11	Stormwater Pit 11	ORAFOL/EHISW11	2025-06-20	10:34:04 AM	0	0	20.9	0	0	-
SW12	Stormwater Pit 12	ORAFOL/EHISW12	2025-06-20	10:34:20 AM	0	0	20.9	0	0	-
SW13	Stormwater Pit 13	ORAFOL/EHISW13	2025-06-20	10:34:58 AM	0	0	20.9	0	0	-
SW14	Stormwater Pit 14	ORAFOL/EHISW14	2025-06-20	10:35:40 AM	0	0	20.9	0	0	-
SW15	Stormwater Pit 15	ORAFOL/EHISW15	2025-06-20	10:36:02 AM	0	0	20.9	0	0	-
SW16	Stormwater Pit 16	ORAFOL/EHISW16	2025-06-20	10:34:36 AM	0	0	20.9	0	0	-
SW17	Stormwater Pit 17	ORAFOL/EHISW17	2025-06-20	10:32:54 AM	0	0	20.9	0	0	-
Bluescope Steel										-
SP1	Service Pit 1	Bluescope SteelService Pit 1	2025-06-20	2:29:50 PM	0	0	20.9	0	0	-
E01	Electrical Pit 1	Bluescope SteelElectrical Pit 1	2025-06-20	2:29:13 PM	0	0	20.9	0	0	-
GR01	Indoor cart celler	Bluescope SteelIndoor cart celler	-	-	-	-	-	-	-	-
O01	Office	Bluescope SteelOffice	2025-06-20	2:29:34 PM	0	0	20.9	0	0	-
S01	Shower	Bluescope SteelShower	2025-06-20	2:28:38 PM	5	0.02	20.9	0	0	-
T01	Toilet	Bluescope SteelToilet	2025-06-20	2:28:58 PM	0	0	20.9	0	0	-
SW11	SW Pit	Bluescope SteelSW11	2025-06-20	2:25:37 PM	0	0	20.9	0	0	-
SW1	SW pit adjacent service road 1	Bluescope SteelSW1	2025-06-20	2:39:00 PM	0	0	20.9	0	0	-
SW2	SW pit adjacent service road 2	Bluescope SteelSW2	-	-	-	-	-	-	-	-
SW3	SW pit adjacent service road 3	Bluescope SteelSW3	2025-06-20	2:39:10 PM	0	0	20.9	0	0	-
SW4	SW pit adjacent service road 4	Bluescope SteelSW4	2025-06-20	2:31:55 PM	0	0	20.9	0	0	-
SW5	SW Pit 5	Bluescope SteelSW5	2025-06-20	2:31:23 PM	0	0	20.9	0	0	-
SW6	SW Pit 6	Bluescope SteelSW6	2025-06-20	2:30:01 PM	5	0	20.9	0	0	-
SW7	SW Pit 7	Bluescope SteelSW7	2025-06-20	2:27:51 PM	0	0	20.9	0	0	-
SW8	SW Pit 8	Bluescope SteelSW8	2025-06-20	2:28:11 PM	0	0	20.9	0	0	-
SW9	SW Pit 9	Bluescope SteelSW9	2025-06-20	2:26:12 PM	0	0	20.9	0	0	-
SW12	SW Pit	Bluescope SteelSW12	2025-06-20	2:28:25 PM	0	0	20.9	0	0	-
GR02	Pump Room	Bluescope SteelGR02	-	-	-	-	-	-	-	-